

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 19 December, 2017 7:55 PM
To: janet.tan@eqinsurance.com.sg
Cc: Vic (LKKAuto); Asher Sng (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving GBF8336Z (OI : EQI - TBA) AND SHC6670R (TP : LKK REF - CC3/EQI17024031/K1ha3) on 16/12/2017
Attachments: TP GIA REPORT.pdf; TP ESTIMATE- MARKED.pdf; Preliminary Advice.pdf; LKK SURVEYOR PHOTO.pdf

WITHOUT PREJUDICE

Dear Lynn,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 6670R at M/s Premier Automotive Services Pte Ltd (Changi South).

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)