

Ty

**MAKE :
MODEL : HYUNDAI SONATA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Wheel Hub Cap, LH <i>Rear Fender (LH) x repair</i>			\$ 150.70
	SUB TOTAL			\$ 150.70
	LESS 20%			\$ 30.14
	DISCOUNTED TOTAL			\$ 120.56
	 Rear Door Tel No. Sticker (LH) +			\$ 10.00
	Rear Door Advertisement Logo (LH) ✓ <i>Fender</i>			\$ 100.00
	<i>Rear Door Advertisement Log. (LH)</i> —			\$ 110.00
	 Labour Charge			200
	Panel Beating- Repair Rear Fender			\$ 400.00
	Spray Painting Charge			\$ 400.00
				180
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 1,030.56
	 <i>Kalin LKKK</i> <i>M 18/12/12 1445hr</i> <i>2 Days</i> <i>L/S</i> <i>After Repair phb</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.