

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : CRUZ ROEL OLERO
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Not Approved

LKR

19/12/17

2/s = 3300/2

4 day.

To inspect After repair

Quotation No : QO17/11-1075	Quotation Date : 13/11/2017	Terms : 30 DAYS
Vehicle No : SLM9739H	Chassis No : MHFB29F3402009110	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: AIG, INSURED VEHICLE NO: SLG9510G, DATE OF ACCIDENT: 11.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	1 <i>20/Dec</i>	1,662.4000	1,662.40
2	BOOTLID LOCK TOP	1 <i>20/Dec</i>	90.4000	90.40
3	BOOTLID LOCK STRIKER BOTTOM	1 <i>11</i>	18.5000	18.50
4	BOOTLID WEATHERSTRIP	1 <i>20/Dec</i>	188.0000	188.00
5	BOOTLID INNER TRIM	1 <i>11</i>	398.7000	398.70
6	BOOTLID INNER TRIM CLIPS	6 <i>11</i>	4.3000	25.80
7	BOOTLID LOCK CABLE CLIPS	3 <i>11</i>	4.3000	12.90
8	BOOTLID VIOS BADGE	1 <i>20/Dec</i>	44.1000	44.10
9	BOOTLID E BADGE	1 <i>20/Dec</i>	34.4000	34.40
10	BOOTLID CENTRE EMBLEM BADGE	1 <i>20/Dec</i>	59.8000	59.80
11	BOOTLID OUTER GARNISH	1 <i>11</i>	105.0000	105.00
12	REAR LICENSE LAMP	2 <i>11</i>	48.5000	97.00
13	REAR END PANEL	1 <i>20/Dec</i>	694.7000	694.70
14	REAR END PANEL INNER TRIM	1 <i>20/Dec</i>	234.3000	234.30
15	REAR END PANEL INNER TRIM CLIPS	6 <i>11</i>	5.0000	30.00
16	REAR BUMPER	1 <i>20/Dec</i>	504.9000	504.90
17	REAR BUMPER REINFORCEMENT	1 <i>20/Dec</i>	323.3000	323.30
18	REAR BUMPER REFLECTOR	2 <i>11</i>	130.5000	261.00
19	REAR BUMPER CLIPS	10 <i>20/Dec</i>	4.3000	43.00
20	REAR BUMPER SIDE RETAINER	2 <i>20/Dec</i>	116.2000	232.40
21	REAR BUMPER SIDE HOLDER	2 <i>20/Dec</i>	22.3000	44.60
22	REAR LUGGAGE FLOOR - COMPARTMENT TOOL FOAM	1 <i>11</i>	109.6000	109.60
23	LESS 25%	1	-1,473.7000	-1,473.70

C/F 0.00

Page 1 of 2

3256.37

2442.27

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : CRUZ ROEL OLERO Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/11-1075	Quotation Date : 13/11/2017	Terms : 30 DAYS
Vehicle No : SLM9739H	Chassis No : MHFB29F3402009110	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED VEHICLE NO: SLG9510G, DATE OF ACCIDENT: 11.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LUGGAGE FLOOR PANEL INNOVATION	1 11	200.0000	X 200.00
25	REAR LICENSE PLATE	1 11	80.0000	X 80.00
26	REAR BUMPER PARKING SENSOR	(ref) 1 slud	400.0000	2005.00 400.00
27	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	900.0000	600 900.00
28	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	880.0000	700 880.00
29	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	150.0000	60 150.00
30	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	150.0000	50 150.00
31	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	20 60.00
32	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER. TO ENABLE REPAIR.	1	120.0000	60 120.00
33	TO REPAIR, REALIGN REAR EXHAUST BOX	1 11	150.0000	X 150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4152.27

Sub Total	6,831.10
GST(7.00%)	478.18
Total (SGD)	7,309.28

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216