

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 17/12/2017

TP Veh Reg No: SKM6006X

Estimate No: ES1791409/AMK

Date: 19 Dec 2017

Policy No: 5087429208

Veh Reg No: SLK2636C

Make/Model: HONDA VEZEL 1.5
HYBRID X A

Chassis No: RU31208103

Engine No: LEB5908113

Reg. Date: 11/01/2017

Estimate Repair Cost to Vehicle No :SLK2636C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	801.70	1 PC	801.70	✓
2 FRONT BUMPER REINFORCEMENT	321.00	1 PC	321.00	✓
3 FRONT BUMPER RH FOG LAMP COVER	30.90	1 PC	30.90	✓
4 FRONT BUMPER RH SIDE RETAINER	23.00	1 PC	23.00	✓
5 FRONT BUMPER LOWER SPOILER	381.00	1 PC	381.00	✓
6 FRONT BUMPER CLIP	3.90	5 PC	19.50	✓
7 FRONT RH FENDER WHEEL ARC GARNISH	195.00	1 PC	195.00	✓
8 FRONT RH FENDER EMBLEM	58.70	1 PC	58.70	✓
9 HEADLAMP RH	1,784.50	1 PC	1,784.50	✓
10 RADIATOR RH SIDE GARNISH	32.10	1 PC	32.10	✓
			3,647.40	
		Less 20%	729.48	2,917.92
Special Net				
11 FRONT BUMPER CHROME MOULDING	300.00	1 SET	300.00	✓
12 FRONT PARKING SENSOR	200.00	1 SET	200.00	✓
13 BODY COATING	350.00	1 UNIT	350.00	✓
			850.00	850.00
Labour				
14 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP;KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	400
15 PUTTY & RESPRAY FRT BUMPER,LOWER SPOILER,FRT RH FENDER & WHEEL ARCH GARNISH & ALL AFFECTED AREAS	600.00	1 LA	600.00	520
			1,100.00	1,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY

#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 17/12/2017

TP Veh Reg No: SKM6006X

Estimate No: ES1791409/AMK

Date: 19 Dec 2017

Policy No: 5087429208

Veh Reg No: SLK2636C

Make/Model: HONDA VEZEL 1.5
HYBRID X A

Chassis No: RU31208103

Engine No: LEB5908113

Reg. Date: 11/01/2017

Estimate Repair Cost to Vehicle No :SLK2636C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 4,867.92
			Add GST @ 7%	340.75
			Total Amount Payable	<u>S\$ 5,208.67</u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE