

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vale Oh

Date: 26 Jan 2018

## **Preliminary Advice**

Insured Vehicle No	: SHC5468R		
TP Vehicle No	: SFK2200Y	Accident Date	: 29/11/2017
Make	: LEXUS LX570	Assignment Date	: 18/12/2017
Date of Inspection	: 23/11/2017	Est. Duration of Repair	: 3 days
Inspection At	: Motorway Car Care Centre Pte Ltd - Lower Delta (HQ) 1094 LOWER DELTA ROAD Singapore 169205		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....N/S front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,123.20
Revised Amount	:S\$	5,518.20
Check Items (Estimated)	:S\$	1,530.00
Total	:S\$	7,048.20

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.