



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Suryana Binte Ali
Apt Blk 484A
Choa Chu Kang Avenue 5
Singapore 681484

*Not with car
11 hrs @ 900/-
Money After Repair
2 days*

Dear sir

Estimate cost of repair to vehicle no. SGC 7210R

TO SUPPLY

- | | | | |
|----------------------------|-------------|--------|-----------|
| 1. Rear bumper | <i>mgm</i> | 865.50 | <i>2</i> |
| 2. Rear bumper retainer x2 | <i>also</i> | 84.00 | <i>LT</i> |
| 3. Rear tail lamp | <i>in</i> | 460.00 | <i>X</i> |
| 4. Rear wheel rim | <i>in</i> | 550.00 | <i>X</i> |
| 5. Tyres | <i>in</i> | 350.00 | <i>X</i> |

208

Labour charges

Rust proofing

Panel beating

Spray painting

<i>nn</i>	80.00	<i>X</i>
	650.00	<i>2001</i>
	680.00	<i>2201</i>
	3719.50	

Total

Your faithfully

[Signature]
ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: