



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Eng Kwee Chew  
166 Cactus Road  
Singapore 809661

Dear sir  
Estimate cost of repair to vehicle no. SKMM 5210D  
To supply

1. Rear bumper
2. Rear bumper retainer x2
3. Rear wheel rim
4. Rear tyres
5. Rear door sticker
6. Rear fender sticker

879.80 debor  
 192.40  
 x550.00 R. 150 S/W  
 240.00  
 120.00  
 110.00

Labour charges  
Rust proofing  
Panel beating  
Spray painting

60.00  
 650.00  
 680.00

Total

Your faithfully

ALBERT POON

Not Author  
 We Repair  
 after painting parts  
 LKK Auto (circled)  
 21/12/2017  
 3w/1day

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

1750/2  
 3w days  
 (circled)