

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1075 L

1 pc	Bootlid emblem <i>X</i> ✓	\$	27.00
1 pc	Bootlid CRDi <i>X</i> ✓	\$	29.00
1 pc	Boot lid lower garnish <i>X</i>	\$	290.00
1 pc	n/s taillamp panel <i>X repair</i>	\$	218.00
1 pc	n/s floor side panel <i>X repair</i>	\$	65.00
1 pc	Rear n/s air vent <i>?</i>	\$	30.00
1 pc	Rear n/s tail lamp <i>?</i>	\$	421.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>n/s ✓ o/s X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>?</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>?</i>	\$	607.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>?</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>?</i>	\$	36.00
1 pc	Rear bumper reflector n/s ✓	\$	46.00
		\$	2,879.00
Less 10%		\$	287.90
		\$	2,591.10

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 pc	Rear n/s fender sticker ✓	\$	60.00
1 set	Bootlid stickers <i>X</i> ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1075 L

Sundry	\$ 50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, end panel etc	\$ 850.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear n/s fender, rear bumper, end panel	\$ 900.00 720
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 X
	<u>\$ 5,379.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LK

20/12/17 0920h

3 Pys

PIP

Before Part pLh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: