

SERVICE ESTIMATE

72325 - C00001
 Mr Chin Chin Kheng Yu
 Blk 124A Bukit Merah View
 #13-412

SL: SERVICE SALES - PC

Singapore 151124

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Chin Kheng Yu

GST Reg.No: M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 30/11/2017
 WIP No. . : 32011
 Veh.In/Out: 29/11/2017
 *Tel.No. . : Mobile: 97366616
 Reg.No. . : SKH5906G
 Reg.date . : 26/12/2012
 Mileage .. : 0
 Chassis No: YV1AS48HBD1167629

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER BUMPER & ETC.		0	1200.00	0	600	1,200.00	S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER BUMPER & ETC.		0	1650.00	0	1100	1,650.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	450.00	0	450	450.00	S
	BUMPER COVER REAR S8	1.0	EA	1454.80		de✓	1,454.80	S
	TOW COVER REAR S80 -	1.0	EA	73.90		X	73.90	S
	BUMPER SPOILER REAR	1.0	EA	434.30		de✓	434.30	S
	BUMPER BRACKET LHR S	1.0	EA	71.70		new✓	71.70	S
	BUMPER BRACKET RHR S	1.0	EA	73.90		new✓	73.90	S
	BUMPER BRACKET REAR	1.0	EA	104.30		new✓	104.30	S
	BLIND RIVET 4.0*21MM	10.0	EA	3.00		new✓	30.00	S
	BUMPER CLIP	10.0	EA	4.80		new✓	48.00	S
	PLASTIC RIVET P/W RA	10.0	EA	6.90		new✓	69.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
 WP
 22/12/17 @ 5pm
 3 days
 Resurvey before paint
 sur@lkkauto.com

SERVICE ESTIMATE

72325 - C00001 SL: SERVICE SALES - PC
Mr Chin Chin Kheng Yu
Blk 124A Bukit Merah View
#13-412

Singapore 151124

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 30/11/2017
WIP No. . : 32011
Veh.In/Out: 29/11/2017
*Tel.No. . : Mobile: 97366616
Reg.No. . : SKH5906G
Reg.date. : 26/12/2012
Mileage . : 0
Chassis No: YV1AS48HBD1167629

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Chin Kheng Yu

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S
	EXTERIOR ADHESIVE GL	1.0 EA	142.20			142.20	S

Labour Total 3,000.00
Parts Total 2,585.50
Package Total 0.00

Gross Total. 5,585.50
Net..... 5,585.50
GST @ 7.0% 390.99
Total..... 5,976.50
Paid..... 0.00
Please Pay.. 5,976.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated