

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3591R

DATE 19/12/2017 10:27

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (LH) ✓			\$ 619.00	
	Front Fender Shield (LH) ✕			\$ 169.80	
	Front Door Mirror (LH) ✕			\$ 980.50	
	Front Wheel Hub Cap (LH) ✓			\$ 150.70	
	Front Door (LH) ✕ repair				
	Rear Door (LH) ✕ repair				
	Front Bumper ✕ repair				
	SUB TOTAL			\$ 1,920.00	
	LESS 20%			\$ 384.00	
	DISCOUNTED TOTAL			\$ 1,536.00	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Front Door Comfort Logo (LH) ✓			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) ✓			\$ 80.00	Nett
				\$ 455.00	
	Labour Charge				
	Panel Beating			\$ 400	
	Spray Painting Charge			\$ 560.00	
	Wiring Charge			\$ 1,100.00	720
	Tuff Kote			\$ 50.00	✕
	FRT Wheel Alignment			\$ 50.00	20
				\$ 120.00	✕
	TOTAL LABOUR			\$ 1,880.00	
	ESTIMATE TOTAL			\$ 3,871.00	
	Kalam LKK/4 26/12/17 1035hr 2 Pys. P/P Before Part photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					