LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Vale Oh Date: 21 Dec 2017

Preliminary Advice

Insured Vehicle No : SKH5732R

TP Vehicle No : SHC8470M Accident Date : 18/12/2017

Make : HYUNDAI I40 Assignment Date : 20/12/2017

Date of Inspection : 20/12/2017 Est. Duration of Repair : 3/Days

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...O/S Body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,909.44
Revised Amount	:S\$	2,888.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,888.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :We have not authorized repairs.