

INS. CASE OWNER:

Wuifham

CC 6 / AIG170

24207, Uwa34

LKK:

IDAC:

Surveyor:

Marpus

DOI:

ASSIGNMENT

21/12/17

Date / Time:

21/12/17

Registered in Merimen:

21/12/17

Pre-assign / CCU / FTE

SLA 2203 X



Insured Vehicle No.:

Name of Insured:

Flann Simon OBNIS

Insured Tel No.:

HP:

90059409

Excess Sec II :SS

D.O.A.:

20/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

6125421639 SG

Policy No.:

200453839

Make / Model:

Citroen

Place of Accident:

Bukit Timah Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFB 7282A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chin Meng



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/12
11:40

SFB 7282A - X SLA 2203 X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

130208

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Date/ Time

26/12
11:40

26/12

DMP. Sent first letter to OI.

16/1/18

Called OI. Confirm accident details. Inform TP claim. Agree to settle and aware NCD will be affected. When find out.

RECEIVED 14 MAY 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:		Confirm by:
Repair Cost:	SS	(days)	Reduction:	%	Email	Call
FINAL SETTLEMENT		Date/Time:	Confirm with	Email	Call	
Final Liability:	%	100 (Agreed / Assessed)	BOLA S/N No.:	27	If NO or B 28, Ass. Lia:	
Repair Cost:	SS	4200.00				
Loss of Rental (LOR):	SS	(days)				
Loss of Use (LOU):	SS	500.00 (\$100 x 5 days)				
Loss of Income (LOI):	SS	(\$ x days)				
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU	<input type="checkbox"/>	LOR + LOI
GIA/LTA Search	SS	7.49	[Tick only one]			
Medical:	SS					1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/ Independent)	2) Report Format:			
Legal Cost	SS					3) Survey fee:
Total:	SS	4707.49	Global Sum SS:			
FINAL PAYMENT		Date/Time:	Confirm with:	Email	Call	
Payee 1:	SS	4707.49	Name 1:	Chin Meng Motors		
Payee 2: (Strike if N.A.)	SS		Name 2:			
Payee 3: (Strike if N.A.)	SS		Name 3:			

COPY SENT
14/1/18

Alb/




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17024207/Uwa3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-12-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 2203X	Veh. Inspected	SFB 7282A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/12/2017	Inspection Date	21/12/2017	
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/53 SINGAPORE 417883.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST513/17/TP

Your Ref: TP claim against SLA2203X

20-Dec-17

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Mercedes Benz E240 no: SFB7282A

Date of accident: 20-12-2017

Parts supply:

- 1 pc Boot
- 1 pc Boot emblem - E240
- 1 pc Boot emblem - C&C
- 1 pc Boot emblem - Logo
- 1 pc Boot inner lock
- 1 pc Boot weatehrstrip
- 2 pcs Taillamps @\$595.00
- 1 pc Rear bumper
- 1 pc Rear bumper reinforcement
- 10 pcs Rear bumper clips @\$5.00
- 1 pc Rear bumper protector - Centre
- 1 pc Rear bumper moulding (chrome - centre)
- 2 pcs Rear bumper side protector @\$133.00
- 2 pcs Rear bumper moulding (chrome - side) @\$112.00
- 1 pc Rear bumper foam
- 2 pcs Rear bumper brackets @\$55.00
- 2 pcs Rear bumper retainers @\$48.00
- 1 pc Rear bumper centre retainer
- 1 pc Rear bumper tow cover
- 1 pc Rear end panel garnish

4448
4003.2

ESTIMATE

Not about
d/s 4200/2
4200
21/12/17
Ch photo Atherly

N SS	1,835.00	X
den	70.00	=
den	60.00	=
den	48.00	=
11	248.00	X
Totol/ twi	256.00	=
cu	1,190.00	2
10/cu	1,420.00	=
m	645.00	2
den	50.00	=
de	223.00	=
den	152.00	=
1	266.00	X
re	224.00	X
vf	328.00	X
cu	110.00	2
11	96.00	X
11	112.00	X
11	65.00	X
11	964.00	X
	8,362.00	

Less 10%: (836.20)

shld 250.00 2005.00

S/Nett Items

- 1 set Rear reverse sensor (S/Nett)

Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.
- To respray affected part.
- To remove and refit rear reverse sensor
- To apply underseal
- To check wirings.

500	600.00
600	800.00
50	60.00
11	50.00 X
22	30.00
SS	9,315.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- Full legal modification is allowed
- Supplemental cost(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

(Signature)

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM017/18/TP
Your Ref: TP claim against SLA2203X

19-Feb-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Accident Involving SFB7282A and SLA2203X on 20-12-2017 along Bukit Timah Road.

We refer to the above matter. The accident was caused solely by the negligence of your insured and as a result, our client had incurred the following cost and losses:-

Cost of Repair (Surveyed by your surveyor):	SS	4,200.00
Loss of use 05 days (4 days + 1 Sunday)@\$120.00 :		600.00
GIA search fee:		7.49
	SS	<u>4,807.49</u>

Enclosed are copies of following documents for your perusal:

- (X) Repair bill
- (X) Letter of authorisation
- (X) GIA report
- (X) Photocopy of driver's IC & DL
- (X) GIA search fee

振明摩托
CHIN MENG MOTORS





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG17024207/Uwa3

19 JANUARY 2018

FLANN SIMON DENIS
27 DAIRY FARM ROAD
#03-06
SINGAPORE 679048

Dear Sir/Madam,

ACCIDENT INVOLVING SLA 2203X AND SFB 7282A ON 20.12.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKINGI/We, WAPP MATTHEW, the owner of vehicle no. SFB 7282A

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Chin Meng Motors

Signed and Acknowledge by:

Wapp
Nric no. and signature of policyholder

Company Stamp

20/12/17
Date


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Yapp Matthew (the third party claimant) of 2 Jalan Merlimau #01-09 S308729 (address), owner of SFB7282A (vehicle no.) hereby authorize CHIN MENG MOTORS ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SFB7282A that was damaged pursuant to the accident which occurred on 20-12-2017 (date) along Bukit Timah Road (location) involving vehicle no/s SLA2203X ("the accident").



I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 21 (day) of 12 (month) 2017 (year)



Signed by "the third party claimant"
(with chop if applicable)

Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, CHIN MENG MOTORS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$ 4,200.00** (Repair Cost), **S\$ 500.00** (Loss of ~~rental~~/use), **S\$ 7.49** (Disbursement), for vehicle no. **SFB7282A** that was damaged pursuant to the accident which occurred on **20-12-2017** (date) along **Bukit Timah Road** (location) involving vehicle no/s **SLA2203X**. This is pursuant to the inspection conducted on **21/12/18** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Yapp Matthew** ("the third party claimant") of vehicle no. **SFB7282A** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SFB7282A** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of 5 (month) 2018 (year)

cks. 

Signed by appointed surveyor




Signed by "the workshop" (with chop)

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM017/18/TP
Your Ref: TP claim against SLA2203X

19-Feb-18

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Final cost of repair to Mercedes E240 no: SFB7282A

Date of accident: 20-12-2017

Total cost of repair and labour charge incurred for dismantling and replacement for parts of the above mentioned vehicle etc as recommended in nett as lump sum by surveyor.

Total lump sum: S\$ 4,200.00

Dollars: Four thousand and two hundred only.

CHIN MENG MOTORS


Sport Authority
 Authority
 ive
 5701
 ation No. : M4-0006529-2

Print Date/Time : 20 Dec 2017 / 15:20:52

Receipt Date/Time : 20 Dec 2017 / 15:20:52

Tax Invoice/Receipt

pt No. : ITNET-00000-171220-001492

ous Receipt No. :

N Item Description/
 Business Transaction Reference
 No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLA2203X

As at 20 Dec 2017/09:00:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLA2203X

Enquiry Fee

20171220151935411585

7.00 0.49 7.49

Sub-Total

7.00 0.49 7.49

Result of Insurance Enquiry - SJF8882T

As at 09 Dec 2017/23:30:00

Insurance Co: NTUC INCOME INS CO-OP LTD

2 Insurance Enquiry - SJF8882T

Enquiry Fee

20171220151935443748

7.00 0.49 7.49

Sub-Total

7.00 0.49 7.49

Total Before Rounding

14.00 0.98 14.98

Rounding Difference

0.03

Total Amount Payable

14.95

Paid By

xxxxxxxxxxxx0994

Credit Card:
Visa/MasterCard

14.95

Total

14.95

Cash Change

0.00

Tendered Amount

14.95

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017 Edit Reg		21 Dec 2017 00:00 Edit Adj Rpt	\$54,200.00 Edit Estimates	\$54,200.00 View Rpt		Pending for Survey Report Cancel Case






























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Flann Simon Denis , ID: S7069536G									
Main Claimant: YAPP MATTHEW , ID: S0514067F									
Vehicle Reg. No.: SFB7282A		Date of Loss: 20/12/2017 09:00 - :59 [171 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6125421639SG		Policy/Cover Note No.: 2100453839 (Comprehensive)							
Vehicle Reg. No. (Insured): SLA2203X		Policy No. (Claimant): GA057567/1							
		Excess:							
Repairer: Chin Meng Motors (HQ) 1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 4810									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/01/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (22/12/2017): No OI GIA Report AIG_SG (22/12/2017): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFB7282A (6125421639SG)
[SLA2203X]**

**TP
YAPP MATTHEW
Dec 20 2017 9:00AM
[Flann Simon Denis]
Chin Meng Motors**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>
Letters/Correspondences						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown				Edit
Assessment Reports						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print
1	09/01/18 10:02	Accident Statement <small>From: SC - Reg. No: SLA2203X; Claimant: FLANN SIMON DENIS</small>				Load HTM
Photos/Images						3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	21/12/17 16:04	Chassis Number				Load JPG <input checked="" type="checkbox"/>
2	21/12/17 16:04	Odometer Reading				Load JPG <input checked="" type="checkbox"/>
3	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
4	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
5	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
6	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
7	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
8	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
9	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
10	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
11	21/12/17 16:04	General View				Load JPG <input checked="" type="checkbox"/>
12	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
13	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
14	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
15	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
16	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
17	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
18	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
19	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
20	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
21	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
22	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
23	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
24	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
25	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
26	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
27	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
28	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
29	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
30	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
31	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
32	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
33	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
34	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
35	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>
36	21/12/17 16:05	General View				Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
37	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/12/17 16:05	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/12/17 15:40	TP ESTIMATE - MARKED	 Load PDF	
2	22/12/17 15:40	TP GIA REPORT	 Load PDF	
3	26/12/17 11:55	Non reporting letter	 Load PDF	
4	17/05/18 11:51	WORKSHOP INVOICE	 Load PDF	
5	17/05/18 11:51	AUTHORISATION TO ACT FORM	 Load PDF	
6	17/05/18 11:51	LETTER TO OI	 Load PDF	
7	17/05/18 11:51	LTA SEARCH	 Load PDF	
8	17/05/18 11:51	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA2203X (Insd veh)	Model:	MERCEDES-BENZ E240 2.6
	SFB7282A (TP veh)		(A)
Date of Accident:	20/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	9,315.80	
Final Repair Cost	:	\$	4,200.00	
Loss of Use	:	\$	500.00	5.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.49	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	4,707.49	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)
** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Chin Meng Motors	:	\$ 4,707.49
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 May
2018

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024207/UWA3Q2

Date: 17/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453839
Claimant
Vehicle No : SFB7282A **Insured Vehicle No :** SLA2203X
Date of Loss: 20/12/2017 **Nature of Claim:** TP **Claim No:** 6125421639SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFB7282A
Make & Model: MERCEDES-BENZ E240, 2.6 (A) **Engine No:** 11291331609036
Reg. Date: 10/09/2003 (Man. Year: 2003) **Chassis No:** WDB2110612A362055
Colour: Blue **Odometer:** 275821 km
Engine Capacity: 2597 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 **Rear Tyre Size:** 225/45 R17
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,775.80	4,203.20	3,572.60	45.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	1,170.00	370.00	24.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,315.80	5,373.20	3,942.60	42.32
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	9,315.80	4,200.00	5,115.80	54.92
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,707.49		

INSPECTION

Date of Assignment: 21/12/2017
Date Inspected: 21/12/2017 **Inspected At:** Chin Meng Motors (HQ)
 1 Kaki Bukit Ave 6 #01-40/63, Autobay
 @ Kaki Bukit
 Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Repair	1,835.00 FL	*- FL
2	1		*BOOT EMBLEM -E240	Necessary	70.00 FL	*70.00 FL
3	1		*BOOT EMBLEM -C&C	Necessary	60.00 FL	*60.00 FL
4	1		*BOOT EMBLEM -LOGO	Necessary	48.00 FL	*48.00 FL
5	1		*BOOT INNER LOCK	Not Necessary	248.00 FL	*- FL
6	1		*BOOT WEATHERSTRIP	Torn /Twisted	256.00 FL	*256.00 FL
7	2		*TAILLAMPS	Cracked	1,190.00 FL	*1,190.00 FL
8	1		*REAR BUMPER	Deformed/Cracked	1,420.00 FL	*1,420.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	645.00 FL	*645.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	1		*REAR BUMPER PROTOCTOR -CENTRE	Deformed	223.00 FL	*223.00 FL
12	1		*REAR BUMPER MOULDING (CHROME-CENTRE)	Necessary	152.00 FL	*152.00 FL
13	2		*REAR BUMPER SIDE PROTECTOR	Repair	266.00 FL	*- FL
14	2		*REAR BUMPER MOULDING (CHROME-SIDE)	Necessary	224.00 FL	*224.00 FL
15	1		*REAR BUMPER FOAM	Not fitted	328.00 FL	*- FL
16	2		*REAR BUMPER BRACKETS	Cracked	110.00 FL	*110.00 FL
17	2		*REAR BUMPER RETAINERS	Not Necessary	96.00 FL	*- FL
18	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	112.00 FL	*- FL
19	1		*REAR BUMPER TOW COVER	Not Necessary	65.00 FL	*- FL
20	1		*REAR END PANEL GARNISH	Not Necessary	964.00 FL	*- FL
21	1		*SET REAR REVERSESENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,612.00	4,648.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	836.20	444.80
Total Parts (\$\$)	7,775.80	4,203.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	600.00	500.00
2	TO SPRAY AFFECTED PART	New	800.00	600.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	60.00	50.00
4	TO APPLY UNDERSEAL	New	50.00	0.00
5	TO CHECK WIRING	New	30.00	20.00
Gross Labour Cost (\$\$)			1,540.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >