ASS REC BY REF	-s/ICS17024223/Gqd3 Special Intervention
(2.6)	ASSIGNMENT (Office)
From (Person) Janice Goh	ECICS Date/Time 4-18pm@ 20/12/19
Estimated Cost:	Bill to
OD TP/WS/TP RES / OD RES / EVA	
To Inspect Vehicle No:	SG 7 , 5833S Insured:
at Workshop m/s Success	United Tel 67461515
of 2 kaki Bkt Ave 2 # C	01-33 Autohub
Policy No:	*Claim No: MPC17 B000 32400
Sum Insured	Excess: \$ 750.00
Make of Veh: (Client's Record)	DOA 16/12/17
CA / RED / REP. / REV 24 HRS	
Date/Time 10-Soam 021/12/17 Per	on Contacted Sinna Vehicle (IX) OUT
Date/Time Action/Instruction (
SGT 5833S-cc4	ICSH024116/Keb3 D.O.A: 16/12/2017
20/17@ 2.34 revert to	Janace by email.
mill @ 240p Janice Go	in informed C/or by email.
	Sivina C/A to Ex. & 750. by our 1.
	d with sorins 4 63350, 7 days.
(Red & 326.50)	



5a.

A)THE MARKET VALUE IS S\$--

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS/ICS17024223/Gqd3 ECICS LTD Ref: 7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE Date: 21-12-2017 SINGAPORE 038987 Code: ICS 1. Policy Particulars :- OWN DAMAGE SGT 5833S Insured Veh. Veh. Inspected Policy No. Coverage (\$) 0.00 750.00 Claim No. MPC17B00032400 Excess (\$) 21/12/2017 JANICE GOH Assign From Assign Date 2. Vehicle Particulars & Condition Make & Model 0 C.C Engine No. HIDDEN Year of Reg. Chassis No. Colour Odometer Steering Brakes Modification General 3. **Conditions of Tyres** Size Make Balance R/H Front Tyre mm L/H Front Tyre mm R/H Rear Tyre mm L/H Rear Tyre mm 4. Description of Damages 5. General Information **Accident Date** 16/12/2017 21/12/2017 Inspection Date Survey held at SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921

Remarks

(EST. AVERAGE)

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: MPC17B00032400

Date: 22nd December 2017

Our Ref: CS/ICS17024223/Gqd3

The Motor Claims Department ECICS Limited

Attn: Janice

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SGT 5833S .


We thank you for the instruction on _20/12/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/12/2017 at the premises of M/s SUCCESS UNITED and have the following to report:-

Workshop Estimate Amount	: S\$	6,576.50	12
Revised Estimate Amount	: S\$	4,014.75	
"Check" Items Amount	: S\$	195.50	
Market Value	: S\$	66,000.00	
Salvage Value	: S\$	46,875.00	
Nett Value	: <u>S</u> \$	19,125.00	

Description of Damage:

The vehicle sustained damages at the n/s body. The undercarriage affected due to collision.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

We have not authorize repair.

Yours faithfully

GUO QIANG Automobile Assessor

Catherine Chong (LKK Auto)

From:

motorsurvey <motorsurvey@ecics.com.sg>

Sent:

Wednesday, 20 December, 2017 4:18 PM

To:

sirina@successunited.com.sg; 'assignments' motorsurvey; Phoebe Jay Xie (ECICS, Claims)

Subject:

RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Attachments:

Estimate.pdf; Owner, driver's DL, IC.PDF; Estimate.pdf

Dear Sirina

Thank you for your email.

We will assign LKK for OD survey.

Aside to LKK

Please arrange OD survey. Policy excess \$750.00

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: sirina@successunited.com.sg [mailto:sirinassk@gmail.com]

Sent: Wednesday, 20 December, 2017 3:19 PM

To: motorsurvey; Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims)

Subject: Fwd: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Hi

Driver's/Owner's NRIC & driving license attached.

Thank You.

Best Regards,

Sirina Soon

Senior Claims Executive Mobile: +65 9223 6288

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2 #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 Fax: 6748 5015

----- Forwarded message -----

From: sirina@successunited.com.sg <sirinassk@gmail.com>

Date: Wed, Dec 20, 2017 at 3:12 PM

Subject: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

To: motorsurvey < motorsurvey@ecics.com.sg >, "Phoebe Jay Xie (ECICS, Operations / Claims)"

<PhoebeJay Xie@ecics.com.sg>, "Janice Goh Siew Geok (ECICS, Operations / Claims)"

<Janice Goh@ecics.com.sg>

Hi

Attached herein our estimate for your action.

We are still waiting for the parts price from our supplier.

Meanwhile, would appreciate if you would your surveyor to assess the damaged.

Appreciate your prompt action.

Thank You.


Best Regards,

Sirina Soon

Senior Claims Executive Mobile: <u>+65 9223 6288</u>

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2 #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921 Tel: 6746 1515 Fax: 6748 5015



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 22 December, 2017 2:42 PM

To:

'sirina@successunited.com.sg'

Cc:

SUR

Subject:

VEHICLE SGT 5833S (DOA: 16/12/2017)

Dear Sirina,

As spoken with you.

Instructed by our client ECICS Insurance, please proceed to repair the insured vehicle SGT 5833S (Excess \$750).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From:

motorsurvey <motorsurvey@ecics.com.sg>

Sent:

Friday, 22 December, 2017 2:40 PM

To:

Shiau Chan (LKKAuto); motorsurvey; assignments

Cc:

Phoebe Jay Xie (ECICS, Claims); SUR

Subject:

RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Dear Shiau

Please proceed to repair if damage is consistent.

Thank you.

Regards, Janice Goh Claims Division

DID: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.

Thank you for your kind patience and understanding.**

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Friday, 22 December, 2017 2:34 PM

To: motorsurvey; assignments

Cc: Phoebe Jay Xie (ECICS, Claims); SUR

Subject: RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Dear Janice,

Enclosed herewith preliminary advice of SGT 5833S.

We have not authorise repair.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 21 December, 2017 10:32 AM

To: 'motorsurvey' < motorsurvey@ecics.com.sg>; assignments < assignments@lkkauto.com>

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 22 December, 2017 2:34 PM

To:

'motorsurvey'; assignments

Cc:

'Phoebe Jay Xie (ECICS, Claims)'; SUR

Subject:

RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Attachments:

CSICS17024223Gqd3.pdf

Dear Janice,

Enclosed herewith preliminary advice of SGT 5833S.

We have not authorise repair.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 21 December, 2017 10:32 AM

To: 'motorsurvey' <motorsurvey@ecics.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Dear Janice,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorsurvey [mailto:motorsurvey@ecics.com.sg]

Sent: Wednesday, 20 December, 2017 4:18 PM

To: sirina@successunited.com.sg; 'assignments' <assignments@lkkauto.com>

Cc: motorsurvey < motorsurvey@ecics.com.sg >; Phoebe Jay Xie (ECICS, Claims) < PhoebeJay Xie@ecics.com.sg >

Subject: RE: OD survey / SGT 5833S / MPC17B00032400 / DoA 16.12.17

Dear Sirina

Thank you for your email.

We will assign LKK for OD survey.



Mitsubishi Colt Used Vehicle List (4 vehicles)

Depreciation Car Model Price Reg Date **Eng Cap** Mileage Company Availability Mitsubishi Colt 1.5A (COE till \$26,500 \$6,720 /yr 11-Dec-2006 1,499 cc 134,000 km Available 11/2021)

Smooth Engine, No Accident Before, Still Can Drive For 4 Years One Month. Price Negotiable.

Office No. - -

Choo Boon Chong - 98493827

Mitsubishi Colt Plus 1.5A (COE \$22,800 \$6,490 /yr 27-Jun-2006 1,499 cc - Creative Auto Available till 06/2021)

No Major Repair Needed, Low Depreciation At Below \$8k, Trade In And Loan Available, Please Call To Make Appointment For Viewing,

Office No. - -

Andychew - 93392128 | Don Teo - 91076963 | Terence Leow - 90290899

Mitsubishi Colt Plus 1.5A (COE \$24,688 \$7,860 /yr 10-Feb-2006 1,468 cc 218,000 km ImbAuto Pte Ltd Available till 02/2021)

No Major Repair Needed, Low Depreciation At Below \$8k. Upgraded Brake Kits. Road Tax Till Feb 2018. Trade In And Loan Available. Consignment Unit. Please Call To Make Appointment For Viewing.

Office No. - -

Benjamin - 83237600

Mitsubishi Colt Mirage1.6M \$63,000 \$7,680 /yr 05-Mar-1996 1,597 cc 273,000 km Available GLXI (COE till 03/2026)

This Escaped The Gallows! Supposedly 1 And Only In Sg. Lovingly Taken Care Of For Last 9 Years. 2nd Owner. 3 Years Old Expensive Paint Job Inside Out. 2nd Coat! Always Shelter Parked. Straight Chassis...

Office No. - -

Wayn - 86886555

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, beauty and wellness, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2017 sgCarMart. All rights reserved.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type	Singapore NRIC	
Owner ID	5403A	
Vehicle Details		
Vehicle No.	SGT5833S	
Vehicle to be Exported	No	
Intended De-registration Date	18 Dec 2017	
Vehicle Make	MITSUBISHI	
Vehicle Model	COLT 1.5M MIVEC	
Primary Colour	Red	
Manufacturing Year	2006	
Engine No.	4A910033857	
Chassis No.	JMYXNZ23A6Z000121	
Maximum Power Output	77.0 kW (103 bhp)	
Open Market Value	\$12,217.00	
Original Registration Date	18 Apr 2007	
First Registration Date	18 Apr 2007	
Transfer Count	2	
Actual ARF Paid	\$13,439.00	
Intended PARF Rebate Details		
PARF Eligibility	Forfeited	
PARF Eligibility Expiry Date	*	
PARF Rebate Amount	\$0.00	
Intended COE Rebate Details		
COE Expiry Date	17 Apr 2027	
COE Category	E - Open Category	
COE Period(Years)	10	
PQP Paid	\$50,230.00	
COE Rebate Amount	\$46,875.00	
Total Rebate Amount	\$46,875.00	

The information contained herein is correct as at 16 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A /	2	ΩI	n	-	МΤ	SТ	ΛТ	Ξ	EΝ	т
A	э	ы	u	=	VII.	01	Α,	7		

Date Of Report

18/12/2017 14:24

Date Of Accident

16/12/2017 10:50

Exact Location Of Accident

SENGKANG RIVERDALE PLAZA CARPARK EXIT

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SGT5833S

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

TAY LING JUN, PATRINE

NRIC No

S7935403A

Email Address

PHILOJUNKIE@GMAIL.COM

Mobile Phone No

(LOCAL) +65-93637822

Alternative Phone No

OFFICE-93637822

Vehicle Particulars

Manufacturer

MITSUBISHI

Model

COLT-1.5 MIVEC (M)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

ECICS LIMITED

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

MPC17B00032400

Cover Note Number

Driver

Name of Driver

TAY LING JUN, PATRINE

NRIC No

S7935403A

Date Of Birth

26/11/1979 INDOOR

Occupation Date Of Driving Pass

08/12/2006

Driving Experience

11 YEARS AND 0 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-93637822

Fax Number

Contact Number

OFFICE-93637822

EMail Address

PHILOJUNKIE@GMAIL.COM

Address

BLK 637A PUNGGOL DRIVE #14-431

Postcode

821637

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

YES

Are accident photos available for attachment? Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLL9767G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

LIEW KIM CHOR

NRIC/Passport Number

S1747138D

Contact Number

84984889

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


- Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you heraby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Sw

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.: SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was exting much storey carporly of Provided Plate to	appear to stom.
wy view nor harded by a large delingy touch packer	
Saw there were no wars and made a right turn to	
knowled on my left lide of car by Vibide B	
No organis or both myself and no other party we I	ew ton the.

DECLARATION

If We declare the foregoing particulars are true in every respect.

Folicyfioliter i Signature Date & Time

Drivers figurature If griver is not the policynology. Date & Time

Reporting Central Fersionnel's Signature Name BRIGHT NAME



聯成汽車維修

SUCCESS UNITED PTE LITO

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015 www.successunited.com.sg Co. / GST Reg: 200402570G

Estimate : OD/17-123

M/s ECiCS Limited

7 Temasek Boulevard

#10-01 Suntec Tower One

Singapore 038987

Attn: Motor Claims

Tel: 63030167

Fax: 63389267

Email: motorsurvey@ecics.com.sg

Date: 20th Dec 2017

Vehicle No : SGT 5833S

Make/ Model: Mit Colt Chassis No: JMYXNZ23A6Z000121

Acc. Date: 16.12.17

Policy No: MPC17B00032400

Your Ref :

S/n.	Qty	Particulars	Un	it Price	1	Mount	
	100000	Materials .					
1	1	Frt Fender LH / but			\$	260.00	
2	1	Frt Fender Signal Lamp LH X / U9			\$	28.00	
3	1	Frt Fender Liner LH - R			\$	78.00	
4	8	Frt Fender Liner Clips - MC CNA	\$	1.50	\$	12.00	-
5	1	Frt Bumper Side Holder LH 3			\$	12.00	
6	1	Frt Fender Splash Guard LH / Sele			\$	55.00	-
7	1	Frt Fender Quarter Glass Moulding LH / / C			\$	170.00	
8	1	Side Rocker and LH X Melan			\$	240.00	
9	1	Center Door Pillar RH x expar			\$	240.00	
10	1	Frt Door LH / bue			\$	560.00	-
11	2	Frt Door Hinge LH, Top & Lower / 67	\$	45.00	\$	90.00	-
12	1	Frt Door Weatherstrip LH 2 / TV			\$	40.00	
13	1	Frt Door Channel Rubber LH X /			\$	60.00	
14	1	Frt Door Mechanism Lock LH X 75VC			\$	160.00	
15	1	Frt Door Regulator Gear LH & / BT			\$	90.00	
16	1	Rear Door LH / 6T			\$	560.00	_
17	1	Frt Shock Absorber LH X (Cur			S	235.00	
18	1	Frt Lower Arm LH X			\$	175.00	
19	1	Frt Wheel Bearing LH			\$	80.00	
20	1	Frt Wheel Hub LH X 5VC			\$	165.00	
		34 (FO) - 12 (T.			\$	3,310.00	
				Plus 15%	\$	496.50	_
					\$	3,806.50	
21	1	Frt Sport Rim LH / SCR		S/Nett	\$	300.00	80 Clocal
			F	Parts Total :	\$	4,106.50	pepar
		Labour					= '
1	To remove	rearrange electrical wirings, check lightings.			\$	40.00	30/
2		replace frt suspension undercarriage parts.			\$	250.00	
3		driving and reset wheel alignment.			S	80.00	
4		repair and replaced damaged bodyparts, realign					00
00000		where consistent to the accident.			\$	900.00	650
5		respray painting on LH frt fender, frt & rear doors,					35
		frt & rear bumpers.			\$	1,200.00	(000
		<u>\$6</u>	i.	abour Total :	S	2,470.00	

Total Parts & Labour : \$ 6,576.50



SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015 www.successunited.com.sg Co. / GST Reg: 200402570G

Success United Pte Ltd

No of Days

Re-Survey Before/Afte Paint Part By Part/Lump Sum

Surveyed By Gue Quary Contact No. 82880282

Date of Survey 21

Fax No. 62564315

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

Guo Qiang @ Ikkawto. com Excess \$750 Not Authorised.

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) iş allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SUCCESS UNITED PTE LTD2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921
Tel: 6746 1515 / 6747 1787 Fax: 6748 5015 www.successunited.com.sg Co. / GST Reg: 200402570G

Finalisation

M/s **ECICS Limited**

7 Temasek Boulevard

#10-01 Suntec Tower One

Singapore 038987

Attn: Motor Claims

Tel: 63030167

Fax: 63389267 Email: motorsurvey@ecics.com.sg

Date: 3rd January 2017

Vehicle No : SGT 5833S

Make/ Model: Mit Colt

Chassis No: JMYXNZ23A6Z000121

Acc. Date: 16.12.17

Policy No: MPC17B00032400

Your Ref:

S/n.	Qty Particulars		Un	it Price	Amount	
		Materials				
1	1	Frt Fender LH			\$	260.00
2	1	Frt Fender Signal Lamp LH			\$	28.00
3	1	Frt Fender Liner LH			\$	78.00
4	8	Frt Fender Liner Clips	\$	1.50	\$	12.00
5	1	Frt Bumper Side Holder LH			\$	12.00
6	1	Frt Fender Splash Guard LH				55.00
7	1	Frt Fender Quarter Glass Moulding LH			\$	170.00
8	1	Frt Door LH			s s s	560.00
9	2	Frt Door Hinge LH, Top & Lower	\$	45.00	\$	90.00
10	1	Frt Door Weatherstrip LH	2020		\$	40.00
11	1	Frt Door Regulator Gear LH			\$	90.00
12	1	Rear Door LH			\$	560.00
13	1	Frt Wheel Bearing LH				80.00
		Control of the Contro			\$ 5	2,035.00
				Plus 15%	\$	305.25
					\$	2,340.25
14	1	Frt Sport Rim LH (Repair)		S/Nett	\$	80.00
		3 3 32 3	F	Parts Total :	\$	2,420.25
		Labour				
1	To remove, r	earrange electrical wirings, check lightings.			\$	30.00
2	To remove, r	eplace frt suspension undercarriage parts.			\$	50.00
3	To road test	driving and reset wheel alignment.			\$	60.00
4	To remove,	repair and replaced damaged bodyparts, realign				
	bodyworks &	where consistent to the accident.			\$	650.00
5	To putty and	respray painting on LH frt fender, frt & rear doors	,			
		frt & rear bumpers.			\$	1,000.0
			L	abour Total:	\$	1,790.0
		То	tal Parts	& Labour :	\$	4,210.2
			1.118	MP SUM	\$	3,350.0



Success United Pte Ltd



聯 成 汽 車 維 修 **SUCCESS UNITED PTE LTD** 2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015 www.successunited.com.sg Co. / GST Reg: 200402570G

No of Days 7

Re-Survey /After Paint Lump Sum

Surveyed By Guo Qiang Contact No. 82880282

Date of Survey 21/12/2017 Fax No.

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Autom	obile
CICS LTD		Ref : CS/ICS1702422	23/Gqd3n2
TEMASEK BOULEVA 10-01 SUNTEC TOW! INGAPORE 038987	ARD ER ONE	Date: 10-05-2018 Code: ICS	
	Policy Parti	culars :- OWN DAMAGE	
Insured Veh.	The state of the s	Veh. Inspected	SGT 5833S
Policy No.	MPC17B00032400	Coverage (\$)	0.00
Claim No.		Excess (\$)	750.00
Assign From	JANICE GOH	Assign Date	20/12/2017
	Vehicle P	articulars & Condition	
Make & Model	MITSUBISHI COLT	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JMYXNZ23A6Z000121	Colour	RED
Odometer	139890	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
	Cor	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/50 R15	DUNLOP	6 mm
L/H Front Tyre	195/50 R15	DUNLOP	6 mm
R/H Rear Tyre	195/50 R15	DUNLOP	6 mm
L/H Rear Tyre	195/50 R15	DUNLOP	6 mm
		ription of Damages	
THE VEHICLE SU COLLISION.	STAINED DAMAGES AT THE	N/S BODY.THE UNDERCA	RRIAGE AFFECTED DUE TO
DAMAGES SEE D			
	AND REAL PROPERTY.	neral Information	21/12/2017
Accident Date	16/12/2017	Inspection Date	21/12/2017
Survey held at	SUCCESS UNITED PTE LT	П	
	2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOI SINGAPORE 417921	HUB	
5a.		Remarks	
A)THE MARKET V B)IN ACCORDAN	VALUE IS S\$66,000.00 (EST. CE TO YOUR INSTRUCTION	AVERAGE) IS, WE HAVE AUTHORISED	REPAIRS.
5b.	Estin	nate Days of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR:

7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 5833S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT FENDER LH (WCP)	BUCKLED	260.00	260.00
	[1] [1] [1] [2] [2] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	CRACKED	28.00	28.00
		DEFORMED	78.00	78.00
	[NECESSARY	12.00	12.00
		CRACKED	12.00	12.00
		SCRATCHED	55.00	55.00
	[전 THE TOTAL CONTROL OF THE TREE TOTAL CONTROL OF THE TREE THE TREE TOTAL CONTROL OF THE CONTRO	NECESSARY	170.00	170.00
		TO REPAIR SEE LABOUR	240.00	-
1	CENTER DOOR PILLAR RH (WCP)	TO REPAIR SEE LABOUR	240.00	-
1	FRT DOOR LH (WCP)	BUCKLED	560.00	560.00
	FRT DOOR HINGE LH. TOP & LOWER @\$45.00 (WCP)	BENT	90.00	90.00
	FRT DOOR WEATHERSTRIP LH (WCP)	TORN	40.00	40.00
1	FRT DOOR CHANNEL RUBBER LH (WCP)	SERVICEABLE	60.00	-
1	FRT DOOR MECHANISM LOCK LH (WCP)	SERVICEABLE	160.00	
1	FRT DOOR REGULATOR GEAR LH (WCP)	BENT	90.00	90.00
1	REAR DOOR LH (WCP)	BENT	560.00	560.00
1	FRT SHOCK ABSORBER LH (WCP)	SERVICEABLE	235.00	-
1	FRT LOWER ARM LH (WCP)	SERVICEABLE	175.00	-
1	FRT WHEEL BEARING LH (WCP)	NECESSARY	80.00	80.00
1	FRT WHEEL HUB LH (WCP)	SERVICEABLE	165.00	9
	COST PLUS 15%		496.50	305.25
	55057065 (0.25 0000000000000000000000000000000000		3,806.50	2,340.25
	SPECIAL NETT ITEMS			
*	FRT SPORT RIM LH (LOCAL REPAIR)(SN)	SCRATCHED	300.00	80.00
	100 mm		300.00	80.00
	LABOUR			20072
	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		40.00	
	TO REMOVE, REPLACE FRT SUSPENSION UNDERCARRIAGE PARTS.		250.00	5
	TO ROAD TEST DRIVING AND RESET WHEEL ALIGNMENT.		80.00	60.00

Report Ref No. CS/ICS17024223/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF SIDE ROCKER PANEL LH AND CENTER DOOR PILLAR RH.		900.00	650.00
	TO PUTTY AND RESPRAY PAINTING ON LH FRT FENDER, FRT & REAR DOORS, REAR FENDER, FRT & REAR BUMPERS.		1,200.00	1,000.00
			2,470.00	1,790.00
	GRAND TOTAL		6,576.50	4,210.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	3,350.00
LESS EXCESS	-750.00
NETT LIABILITY	2,600.00

Report Ref No. CS/ICS17024223/Gqd3n2

8

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.