

INS. CASE OWNER:

CC3 / EQ1170 24248, Gwa3 9

LKK:
IDAC:

ASSIGNMENT

Strategy:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: S\$ 1518.65

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ 180.00 (5 60 x 3 days)

Loss of Income (LOI): S\$ (5 x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 2.00

Medical:

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$ 1700.65

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 1700.65

Name 1:

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:

Cycle & Carriage - Fulco motor Dealer Pte Ltd.

RECEIVED 8 FEB 2018

COMPLAINT
1/2/18




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI17024248/wa3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 22-12-2017	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 5139E	Veh. Inspected	SLQ 5403G	
Policy No.	DMPPHQ17-001451	Coverage (\$)	0.00	
Claim No.	DM17HO02904	Excess (\$)	0.00	
Assign From		Assign Date	22/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/12/2017	Inspection Date		
Survey held at	CYCLE & CARRIAGE FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLQ5403G
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	KIA
Vehicle Model :	CERATO K3 1.6A
Chassis No. :	KNAFX411MH5697733
Propellant :	Petrol
Engine No. :	G4FGGH667939
Engine Capacity :	1591 cc
Maximum Power Output :	95.3 kW (127 bhp)
Maximum Laden Weight :	1740 kg
Unladen Weight :	1295 kg
Year Of Manufacture :	2016
Original Registration Date :	14 Jul 2017
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$42,801.00
COE Expiry Date :	13 Jul 2027
Road Tax Expiry Date :	13 Jan 2018
PARF Eligibility Expiry Date :	13 Jul 2027
Inspection Due Date :	13 Jul 2020



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr LIM TIEN THENG JEANNE Blk 413 Bedok North Ave 2 #10-156 Singapore 460413	Cust No/Name /Mr Lim Tien Theng Jeanne Reg No/Reg Date SLQ5403G*1F / 14/07/2017 Date In/Mileage 21/12/2017/ 0 Chassis No KNAFX411MH5697733 Engine No G4FGGH667939 Make/Model KIA/CERATO K3 1.6 A EX Colour/Trim D7U / WK
Contact No Mobile: 94319489	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	21/12/2017/ 19:04	DS	218 / MarsLer	49416

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60 80.00
S MIPNT88088 TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS			NN	X 600.00
S MIPNT88088 TO REPLACE REAR BUMPER,REAR BEAM,ETC -REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				600 1800.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				420 1260.00
P KS 86611 A7 800 COVER - REAR BUMPER	1.00	668.00	10.00	601.20
M KS 86695 A7 800 COVER - REAR BUMPER	1.00	347.00	10.00	312.30
M KS 86631 A7 800 BEAM - REAR BUMPER	1.00	313.00	10.00	281.70
M KS 86641 A7 800 STAY - REAR BUMPER	1.00	120.00	10.00	108.00
M KS 86642 A7 800 STAY - REAR BUMPER	1.00	120.00	10.00	108.00
M KS 86613 A7 001 LH BRACKET - REAR BU	1.00	29.00	10.00	26.10
M KS 86614 A7 001 RH BRACKET - REAR BU	1.00	29.00	10.00	26.10
P JJMR328954 CLIP,RR BUMPER CLIP	10.00	3.00	10.00	27.00

Z NOTES

ACCIDENT ON 12/12/2017 ALONG COMMONWEALTH AVENUE WEST
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP : SKC5139E TP INS : EQ

3 Days
before paint photos
27/12/17

LK&C Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

Gundariap - 82880282

Parts	1,490.40
Labour	0.00
Standard Menu	0.00
Specialist Job	3,740.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	5,230.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DM17HO02904
Our ref: CC3/EQ117024248/Gwa3

Date: 05.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SLQ 5403G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.12.2017 at the premises of M/s Cycle & Carriage, Fulco Motor Dealer Pte Ltd - Ubi and have the following to report:

Workshop Estimate Amount	: S\$	5,230.40
Revised Estimate Amount	: S\$	1,419.30
"Check" Items Amount	: S\$	497.70
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>
Sent: Thursday, 28 December, 2017 9:25 AM
To: Mei Kwan (LKKAUTO)
Cc: Vivian Lau (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SKC5139E (OI : EQI - DM17HO02904) AND SLQ5403G (TP : LKK REF - CC3/EQI17024248/wa3) on 12/12/2017
Attachments: SKC5139E 12.12.2017.pdf
Categories: HMK

Dear Mei Kwan

Please find attached.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, December 27, 2017 7:22 PM
To: Bazlin Ahmad
Cc: Vivian Lau (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SKC5139E (OI : EQI - TBA) AND SLQ5403G (TP : LKK REF - CC3/EQI17024248/wa3) on 12/12/2017

WITHOUT PREJUDICE

Dear Lynn,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

"Wishes you a Happy New Year 2018"

Thank you.

Best Regards,



CYCLE & CARRIAGE

Our Ref : SLQ5403G
Your Ref : SKC5139E

A.R. REGISTERED

January 31, 2018

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD # 17-00
TOWER BLOCK , MND COMPLEX
SINGAPORE 069110

Attention: Motor Claims

Dear Sir/Madam,

Repair Services Rendered to Vehicle Reg. No.SLQ5403G – Accident on 12/12/2017
Along COMMONWEALTH AVENUE WEST.

We are pleased to enclose our invoice number **77357121** dated 23/01/2018 amounting as follows:

Cost of Repair	S\$1518.65
Loss of USE 03DAYS80/DAYS	S\$ 240.00
LTA Search Fee	S\$ 2.00
Grand Total	S\$ 1760.65

In addition, attached are the supporting documents of repair services rendered to the abovementioned vehicle.

Please acknowledge receipt of the same.

Take Notice, the agreed settlement and acceptance for this case is subject to the understanding that we must receive your payment for the agreed sum within 30 days herein. Failing to, the above-mentioned agreed settlement and acceptance is considered void and nil and we will proceed to forward this case to our solicitors to proceed accordingly without further notices to you. To avoid unnecessary legal fees, kindly let us have your payment as stipulated above

Thank you.

Yours sincerely



Cycle & Carriage –Fulco Motor Dealer Pte Ltd
Eunos Service Centre

Encs.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3EQI17024248/Gwa3

11 JANUARY 2018

SOON KONG YONG
174A EDGEDALE PLAINS
#04-157
SINGAPORE 821174

Dear Sir/Madam,

ACCIDENT INVOLVING SKC 5139E AND SLQ 5403G ON 12.12.17

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING SLQ5403G AND SKC5139E ON 12/12/2017
Own Vehicle's Number Other Vehicle's Number Date Of Accident

Along COMMONWEALTH AVENUE WEST (TRAFFIC JUNCTION)
Accident Location

BY THE LETTER OF AUTHORITY, I/We LIM TIEN THENG JEANNE
Name of Policy Holder & NRIC/Passport/Fin #

Of BLK 413 BEDOK NORTH AVENUE 2 #10-156 SINGAPORE 460413
Address of Policy Holder

Owner of Vehicle Registration Number SLQ5403G hereby authorize **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** to act for me with respect to my claim for repair cost and Car Rental and/or Loss of Use ("claim")
Own Vehicle Number
for my vehicle SLQ5403G that was damaged.
Own Vehicle Number

I further Authorized **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** To settle my above mentioned claim in a manner that they deem fit and **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** Is further Authorize to Signed on my behalf & receive payment further to settlement cheque/s of my claim with payment being made in favour of **Cycle & Carriage-Fulco Motor Dealer Pte Ltd** I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis in so far as the driver/owner/insurers of the vehicle/s is concerned.

Dated this 8 Day of JANUARY (Month) 2018 (Year)



LIM TIEN THENG JEANNE
Signed By Claimant/Policy Holder



Signed by "The Workshop"





CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



TAX INVOICE

Co Reg No : 1997073032

GST Reg No : 19-9707303-2

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name /Mr Lim Tien Theng Jeanne Reg No/Reg Date SLQ5403G*1F / 14/07/2017 Date In/Mileage 21/12/2017/ 1574 Chassis/Package KNAFX411MH5697733 /KC17(F) Engine No G4FGGH667939 Make/Model KIA/CERATO K3 1.6 A EX Colour/Trim D7U / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
F0000061	Credit	23/01/2018/ 11:07	DS	323 / ChrisBulaclac	49416	77357121		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS								60.00
S MIPNT88088 TO REPLACE REAR BUMPER,REAR BEAM,ETC -REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								600.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								420.00
X	KS B6695 A7 800		COVER - REAR BUMPER,	1.00	347.00	10.00		312.30
X	JJMR328954		CLIP,RR BUMPER CLIP	10.00	3.00	10.00		27.00
Z	NOTES ACCIDENT ON 12/12/2017 ALONG COMMONWEALTH AVENUE WEST OWNER CLAIMING THIRD PARTY LOSS OF USE 03DAYS x \$80.00 = \$240.00 TP : SKC5139E TP INS : EQ INSURANCE							F.O.C.

Parts	339.30	7% GST on	Nett	1,419.30
Labour	0.00			99.35
Standard Menu	0.00			
Specialist Job	1,080.00		Total Payable	1,518.65
Others(Lub,etc)	0.00		Paid	0.00
Sundry	0.00		Total Due	1,518.65
Total(w/o GST)	1,419.30		Balance B/FWD	9,535.31
			Total Payable or C/FWD	11,053.96

Any dispute to the invoice must be made within 3 days.
Cheques should be crossed and made payable to CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - (SERVICE)
This is a computer generated document, no signature is required.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-193066

Date of Request: 21/12/2017

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date: 21/12/2017

Enquiry By: Mars Ler

TP Vehicle No: SKC5139E

Accident Date: 12/12/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKC5139E	EQ Insurance Company Ltd	13/03/2017-12/03/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-193066
Date of Request: 21/12/2017

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 21/12/2017
Enquiry By Mars Ler
TP Vehicle No. SKC5139E
Accident Date 12/12/2017

DESCRIPTION	AMOUNT (\$\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 07/02/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKC 5139E (Insd Veh)	Your Ref. No. : DM17HO02904
	SLQ 5403G (TP Veh)	Our Ref. No. : CC3/EQI17024248/Gwa3q2
Date of Accident	12/12/2017	

Liability	100%	
Final Repair Cost	: \$ 1,518.65	
Loss of Use	: \$ 180.00	3 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	1,700.65	
Final Settlement Sum	: \$ 1,700.65	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	CYCLE & CARRIAGE.FULCO MOTOR DEALER PTE LTD	: \$ 1,700.65
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC3/EQ17024248/Gwa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 07-02-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 5139E	Veh. Inspected	SLQ 5403G	
Policy No.	DMPPHQ17-001451	Coverage (\$)	0.00	
Claim No.	DM17HO02904	Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAFX411MH5697733	Colour	GREY	
Odometer	7633	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	8 mm	
L/H Front Tyre	205/55 R16	NEXEN	8 mm	
R/H Rear Tyre	205/55 R16	NEXEN	8 mm	
L/H Rear Tyre	205/55 R16	NEXEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/12/2017	Inspection Date	27/12/2017	
Survey held at	CYCLE & CARRIAGE FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5403G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-REAR BUMPER (SN)	TO REPAIR SEE LABOUR	601.20	-
1	COVER-REAR BUMPER (SN)	CUT	312.30	312.30
1	BEAM-REAR BUMPER (SN)	NOT NECESSARY	281.70	-
1	STAY -REAR BUMPER (SN)	NOT NECESSARY	108.00	-
1	STAY -REAR BUMPER (SN)	NOT NECESSARY	108.00	-
1	LH BRACKET -REAR BU(SN)	NOT NECESSARY	26.10	-
1	RH BRACKET -REAR BU(SN)	NOT NECESSARY	26.10	-
10	CLIP,RR BUMPER CLIP (SN)	NECESSARY	27.00	27.00
			1,490.40	339.30
	LABOUR			
	TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		80.00	60.00
	TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	NOT NECESSARY	600.00	-
	TO REPLACE REAR BUMPER,REAR BEAM,ETC -REPAIR REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF COVER-REAR BUMPER.		1,800.00	600.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		1,260.00	420.00
			3,740.00	1,080.00
	GRAND TOTAL		5,230.40	1,419.30
	RECOMMENDED COST OF REPAIRS			1,419.30

Report Ref No. CC3/EQ117024248/Gwa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.