

15/5/2010

INS. CASE OWNER:

CC 4/EQ1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
26/1/18	Non-Reporting ltr (1st):	
26/1/18	Non-Reporting ltr (2nd):	
26/1/18	Non-Reporting ltr (Final):	
28-12-17	Notification ltr (if non-pickup):	
28-12-17	Call OI:	
28-12-17	After call ltr to OI:	
28-12-17	Documentation Check List:	
28-12-17	Notification ltr (if non-pickup):	
28-12-17	After call ltr to OI:	
28-12-17	Authorisation To Act:	
28-12-17	Release Voucher:	
28-12-17	Final Repair Bill:	
28-12-17	Car Rental Invoice:	
28-12-17	Towing Invoice:	
28-12-17	LTA / GIA:	
28-12-17	Medical Bill:	
28-12-17	PIR:	
28-12-17	Mandate/Reject Instruction:	
28-12-17	LOD:	
28-12-17	Payment Breakdown Form:	
28-12-17	Post-Repair Photos:	
28-12-17	Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

MRS. QUAK

Email

Call

Final Liability:

SS

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: W GST

SS

3,317.xx

Loss of Rental (LOR):

SS

500.xx

(5 days) X 100

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR

LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

x y

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,817.xx

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,817.00

Name 1:

CITY AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI17024268/Kjb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 22-12-2017	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 7078B	Veh. Inspected	SLQ 5019H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspector Date	26/12/2017
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI17024268/Kjb3

Date: 27.12.2017

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLO5019H


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.12.2017 at the premises of M/s City Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,900.50
Revised Estimate Amount	: S\$	3,534.60
"Check" Items Amount	: S\$	574.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

EQ Insurance Co Ltd Singapore
 5 Maxwell Road #17-00
 Tower Block MND Complex
 Singapore 069110

Attention : Motor Claim Department
 Contact : 62239433 Fax No. : 62243903

Estimate : ES004936

Date : 20/12/2017
 Vehicle Num. : SLQ 5019H
 Make/Model : Volkswagen Golf
 Chassis/Eng# : WVVZZZAUZEW358208 (2014)
 Accident Date : 18/12/2017
 Claim No. : TP EQ
 Reference : -
 Policy No. : 5093841158

*Not authorized
 1. B 1
 Reclaim by party
 4 days*

S/N Quantity Particular Unit Price Amount SS

LIST ITEMS :			
1.	1	Rear boot	<i>Ry</i> 1,350.00 ✓
2.	1	Rear boot emblem - logo	<i>Im</i> 128.00 X
3.	1	Rear boot emblem - golf	<i>ve</i> 98.00 ✓
4.	1	Rear boot emblem - TSI	<i>ve</i> 98.00 ✓
5.	1	Rear boot emblem - bluemotion	<i>ve</i> 98.00 ✓
6.	1	Rear bumper	<i>Bu</i> 690.00 ✓
7.	1	Rear bumper reinforcement	<i>Bt</i> 418.00 71
8.	1	Tow cover	<i>Im</i> 35.00 X
9.	1	Rear bumper top garnish	<i>Not/WT</i> 210.00 ✓
10.	1	Rear end panel	<i>It</i> 1,150.00 X
11.	1	Number plate garnish	<i>R</i> 135.00 74
12.	1	Rear bumper lamp	<i>ve</i> 85.00 74
List Total SS :			4,495.00 2,462.00
10.00% Discount SS :			449.50
			4,045.50
SPECIAL NETT ITEMS :			
1.	1	Reverse sensor	<i>Per</i> 250.00 2005m
2.	1	Number plate	<i>Ry</i> 25.00 } 455m
3.	1	Number plate casing	35.00
Special Nett Total SS :			310.00 245.00

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

EQ Insurance Co Ltd Singapore
 5 Maxwell Road #17-00
 Tower Block MND Complex
 Singapore 069110

Attention : Motor Claim Department

Contact : 62239433 Fax No. : 62243903

Estimate : ES004936

Date : 20/12/2017
 Vehicle Num. : SLQ 5019H
 Make/Model : Volkswagen Golf
 Chassis/Eng# : WWWZZZAUZEW358208 (2014)
 Accident Date : 18/12/2017
 Claim No. : TP EQ
 Reference : -
 Policy No. : 5093841158

S/N Quantity Particular

Unit Price Amount S\$

LABOUR :

- *To check and rewiring
- *To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- *Spray painting on affected & replace parts

45.00 *201*

650.00 *4801*

850.00 *5001*

Labour Total S\$:

1,545.00 *1,000.00*

P- \$ 2,962.00
 - 10/-
 2,962.00

SN - \$ 245.00

4s - \$ 3,150.00
 4 Days

L- \$ 1,000.00
 \$ 3,910.80
 - 2070
 \$ 3,123.64

E. & O.E.

Total S\$: 5,900.50

=====

HA

for CITY AUTO PTE LTD



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

EQ Insurance Co Ltd Singapore
 5 Maxwell Road #17-00
 Tower Block MND Complex
 Singapore 069110

Attention : Motor Claim Department

Contact : 62239433 Fax No. : 62243903

Estimate : ES004936

Date : 20/12/2017

Vehicle Num. : SLQ 5019H

Make/Model : Volkswagen Golf

Chassis/Eng# : WWZZZAUZEW358208 (2014)

Accident Date : 18/12/2017

Claim No. : TP EQ

Reference : -

Policy No. : 5093841158

*Not authorized
 1.B.1
 Running B&P
 4 days*

S/N Quantity Particular

Unit Price Amount S\$

- | S/N | Quantity | Particular |
|-----|----------|-------------------------------|
| 1. | 1 | LIST ITEMS : |
| 2. | 1 | Rear boot |
| 3. | 1 | Rear boot emblem - logo |
| 4. | 1 | Rear boot emblem - golf |
| 5. | 1 | Rear boot emblem - TSI |
| 6. | 1 | Rear boot emblem - bluemotion |
| 7. | 1 | Rear bumper |
| 8. | 1 | Rear bumper reinforcement |
| 9. | 1 | Tow cover |
| 10. | 1 | Rear bumper top garnish |
| 11. | 1 | Rear end panel |
| 12. | 1 | Number plate garnish |
| 13. | 1 | Rear bumper lamp |

List Total S\$:

10.00% Discount S\$:

SPECIAL NETT ITEMS :

- | | | |
|----|---|---------------------|
| 1. | 1 | Reverse sensor |
| 2. | 1 | Number plate |
| 3. | 1 | Number plate casing |

Special Nett Total S\$:

<i>By</i>	1,350.00	✓
<i>Sm</i>	128.00	x
<i>Nc</i>	98.00	—
<i>Nc</i>	98.00	—
<i>Nc</i>	98.00	—
<i>By</i>	690.00	✓
	418.00	✓
<i>Sm</i>	35.00	x
<i>Not/Wt</i>	210.00	✓
<i>N</i>	1,150.00	x
	135.00	✓
	85.00	✓
	4,495.00	
	449.50	
	4,045.50	

<i>Per</i>	250.00	<i>2005n</i>
<i>By</i>	25.00	} <i>455n</i>
	35.00	
	310.00	

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

EQ Insurance Co Ltd Singapore

5 Maxwell Road #17-00
 Tower Block MND Complex
 Singapore 069110

Attention : Motor Claim Department

Contact : 62239433 Fax No. : 62243903

Estimate : ES004936

Date : 20/12/2017

Vehicle Num. : SLQ 5019H

Make/Model : Volkswagen Golf

Chassis/Eng# : WWZZZAUZEW358208 (2014)

Accident Date : 18/12/2017

Claim No. : TP EQ

Reference : -

Policy No. : 5093841158

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

- *To check and rewiring
- *To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- *Spray painting on affected & replace parts

45.00 *200*

650.00 *4800*

850.00 *5000*

1,545.00

Labour Total S\$:

E. & O.E.

Total S\$: 5,900.50

=====

HA
 for CITY AUTO PTE LTD

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Friday, 22 December, 2017 10:35 AM
To: assignments
Cc: Admin A
Subject: FW: Our ref: GBA7078B- Arrange survey for SLQ5019H

Hi Cath,

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

22/12/2017 @ 10:40am
Vronica veh not in

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Friday, 22 December, 2017 10:32 AM
To: City Auto <cityauto@singnet.com.sg>; Admin A <admin-a@lkkauto.com>
Cc: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Subject: Our ref: GBA7078B- Arrange survey for SLQ5019H

Without Prejudice ***Save As To Costs***

Dear Vronica

Please be informed that Hansel Ang is no longer at EQI and Tan Wei Yin is no longer handling motor claims.

For future cases, please email to elaine.cheong@eqinsurance.com.sg; Bazlin Ahmad bazlin.ahmad@eqinsurance.com.sg and janet.tan@eqinsurance.com.sg

Otherwise, please fax to 6223 4190.

Aside to LKK, please take note of the date of assignment and proceed to direct settle if possible.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



From: City Auto [mailto:cityauto@singnet.com.sg]
Sent: Friday, December 22, 2017 10:01 AM
To: Hansel Ang <hansel.ang@eqinsurance.com.sg>
Cc: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Subject: Arrange survey for SLQ5019H

Dear Motor survey department,

Kindly arrange **LKK Auto Consultants Pte Ltd** survey on Tuesday 26/12/2017 10:00AM-12:00PM on following vehicle :

Resurvey TP

Your vehicle : GBA7078B

Our vehicle : SLQ5019H

D.O.A : 18/12/2017

LOCATION : Blk 8, Sin Ming Industrial Estate Sector B #01-58/60/62 Singapore 575643.

Thank you.

Best Regards,

Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MANC/716772 Vehicle Registration No: GBA 7078B
Name (as shown in NRIC) : TRANS ORIENT SINGAPORE PTE LTD NRIC/FIN/Passport No : 201216852
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate.
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 98061782
Email Address : _____
Date of Accident : 19/12/2017 Time of Accident : 12.00 p.m
Place of Accident : Along Rocher Road.
Insurance Company: EQ INSURANCE


(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1.) To amend the insurance company.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Thursday, 28 December, 2017 12:03 PM
To: City Auto
Cc: Admin A; Shu Pei (LKKAUTO)
Subject: RE: Our ref: GBA7078B- Arrange survey for SLQ5019H ***LKK
REF:CC4/EQI17024268/Kjb3

WITHOUT PREJUDICE

Dear Vronica,

With reference to the subject.

Please be informed that basing on the accident statements submitted by parties involved, the liability is clear.

Please note that this e-mail is on without prejudice basis and does not amount to an authorisation of repair to your client's vehicle. Further, contents herein should not be construed as an admission of any liability, confirmation of damages whatsoever to our Insured's part. The final repair cost is subject to the consistency of the damages according to the nature of the accident. And the days for losses(use and/or rental) will be based on the number of days of repair recommended by our surveyor.

Kindly forward your Letter of Demand and all supporting documents to us as soon as possible.

Please amend your date of accident in your client's report from 18/12/2017 to 19/12/2017.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Shu Pei (LKKAUTO)
Sent: Thursday, 28 December, 2017 10:01 AM
To: City Auto <cityauto@singnet.com.sg>
Cc: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>
Subject: RE: Our ref: GBA7078B- Arrange survey for SLQ5019H ***LKK REF:CC4/EQI17024268/Kjb3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 13/02/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBA 7078B (Insd Veh)	Your Ref. No. : DMCPHQ17-004032
	SLQ 5019H (TP Veh)	Our Ref. No. : CC4/EQI17024268/Kjb3s2
Date of Accident	19/12/2017	

Liability	100%	
Final Repair Cost	: \$ 3,317.00	(W/GST)
Loss of Use	: \$	days
Rental (If any)	: \$ 500.00	5 days
Others:	: \$	
	: \$	
	3,817.00	
Final Settlement Sum	: \$ 3,817.00	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	CITY AUTO PTE LTD	: \$ 3,817.00
		: \$

NUR SHAQILAH
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ117024268/Kjb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 13-02-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7078B	Veh. Inspected	SLQ 5019H
Policy No.	DMCPHQ17-004032	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF TSI (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WVWZZZAUZEW358208	Colour	METALLIC GREY
Odometer	51382	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	PIRELLI	3 mm
L/H Front Tyre	225/45R17	PIRELLI	3 mm
R/H Rear Tyre	225/45R17	PIRELLI	4 mm
L/H Rear Tyre	225/45R17	PIRELLI	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/12/2017	Inspection Date	26/12/2017
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5019H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	BENT	1,350.00	1,350.00
1	REAR BOOT EMBLEM - LOGO	SERVICEABLE	128.00	-
1	REAR BOOT EMBLEM - GOLF	NECESSARY	98.00	98.00
1	REAR BOOT EMBLEM - TSI	NECESSARY	98.00	98.00
1	REAR BOOT EMBLEM - BLUEMOTION	NECESSARY	98.00	98.00
1	REAR BUMPER	BUCKLED	690.00	690.00
1	REAR BUMPER REINFORCEMENT	BENT	418.00	418.00
1	TOW COVER	SERVICEABLE	35.00	-
1	REAR BUMPER TOP GARNISH	DENTED / CUT	210.00	210.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,150.00	-
1	NUMBER PLATE GARNISH	SERVICEABLE	135.00	-
1	REAR BUMPER LAMP	SERVICEABLE	85.00	-
	LESS 10% DISCOUNT		-449.50	-296.20
			4,045.50	2,665.80
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SCRATCHED	250.00	200.00
1	NUMBER PLATE (SN) }	BENT	25.00	45.00
1	NUMBER PLATE CASING (SN) }		35.00	-
			310.00	245.00
<u>LABOUR</u>				
	TO CHECK AND REWIRING.		45.00	20.00
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		650.00	480.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		850.00	500.00
			1,545.00	1,000.00
GRAND TOTAL			5,900.50	3,910.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC4/EQ17024268/Kjb3s2



Report Ref No. CC4/EQI17024268/Kjb3s2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.