

INS CASE OWNER:

WILSON

CC6 / LCR170 242731 UJ93

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

MIMIX

Date / Time:

22/12/17

Registered in Merimen:

22/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 89360

Name of Insured:

LCR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ZULKIFLI BEN IBRAHIM

Driver Tel No.:

(V/L YES / NO)

Claim No.:

348748487454

Policy No.:

799995170

Make / Model:

HONDA VIZOL

Place of Accident:

WOODLANDS RD (TOWARD CATT)

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Insured Liability:

%

Final ? Yes / No

FS 6694C



INSRS:

WSP:

Tel:

Liability:

RMKS:

EROFIA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

FS 6694C - X ; SLE 89360 - X

26.12.17

OI STRAIGHT

TP TURNING

TO GET TP EVIDENCE, OTHERWISE
REJECT.

TP - NO EVIDENCE.

TP - WARNED BY TRAFFIC POL.

AIG MANDATE TO REJECT.

Reject Case

Approved by: [Signature]
Date: 05/01/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

☐ ☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

0

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

HIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/Independent)

Legal Cost

S\$

-

Total:

S\$

-

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

-

Name 1:

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

COPY SENT
18/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1320

Surveyor

REF:

ALG

Ref: 17024273/US3

ASSIGNMENT

From: _____ Date: 22/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FSG694L

at Workshop m/s Erofia Motor

of No. 1, Kaki Bukit Ave 6 # 02-62

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5

days

Res: _____

Yes or No

Lum Sum: _____

20

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

lup 10/2020

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: FS6694L Regn: 1000

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda NSR150SP cc 149

Colour: blue/white A/C: Insured / Std / NI / NA

Sp. Reading: 67518 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: _____

90-80-17

R: _____

110-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal: _____

5

mm

R/Bal: _____

5

mm

L/Bal: _____

mm

L/Bal: _____

mm

D.O.A: _____

11/12/17

D.O.I: _____

22/12/17

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS - O/S 2 sh.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L74 615

2048x

2 yrs 10 mths

vehicle hasn't send in for repair warning by traffic police.

4/5 & 3/00

R (\$ 4,373.60/599)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

Site Insp: (\$ _____)

☐

Interview: (\$ _____)

☐

Tech. Invs: (\$ _____)

☐

Weekend: (\$ _____)

\$ - RS - \$

Photos

Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR17024273/Ujs3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 22-12-2017



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 8936D	Veh. Inspected	FS 6694L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/12/2017	Inspection Date	22/12/2017
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit, Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Keefe Kendrick Lee

Accident Date : 11-Dec-17

Vehicle No : FS 6694 L

Vehicle Model : Honda NSR150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Top cowling	24/12/17 \$ 627 165.00
1	Windshield	\$ 500 75.00
1	Headlamp	\$ 17 165.00
1	Front fender	\$ 627 68.00
2	Fork inner tubes	\$ 2 420.00
2	Fork outer tubes	\$ 2 430.00
1	Fork under bracket	\$ 17 125.00
1	Fork under bracket	\$ 17 175.00
1	Front brake disc	\$ 17 155.00
1	Front sport rim	\$ 17 280.00
1	Front rim shaft	\$ 17 38.00
2	Side mirrors	\$ 0/500 70.00
2	Handle bars	\$ 50 210.00
2	Handle bar ends	\$ 50 36.00
1	Hand grip (1 set)	\$ 70 40.00
1	Clutch lever	\$ 17 15.00
1	Brake lever	\$ 50 18.00
2	Front signals	\$ 00 84.00
2	Centre fairings	\$ 00 170.00
2	Lower fairings	\$ 600 230.00
2	Air intake tubes	\$ 00 76.00
1	Centre inner fairing	\$ 00 75.00
2	Inner panels	\$ 70 40.00
1	Radiator	\$ 70 210.00
1	Radiator grille	\$ 70 38.00
1	Lampstay	\$ 17 75.00
1	Fuel tank	\$ 00 385.00
2	Rear footrests	\$ 50 80.00
2	Rear footrest brackets	\$ 50 130.00
1	Exhaust pipe	\$ 50 380.00
2	Rear tailboards	\$ 00 250.00
1	Rear centre cowling	\$ 00 28.00
1	Chain guard	\$ 00 48.00
1	Rear sport rim	\$ 00 280.00
1	Swing arm	\$ 2 980.00
		\$ 6,044.00
	Less 10%	\$ 604.40
		\$ 5,439.60

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Keefe Kendrick Lee

Accident Date : 11-Dec-17

Vehicle No : FS 6694 L

Vehicle Model : Honda NSR150

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ <i>net</i>	28.00	<i>10</i>
2	Fork oils	\$ <i>net</i>	30.00	<i>✓</i>
2	Fork oil seals	\$ <i>net</i>	56.00	<i>✓</i>
1	Steering cone (1 set)	\$ <i>net</i>	75.00	<i>✓</i>
1	Racing footrest (1 set)	\$ <i>tm</i>	250.00	<i>150</i>
1	Front tyre	\$ <i>net</i>	120.00	<i>α</i>
1	Rear tyre	\$ <i>net</i>	120.00	<i>α</i>
		\$	679.00	

S/No.

Labour

1	To provide towing service.	\$ <i>30</i>	45.00	
2	To check wiring and reset headlamp focusing.	\$ <i>net</i>	80.00	<i>α</i>
3	To provide labour.	\$ <i>280</i>	380.00	
4	To respray painting.	\$ <i>300</i>	450.00	
5	To repair body frame.	\$ <i>200</i>	400.00	
		\$	1,355.00	

Grand Total

\$ 7,473.60

Dollars: Seven Thousand Four Hundred Seventy-Three And Sixty Cents Only.

EROFIA MOTOR TRADING PTE LTD

EROFIA MOTOR TRADING PTE LTD hereby
represents and warrants that the following:
• To resurvey below after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2048Z
Vehicle Details	
Vehicle No.:	F56694L
Vehicle to be Exported:	No
Intended De-registration Date:	22 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	NSR150SP
Primary Colour:	Green
Manufacturing Year:	2000
Engine No.:	NS150SPE0010490
Chassis No.:	NS150SP0010490
Maximum Power Output:	-
Open Market Value:	\$4,200.00
Original Registration Date:	16 Oct 2000
First Registration Date:	16 Oct 2000
Transfer Count:	12
Actual ARF Paid:	\$630.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Oct 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,353.00
COE Rebate Amount:	\$615.00

Bike model

Type

Any



Price From

Any



Price To

Any



Class

Any



MORE SEARCH OPTIONS ▼

SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)

SEARCH ▼

Honda NSR150SP (/listing/usedbike/honda-honda-nsr150sp/3234/)



(/listing/usedbike/honda-honda-nsr150sp/3234/)

SGD\$3600

Reg : 21/03/2000

Type: **Sport Bikes**

149cc

Good condition. Come to Yong Seng Heng Motor. Price is Neg. Trade in/Loan Available.

Posted on : 21/12/2017

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-NSR150SP/3234/)

Honda NSR150SP (/listing/usedbike/honda-honda-nsr150sp/2315/)

(/listing/usedbike/honda-honda-nsr150sp/2315/)

sgd\$2500

Reg : 23/12/1999

Type: Sport Bikes

149cc

Honda NSR150SP for sale. Welcome trade in. Loan available. Ambra Enterprises is located at Blk 5034 Ang Mo Kio Industrial Park 2 #01-327.

Posted on : 02/12/2017

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-NSR150SP/2315/)

Honda NSR150SP (/listing/usedbike/honda-honda-nsr150sp/5066/)

(/listing/usedbike/honda-honda-nsr150sp/5066/)

sgd\$3500

Reg : 12/10/2001

Type: Sport Bikes

149cc

COE Renewable. What you see is what you will get. Viewing at CCK Area.

Posted on : 18/12/2017

★ DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-NSR150SP/5066/)

Honda NSR150SP (/listing/usedbike/honda-honda-nsr150sp/5042/)

Engine Capacity	149cc
Classification	2B
Registration Date	21/03/2000
COE Expiry Date	29/02/2020 (2 years 2 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Sport Bikes (/listing/usedbikes/listing/?bike_type=8)

Price: SGD\$3600

Details

Good condition. Come to Yong Seng Heng Motor. Price is Neg. Trade in/Loan Available.



Similar Bikes

[View All \(/listing/usedbikes/listing/\)](/listing/usedbikes/listing/)



Honda NSR150SP
(/listing/usedbike/honda-honda-nsr150sp/3234/)



Honda NSR150SP
(/listing/usedbike/honda-honda-nsr150sp/2315/)



Honda NSR150SP



Honda NSR150SP

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 3 August 2018 5:13 PM
To: 'erofia@singnet.com.sg'
Cc: Admin A
Subject: FS 6694C AND SLE 8936D ON 11.12.2017

WITHOUT PREJUDICE

Dear Sirs,

We refer to the subject.

Our insured reiterated that the accident was due to the entire negligence of your client my turning whilst our insured was travelling straight.

We reviewed the matter and basing on the agreed reported scenario by the parties involved, we are of the opinion that onus is unto the turning vehicle.

In view of the above, we regret to inform you that we are unable to look into your claim.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2017 Edit Reg		22 Dec 2017 00:00 Edit Adj Rpt	\$3,100.00 Edit Estimates	\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Main Claimant:	KEEFE KENDRICK LEE, ID: S9740416Z			
Vehicle Reg. No.:	FS6694L	Date of Loss:	11/12/2017 00:00 - :59 [205 Months and 25 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 3482484824SG	Policy/Cover Note No.:	(Comprehensive)	
Vehicle Reg. No. (Insured):	SLE8936D	Policy No. (Claimant):	5098381793TP	
		Excess:		
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/01/2018]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (03/08/2018): Alert - Adj Mandate Approved (\$0.00) - FS6694L - Claim Handler: Tan, Wilson-KL
- AIG_SG (26/12/2017): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FS6694L (3482484824SG)
[SLE8936D]
TP
KEEFE KENDRICK LEE
Dec 11 2017 12:00AM
[LCRF PTE LTD]
Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	22/12/17 15:28	Chassis Number														Load JPG	☒			
2	22/12/17 15:28	Odometer Reading														Load JPG	☒			
3	22/12/17 15:28	General View														Load JPG	☒			
4	22/12/17 15:28	General View														Load JPG	☒			
5	22/12/17 15:28	General View														Load JPG	☒			
6	22/12/17 15:28	General View														Load JPG	☒			
7	22/12/17 15:28	General View														Load JPG	☒			
8	22/12/17 15:28	General View														Load JPG	☒			
9	22/12/17 15:28	General View														Load JPG	☒			
10	22/12/17 15:28	General View														Load JPG	☒			
11	22/12/17 15:28	General View														Load JPG	☒			
12	22/12/17 15:28	General View														Load JPG	☒			
13	22/12/17 15:28	General View														Load JPG	☒			
14	22/12/17 15:28	General View														Load JPG	☒			
15	22/12/17 15:28	General View														Load JPG	☒			
16	22/12/17 15:28	General View														Load JPG	☒			
17	22/12/17 15:28	General View														Load JPG	☒			
18	22/12/17 15:28	General View														Load JPG	☒			
19	22/12/17 15:28	General View														Load JPG	☒			
20	22/12/17 15:28	General View														Load JPG	☒			
21	22/12/17 15:28	General View														Load JPG	☒			
22	22/12/17 15:28	General View														Load JPG	☒			
23	22/12/17 15:28	General View														Load JPG	☒			
24	22/12/17 15:28	General View														Load JPG	☒			
25	22/12/17 15:28	General View														Load JPG	☒			
26	22/12/17 15:28	General View														Load JPG	☒			
27	22/12/17 15:28	General View														Load JPG	☒			
28	22/12/17 15:28	General View														Load JPG	☒			
29	22/12/17 15:28	General View														Load JPG	☒			
30	22/12/17 15:28	General View														Load JPG	☒			
31	22/12/17 15:28	General View														Load JPG	☒			
32	22/12/17 15:28	General View														Load JPG	☒			
33	22/12/17 15:28	General View														Load JPG	☒			
34	22/12/17 15:28	General View														Load JPG	☒			
35	22/12/17 15:28	General View														Load JPG	☒			
36	22/12/17 15:28	General View														Load JPG	☒			
37	22/12/17 15:28	General View														Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/12/17 15:28	General View	 Load JPG	☒
39	22/12/17 15:28	General View	 Load JPG	☒
40	22/12/17 15:29	General View	 Load JPG	☒
41	22/12/17 15:29	General View	 Load JPG	☒
42	22/12/17 15:29	General View	 Load JPG	☒
43	22/12/17 15:29	General View	 Load JPG	☒
44	22/12/17 15:29	General View	 Load JPG	☒
45	22/12/17 15:29	General View	 Load JPG	☒
46	22/12/17 15:29	General View	 Load JPG	☒
47	22/12/17 15:29	General View	 Load JPG	☒
48	22/12/17 15:29	General View	 Load JPG	☒
49	22/12/17 15:29	General View	 Load JPG	☒
50	22/12/17 15:29	General View	 Load JPG	☒
51	22/12/17 15:29	General View	 Load JPG	☒
52	22/12/17 15:29	General View	 Load JPG	☒
53	22/12/17 15:29	General View	 Load JPG	☒
54	22/12/17 15:29	General View	 Load JPG	☒
55	22/12/17 15:29	General View	 Load JPG	☒
56	22/12/17 15:29	General View	 Load JPG	☒
57	22/12/17 15:29	General View	 Load JPG	☒
58	22/12/17 15:29	General View	 Load JPG	☒
59	22/12/17 15:29	General View	 Load JPG	☒
60	22/12/17 15:29	General View	 Load JPG	☒
61	22/12/17 15:29	General View	 Load JPG	☒
62	22/12/17 15:29	General View	 Load JPG	☒
63	22/12/17 15:29	General View	 Load JPG	☒
64	22/12/17 15:29	General View	 Load JPG	☒
65	22/12/17 15:29	General View	 Load JPG	☒
66	22/12/17 15:29	General View	 Load JPG	☒
67	22/12/17 15:29	General View	 Load JPG	☒
68	22/12/17 15:29	General View	 Load JPG	☒
69	22/12/17 15:29	General View	 Load JPG	☒
70	22/12/17 15:29	General View	 Load JPG	☒
71	22/12/17 15:29	General View	 Load JPG	☒
72	22/12/17 15:29	General View	 Load JPG	☒
73	22/12/17 15:29	General View	 Load JPG	☒
74	22/12/17 15:29	General View	 Load JPG	☒
75	22/12/17 15:29	General View	 Load JPG	☒
76	22/12/17 15:29	General View	 Load JPG	☒
77	22/12/17 15:29	General View	 Load JPG	☒
78	22/12/17 15:29	General View	 Load JPG	☒
79	22/12/17 15:29	General View	 Load JPG	☒
80	22/12/17 15:29	General View	 Load JPG	☒
81	22/12/17 15:29	General View	 Load JPG	☒
82	22/12/17 15:29	General View	 Load JPG	☒
83	22/12/17 15:29	General View	 Load JPG	☒
84	22/12/17 15:29	General View	 Load JPG	☒
85	22/12/17 15:29	General View	 Load JPG	☒
86	22/12/17 15:29	General View	 Load JPG	☒
87	22/12/17 15:29	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	22/12/17 15:29	General View	 Load JPG	☒
89	22/12/17 15:29	General View	 Load JPG	☒
90	22/12/17 15:29	General View	 Load JPG	☒
91	22/12/17 15:29	General View	 Load JPG	☒
92	22/12/17 15:29	General View	 Load JPG	☒
93	22/12/17 15:29	General View	 Load JPG	☒
94	22/12/17 15:29	General View	 Load JPG	☒
95	22/12/17 15:29	General View	 Load JPG	☒
96	22/12/17 15:29	General View	 Load JPG	☒
97	22/12/17 15:29	General View	 Load JPG	☒
98	22/12/17 15:29	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/17 11:46	ACKNOWLEDGEMENT EMAIL TO AIG DD 21.12.2017	 Load PDF	
2	26/12/17 11:47	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load PDF	
3	27/12/17 10:59	TP ESTIMATE- MARKED	 Load PDF	
4	03/08/18 17:14	REJECTION EMAIL	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/12/17 11:16	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17024273/UJA3Q2

Date: 13/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FS6694L

Insured Vehicle No : SLE8936D

Date of Loss: 11/12/2017

Nature of Claim: TP

Claim No: 3482484824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FS6694L**

Make & Model: HONDA NSR150SP, 149cc (M)

Engine No: NS150SPE0010490

Reg. Date: 16/10/2000 (Man. Year: 2000)

Chassis No: NS150SP0010490

Colour: White/Blue

Odometer: 67518 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90-80-17

Rear Tyre Size: 110-70-17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,118.60	3,046.20	3,072.40	50.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,355.00	810.00	545.00	40.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,473.60	3,856.20	3,617.40	48.40
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	7,473.60	3,100.00	4,373.60	58.52
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/12/2017

Date Inspected: 22/12/2017 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Deep Cut	165.00 FL	*165.00 FL
2	1		*WINDSHIELD	Scratched	75.00 FL	*75.00 FL
3	1		*HEADLAMP	Not Necessary	165.00 FL	*- FL
4	1		*FRONT FENDER	Cut	68.00 FL	*68.00 FL
5	2		*FORK INNER TUBES	Repair	420.00 FL	*- FL
6	2		*FORK OUTER TUBES	Repair	430.00 FL	*- FL
7	1		*FORK UNDER BRACKET	Not Necessary	125.00 FL	*- FL
8	1		*FORK UNDER BRACKET	Not Necessary	175.00 FL	*- FL
9	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
10	1		*FRONT SPORT RIM	Not Necessary	280.00 FL	*- FL
11	1		*FRONT RIM SHAFT	Not Necessary	38.00 FL	*- FL
12	1		*SIDE MIRROR	O/S Cut	70.00 FL	*35.00 FL
13	1		*HANDLE BARS	O/S Bent	210.00 FL	*105.00 FL
14	1		*HANDLE BAR ENDS	O/S Scratched	36.00 FL	*18.00 FL
15	1		*SET HAND GRIP	Torn	40.00 FL	*40.00 FL
16	1		*CLUTCH LEVER	Not Necessary	15.00 FL	*- FL
17	1		*BRAKE LEVER	Scratched	18.00 FL	*18.00 FL
18	2		*FRONT SIGNALS	Cracked	84.00 FL	*84.00 FL
19	2		*CENTRE FAIRING	Cracked	170.00 FL	*170.00 FL
20	2		*LOWER FAIRING	Cracked	230.00 FL	*230.00 FL
21	2		*AIR INTAKE TUBES	Cracked	76.00 FL	*76.00 FL
22	1		*CENTRE INNER FAIRING	Cracked	75.00 FL	*75.00 FL
23	2		*INNER PANELS	Twisted	40.00 FL	*40.00 FL
24	1		*RADIATOR	Bent / Punctured	210.00 FL	*210.00 FL
25	1		*RADIATOR GRILLE	Torn	38.00 FL	*38.00 FL
26	1		*LAMPSTAY	Not Necessary	75.00 FL	*- FL
27	1		*FUEL TANK	Dented	385.00 FL	*385.00 FL
28	2		*REAR FOOTREST	Bent	80.00 FL	*80.00 FL
29	2		*REAR FOOTREST BRACKETS	Bent	130.00 FL	*130.00 FL
30	1		*EXHAUST PIPE	Dented / Bent	380.00 FL	*380.00 FL
31	2		*REAR TAILBOARDS	Cracked	250.00 FL	*250.00 FL
32	1		*REAR CENTRE COWLING	Cracked	28.00 FL	*28.00 FL
33	1		*CHAIN GUARD	Cracked	48.00 FL	*48.00 FL
34	1		*REAR SPORT RIM	Dented / Bent	280.00 FL	*280.00 FL
35	1		*SWING ARM	Repair	980.00 FL	*- FL
36	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
37	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
38	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
39	1		*SET STEERING CONE	Necessary	75.00 FS	*75.00 FS
40	1		*SET RACING FOOTREST	Twisted	250.00 FS	*150.00 FS
41	1		*FRONT TYRE	Not Necessary	120.00 FS	*- FS
42	1		*REAR TYRE	Not Necessary	120.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,723.00	3,349.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	604.40	302.80
Total Parts (\$\$)	6,118.60	3,046.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	45.00	30.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	280.00
4	TO RESPRAY PAINTING	New	450.00	300.00
5	TO REPAIR BODY FRAME	New	400.00	200.00
Gross Labour Cost (S\$)			1,355.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >