

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 04 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKS6902C		
TP Vehicle No	: SJV9406U	Accident Date	: 20/12/2017
Make	: KIA CERATO FORTE	Assignment Date	: 22/12/2017
Date of Inspection	: 02/01/2018	Est. Duration of Repair	: 5 days
Inspection At	: Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front & U/C.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,323.90
Revised Amount	:S\$	2,704.20
Check Items (Estimated)	:S\$	1,642.30
Total	:S\$	4,346.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.