

160 Sin Ming Drive, #05-11,

Sin Ming AutoCity

Singapore 575722

(Registration no :095744/00B)

Tel : 64533100, Fax 62669932

DATE OF ACCIDENT : 20/12/2017

YOUR INSURED

VEHICLE NO : SKS 6902C

<u>Estimate repair cost to KIA CERATO FORTE reg no : SJV 9406 U</u>		
1pc front bumper	S\$	CMA 597.00
1pc front bumper n/s retainer		CMA 23.00
1pc n/s front headlamp		CMA 560.00
1pc n/s/f fender		B 485.00
1pc n/s/f fender inner shield		DI 73.00
1pc n/s/f shock absorber		338.00
1pc n/s/f knuckle arm		382.00
1pc n/s/f wheel hub		186.00
1pc n/s/f wheel bearing		159.00
1pc n/s/f lower arm		482.00
1pc n/s/f stabilizer link		SM 86.00
		3371.00
	Less 10%	337.10
		3033.90
<u>Labour & misc charges</u>		
Panel knocking		700.00
Spray painting		800.00
1pc n/s/f sport rim		450.00
Computer wheel alignment		90.00
Labour to remove and refix left under carriage		250.00
		5323.90

HWA SENG SPRAY PAINTING COMPANY

Not Authored
 21 Sep 87
 Penny Ate Penny