



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 17/12/2017

ESTIMATE

NO : QUOT201712-0061(00)
DATE : 19/12/2017
POLICY NO : 999995580
VEH REG NO : GBG7561R
MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR
CHASSIS NO : WDF4156052U221837
ENGINE NO : K9KE628D403738
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7561R

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Front bumper inner carrier	1	285.00	285.00 ✓
2 Washer tank	1	105.00	105.00 ✓
			390.00
		Add 10%	39.00
			429.00
		TOTAL	S\$ 429.00
		ADD GST @ 7%	30.03
		GRAND TOTAL	S\$ 459.03

SINGAPORE DOLLAR FOUR HUNDRED FIFTY-NINE AND CENTS THREE ONLY

8
\$ 5,445.35
XS 1,200.00

\$ 4,745.35
7% 332.17

\$ 5,077.52

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE