

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

1719

Name : Abdul Malik B Bidin

Accident Date : 12-Dec-17

Vehicle No : FC 3995 Y

Vehicle Model : Vespa PX20

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender	\$ 85.00 ✓
1	Front fork assy	\$ 580.00 ?
1	Front shock absorber	\$ 250.00 ?
1	Front fork cover	\$ 42.00 ✓
1	Front rim hub with bearing	\$ 385.00 ?
1	Front rim	\$ 80.00 X
1	Top cowling	\$ 120.00 X
1	Steering lower cowling	\$ 120.00 ✓
1	Front centre cowling	\$ 85.00 ✓
1	Front panel	\$ 320.00 a
2	Front panel chrome mouldings	\$ 220.00 ✓
1	Headlamp rim	\$ 40.00 X
2	Front signals	\$ 130.00 ✓
1	Side mirror -R/H	\$ 60.00 ✓
1	Handle bar	\$ 185.00 ✓
1	Hand grip (1 set)	\$ 38.00 ✓
1	Brake lever	\$ 26.00 ✓
2	Step board panel mouldings	\$ 100.00 ✓
2	Engine covers	\$ 310.00 ✓
2	Engine cover mouldings	\$ 100.00 ✓
1	Kick starter	\$ 90.00 ✓
1	Rear signal -R/H	\$ 55.00 X
1	Main stand	\$ 85.00 ✓
		\$ 3,506.00
	Less 10%	\$ 350.60
		\$ 3,155.40

Not Adjust
RHL
1/5
6 dy.
22/11/17
Vehicle Assembly

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Abdul Malik B Bidin

Accident Date : 12-Dec-17

Vehicle No : FC 3995 Y

Vehicle Model : Vespa PX20


Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	Prof \$ 28.00	10
1	Steering cone (1 set)	\$ 85.00	✓
1	Rear box	\$ 180.00	150
1	Rear box bracket	\$ 100.00	✓
1	Helmet	\$ 75.00	α
		<u>\$ 468.00</u>	

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 50.00	30
2	To provide labour.	\$ 380.00	300
3	To respray painting.	\$ 1,000.00	500
4	To repair body frame.	\$ 450.00	300
		<u>\$ 1,880.00</u>	

Grand Total \$ 5,503.40

Dollars: Five Thousand Five Hundred Three And Forty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: