

Honda Jazz SLF 8435. C

- 1) Rear Bootlid — Solids —
- 2) " " Handle — 11 X
- 3) " " Top Garnish — 11 X
- 4) " " " " Emblem — 11 X
- 5) " " Inner Lock — 701 —
- 6) " " No plate Lamp — 11 X
- 7) " " Glass Sealant — 11 X
- 8) " " Rubber — 11 X
- 9) " " Wiper motor — 11 X
- 10) " " 'JAZZ' plate — 11 X
- 11) Rear No plate Assy — 11 X
- 12) Rear Reverse Camera — 11 X
- 13) Rear Reverse Sensor (Ex) — 11 X
- 14) Rear Panel — 11 X
- 15) " " Inner garnish — 11 X
- 16) " " Panel Rubber — 11 X
- 17) " " Stricker — 11 X
- 18) Rear Taillamp (Ex) — 11 X
- 19) Rear Taillamp Panel (Fu) — 11 X
- 20) Rear Bumper — 11 X
- 21) " " clip — 11 X
- 22) " " Retainer (Ex) — 11 X
- 23) " " Grille Garnish (Ex) — 11 X
- 24) Rear fender Inner shield clip (Ex) — 11 X

SLF 8435-C Honda Jazz

Labour:-

1) Transfer Booted fitting — 120	60
2) " " plan — 120	✓
3) Check wiring — 100	30
4) Anti Rust proofing — 80	40
5) Rear Panel Joint Sealant — 80	700 SUS. W
6) Interior Upolstery — 100	60
7) Panel Beating — 750	720
8) Paintwork — 950	800

26/12/11 4 day.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability (under warranty) is allowed
- Supplier terms (if any) must be resurveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature:

Date: