

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg1

AIG Asia Pacific Insurance Pte Ltd

Date: 26.12.2017

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

DOA: 21.12.2017

No	Description	Unit	Est (\$)
1	FRONT BONNET	1	\$ <i>bt</i> 1,290.00
2	FRONT BONNET HINGE	2	\$ <i>bt</i> 196.00
3	FRONT BONNET LOCK	1	\$ <i>? Xun</i> 265.94
4	FRONT FENDER RH	1	\$ <i>bt</i> 699.00
5	FRONT FENDER SHIELD RH	1	\$ <i>de</i> 208.00
6	FRONT HEADLAMP LH	1	\$ <i>Xun</i> 2,700.00
7	FRONT HEADLAMP RH	1	\$ <i>Cna</i> 2,700.00
8	FRONT HEADLAMP LOWER BRACKET RH	1	\$ <i>new</i> 110.00
9	FRONT FENDER INNER PANEL RH	1	\$ <i>Rx</i> 800.00
10	FRONT FENDER TOP GARNISH RH	1	\$ <i>de</i> 75.00
11	RH ROOF MOULDING / GARNISH	1	\$ <i>? Xun</i> 728.02
12	FRONT REINFORCEMENT	1	\$ <i>bt</i> 380.00
13	FRONT BUMPER SPONGE	1	\$ <i>Xun</i> 240.00
14	FRONT BUMPER SIDE RETAINER <i>LH-X^{mm} RH-de</i>	2	\$ <i>de</i> 230.00
15	FRONT FOGLAMP GARNISH <i>LH-X^{mm} RH-dis</i>	2	\$ <i>dis</i> 250.00
16	FRONT BUMPER TOW COVER	1	\$ <i>de</i> 65.00
17	FRONT ABSORBER LH	1	\$ <i>Xun</i> 695.00
18	FRONT ABSORBER RH	1	\$ <i>? bt</i> 695.00
19	FRONT ABSORBER MOUNTING RH	1	\$ <i>? Xun</i> 270.00
20	FRONT ABSORBER MOUNTING LH	1	\$ <i>? Xun</i> 270.00
21	FRONT ABSORBER STOPPER RH	1	\$ <i>? Xun</i> 80.00
22	FRONT ABSORBER STOPPER LH	1	\$ <i>? Xun</i> 80.00
23	FRONT ABSORBER DUST COVER LH	2	\$ <i>? Xun</i> 156.00
24	FRONT ABSORBER BALL BEARING	2	\$ <i>? Xun</i> 150.00
25	FRONT LOWER ARM RH	1	\$ <i>? bt</i> 580.00

Parts \$3537.66
GM \$9354.50
Labour \$2290.00
\$19282.00

Total (A):	\$ <i>7353</i>	13,912.96
Less 10%:	\$	1,391.30
Total:	\$ <i>6617.20</i>	12,521.66

115.10
125.10

[illegible]

#01-80 SINGAPORE 159723

Pg2

AlG Asia Pacific Insurance Pte Ltd

Owner's Name : Joey Teo CaiYi

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

DOA: 21.12.2017

No.	Description	Unit	List (\$)
26	FRONT STABILIZER BAR WITH BUSH	2	\$ 8 un 395.00
27	KNUCKLE ARM RH	1	\$? bl ✓ 932.18
28	LINKAGE RH	1	\$? bl ✓ 90.00
29	WHEEL BEARING RH	1	\$ X un 198.20
			\$ 1022.18
		-10%	\$ 919.96
		Total (B) :	\$ 1,615.38
		Less 10% :	\$ 161.54
		Total :	\$ 1,453.84

1800
9354.50

No	Description	Unit	Est (\$)
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 1,200.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 2,000.00
3	Check Wiring System & Light	1	\$ 100.00
4	Anti Rust Treatment	1	\$ 120.00
5	To Check & Adjust Wheel Aligment	1	\$ 100.00
6	To Remove / Refix Front Bonnet Attachment	1	\$ 200.00
7	To Check Water Leaking	1	\$ 120.00
8	To Remove/ Refix Bumper Sensor	1	\$ 120.00
9	To Remove / Refix Front Under Carriage	1	\$ 250.00
10	To Remove / Replace Tyre & Rim	1	\$ 250.00
11	To Remove / Replace Outer Roof Moulding	1	\$ 250.00
Tanphih 97495749 27/12/17 @ 1745 Resurvey before paint 8 days sur @ 1uhand.com.			
KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer Signature: Date:			
Total (D):			\$ 4,710.00
Grand Total:			\$ 28,650.81

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

SUPPLEMENTARY ESTIMATE REPAIR ①

Pg1

AIG Asia Pacific Insurance Pte Ltd

Date: 15.1.2018

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

DOA: 21.12.2017

No	Description	Unit	List (\$)
1	FRONT BEAM	1	\$ Cna 655.40
2	LOWER COVER / GARNISH	1	\$ de 85.00
3	DRIVE SHAFT RH	1	\$ bt 1,940.40
4	HEADLAMP SUPPORT BRACKET RH	1	\$ Cna 35.00
5	FRONT REINFORCEMENT ARM RH	1	\$ bt 168.30
6	SPARE TANK	1	\$ de 180.50
7	UNDER ENGINE COVER (FRONT)	1	\$ de 182.97
8	UNDER ENGINE COVER (CENTRE)	1	\$ de 290.60
Resurvey 17/1/18 P 1140			
LKK Auto Consultants hence notify the Repairer of the following:			
• To resurvey before/after spray painting			
• To display damaged part(s) during resurvey			
• Parts prices are subject to confirmation			
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			
Date:			

Total (A) :	\$	3,538.17
Less 10% :	\$	353.82
Total :	\$	3,184.35

[illegible]

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

SUPPLEMENTARY ESTIMATE REPAIR (2)

Pgl

AIG Asia Pacific Insurance Pte Ltd

Date: 25.1.2018

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Claim Type: Third Party Claim

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Chassis No: WDD1173422N575979

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

DOA: 21.12.2017

[illegible]

\$ 745.20

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

SUPPLEMENTARY ESTIMATE REPAIR (4)

Pgl

AIG Asia Pacific Insurance Pte Ltd

Date: 25.1.2018

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

DOA: 21.12.2017

[illegible]