



SLD4407X

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

odo: 23891

TP INSURER : LONPAC
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 21/12/2017

Vehicle Reg. No. : SLD4407X
Vehicle Reg. Date: 16-Jun-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4036438
Chassis No. : RU11116435

COST OF CLAIMS

Parts Cost / List Items : \$ 19,243.70
Plus/Less 20% \$ 3,848.74
Total Cost / List : \$ 15,394.96
Special Nett Items : \$ 1,375.00
Total Parts Amount : \$ 16,769.96
Total Labour Amount : \$ 5,220.00
Gross Total : \$ 21,989.96
GST % : 7% \$ 1,539.30
Nett Amount : \$ 23,529.26

Surveyor Name and Company :

Tan Jiah 97445749
Date of survey : 22/12/17
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without/Prejudice Without Prejudice
Email : suu@lkkauto.com
Fax No : _____
HP No : _____

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4407X**
 Vehicle Reg. Date: 16/6/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4036438
 Chassis No. : RU11116435

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bt ✓	\$ 1,860.00		
2	1	Tailgate outer garnish	x	\$ 285.00		
3	1 set	Tailgate outer garnish clips	x	\$ 40.00		
4	1	Tailgate logo	new ✓	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	new ✓	\$ 56.20		
6	2	Tailgate lamp LH/RH	x	\$ 980.00		
7	2set	Tailgate lamp clips	x	\$ 50.00		
8	1	Tailgate outer handle switch	x	\$ 180.00		
9	2	Tailgate damper LH/RH	x	\$ 424.00		
10	1	Tailgate wiper motor	x	\$ 250.00		
11	1	Tailgate wiper blade	x	\$ 75.00		
12	1	Tailgate buzzer	x	\$ 150.00		
13	1	Tailgate inner handle	x	\$ 74.00		
14	1	Tailgate inner lock	x	\$ 245.00		
15	1	Tailgate lock sensor	x	\$ 220.00		
16	1	Tailgate striker	x	\$ 32.00		
17	1	Tailgate trimboard	x	\$ 295.00		
18	1 set	Tailgate trimboard clips	x	\$ 45.00		
19	1	Tailgate weatherstrip	auto ✓	\$ 145.00		
20	1 set	Tailgate windscreen moulding	new ✓	\$ 164.00		
21	2	Tail lamp LH/RH	x	\$ 978.00		
22	1set	Tail lamp clips	x	\$ 36.00		
23	1	Rear bumper	de ✓	\$ 950.00		
24	1set	Rear bumper clips	new ✓	\$ 50.00		
25	2	Rear bumper retainer LH/RH	L	\$ 144.00		
26	2	Rear bumper bracket LH/RH	x	\$ 116.00		
27	2	Rear bumper reflector LH/RH	x	\$ 334.00		
28	2	Rear bumper cover LH/RH	x	\$ 420.00		
29	1set	Rear bumper cover clips	x	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	x	\$ 84.00		
31	1	Rear end panel outer	Ry	\$ 585.00		
32	1	Rear end panel inner	x	\$ 396.00		
33	1	Rear end panel top garnish	x	\$ 184.00		
34	1set	Rear end panel top garnish clips	x	\$ 25.00		
35	1	Spare tyre panel	x	\$ 1,230.00		
36	1	Spare tyre panel insulator	x	\$ 240.00		
37	1	Spare tyre panel top board	x	\$ 420.00		
38	1	Spare tyre tool tray	x	\$ 430.00		
39	1	EDLC module	x	\$ 1,750.00		
40	2	Rear fender panel LH	x	\$ 1,900.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4407X**
Vehicle Reg. Date: **16/6/2016**
Make / Model : **H. VEZEL 1.5X CVT**
Engine No. : **L15B4036438**
Chassis No. : **RU11116435**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2	Rear fender inner trim LH/RH	X	\$ 480.00		
42	2	Tail lamp panel LH/RH	X	\$ 550.00		
43	2	Rear fender arch garnish LH/RH	X	\$ 330.00		
44	2set	Rear fender arch garnish clips	X	\$ 60.00		
45	2	Rear fender inner water shield LH/RH	X	\$ 320.00		
46	2set	Rear fender inner water shield clips	X	\$ 60.00		
47	2	Rear fender Air duct LH/RH	X	\$ 150.00		
48	1	Exhaust muffler	X	\$ 855.00		
49	1	Exhaust muffler mounting	X	\$ 79.50		
50	1	Exhaust muffler heat shield	X	\$ 165.00		
51	2	Rear plate lamp LH/RH	X	\$ 250.00		
52	1	Rear number plate with frame	X		\$ 45.00	
53	1	Tailgate windscreen sealant	all /		\$ 80.00	
54	1	Tailgate windscreen inner seal	all /		\$ 80.00	
55	1	Rear end panel sealant	X		\$ 80.00	
56	1	Reverse sensor	* ?	200	\$ 300.00	
57	1	Spare tyre panel sealant	X		\$ 80.00	
58	1	Spare tyre panel padding	X		\$ 100.00	
59	1	Sundries	/	20	\$ 60.00	
60	1	Reverse camera	X		\$ 550.00	
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]