| | VAIDVIMVIO 16860 v City nepines. | Bill to: | Date/Time: Insured: Tel: 678 | 10300 |
|---------------------------------|--|---|---|---|
| PRES, OD RESTE No: SUM Ca | v city . | CS | 110 | 10300 |
| | | | | |
| | 15061700 | Claim No: _ Excess: | SNM1700 1250. | 7206 C01 |
| | | | D.O.A. | 20/17/17 |
| EP. / REV 24 HRS | Person Contacted | k | | LOUT |
| | n 16860 | CU3/CTI (707 | | 0017-20/12/17 |
| 13m veneral | 700 mbo/a | ned CIA | at \$8364.0 | of via merimen |
| out latin | and have H | In CIA DE | X; \$ 1250 h | 4 enil. |
| 1 | Action/Instruction (SHB S387X SH IM VENEYA 23M SUSAN ONLY INFORM 3-21M CONFUN | Action/Instruction () Estima SHB S387X SLM 16860 Ign vever to born Se 23m Susan Teo informed Mr + 3.71m confirmed with | Person Contacted: Person Contacted: Action/Instruction () Estimate Sty Sign 16860 CU3 CT1 (70) Ign vever to boon Sen Us Mer 23pm Susan Teo informed Char 10mm Informed Mr Ho GA Ste 3-71m confirmed with live Ho Fire | D.O.A. REP. / REV 24 HRS Person Contacted: Person Contacted: Vehicle IN Action/Instruction () Estimate CC3 CT1 (707477) Syb3 Lyn Verent to Boon Sen Us Newmen. 23m Susan Teo informed CA at \$8264.0 10mm informed My Ho GA Sex: \$1250 b 3-71m confirmed with lim to final fig \$5235 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Se. | | | ationale Des Experts En Autom | | | | |
|--------------|------------------|---|-------------------------------|--|--|--|--|
| CHIN | NA TAIPING INSUR | ANCE (S) PTE LTD | Ref : CS/CTI1702436 | 3/Uqb | | | |
| | | | | | | | |
| AN | ISON ROAD #16-0 | 0 SINGAPORE 079909 | Date: 26-12-2017 | | | | |
| SPK | INGLEAF TOWER | SINOAI ONE O' OOG | Code: CTI | 6 (11)1111111111111111111111111111111111 | | | |
| 1. | | Policy Parti | culars :- OWN DAMAGE | | | | |
| •• | Insured Veh. | | Veh. Inspected | SLM 1686D | | | |
| | Policy No. | DMPCSN3035061700 | Coverage (\$) | 0.00 | | | |
| | Claim No. | SNM17D07226C01 | Excess (\$) | 1,250.00 | | | |
| | Assign From | | Assign Date | 22/12/2017 | | | |
| 2. | | Vehicle P | articulars & Condition | | | | |
| Make & Model | | | c.c | 0 | | | |
| | Engine No. | HIDDEN | Year of Reg. | | | | |
| | Chassis No. | | Colour | | | | |
| | Odometer | 14 | Steering | | | | |
| | Brakes | | Modification | | | | |
| | General | | | | | | |
| 3. | | Cor | nditions of Tyres | | | | |
| | | Size | Make | Balance | | | |
| | R/H Front Tyre | | | mm | | | |
| | L/H Front Tyre | | | mm | | | |
| | R/H Rear Tyre | | | mm | | | |
| | L/H Rear Tyre | | | mm | | | |
| 4. | | Desc | ription of Damages | | | | |
| 5. | | Ge | neral Information | | | | |
| 5. | Accident Date | 20/12/2017 | Inspection Date | 26/12/2017 | | | |
| | Survey held at | CAR CITY AUTO CENTRE | | | | | |
| | Survey note at | BLK 9006 TAMPINES ST 9 #01-198 SINGAPORE 528840 | | | | | |
| 5a. | | | Remarks | | | | |
| and the last | ANTHE MARKET | ALUE IS S\$(EST. | AVERAGE) | DEDAIRS | | | |
| 1 | B)IN ACCORDAN | CE TO YOUR INSTRUCTION | NS, WE HAVE AUTHORISED | KEPAIKS. | | | |

...CLAIM SUBFOLDER...(New Assignment)

| Case Notified Est Submitted Adj Assigned Adj Rpt Adj Submitted Ins Auth'ed S | |
|--|--|
| 22 Dec 2017 | And the first words to be a fine or a series where |
| 22 0 0 2017 22 DEC 2017 | New Assignment |
| 22 Dec 2017 22 Dec 2017 14:31 15:50 Assign | Cancel Case |

| Main | Reference | Claim Details | Docum | ents | Show All |
|--|---|--------------------------|----------------|----------------|---------------------------|
| CLAIM SUBFOLDER DE | SEE KIM SIONG PETER, ID: S | Tel: +65911 | 50668 Email: 5 | SEE.PETER@G | MAIL.COM |
| Insured: | SEE KIM SIONG PETER, ID: S. | 7/06539C, Tel. +65911 | 20/1 | 2/2017 18:0 | 0 - :59 |
| Vehicle Reg. No.: | SLM1686D | Date of Loss: | | CSN3035061 | |
| a turbinat was tweet | OD / SNM17D07226C01 | Policy/Cover Note N | | nprehensive) | |
| Claim Type: | Car City Auto Centre Pte Ltd (| Excess: | S\$1 | ,250.00 | |
| Repairer: Handling Insurer: | O300 China Taiping Insurance (Sing LKK Auto Consultants Pte Ltd | papore) Pte. Ltd. (HQ) - | Lillar Khe a | 30 0 1/ 0 2/ 2 | oy Chong Boon Ser 018] |
| Driver/Custodian: | SEE KIM SIONG PETER (40 / Male SURVEY REVERT | e), NRIC: S7706539C, | Tel: +65911596 | | |
| Adjuster: Driver/Custodian: Adj Asg. Remarks: ASSOCIATED MAIL RE | SEE KIM SIONG PETER (40 / Male SURVEY REVERT | e), NRIC: S7706539C, | Tel: +65911596 | View All | |
| Driver/Custodian: Adj Asg. Remarks: | SEE KIM SIONG PETER (40 / Male SURVEY REVERT | e), NRIC: S7706539C, | Tel: +65911596 | | Compose Case Mai |



Shiau Chan (LKKAuto)

From:

CAR CITY AUTO CENTRE PTE LTD <ccacpl@singnet.com.sg>

Sent:

Friday, 27 July 2018 3:21 PM

To:

Shiau Chan (LKKAuto)

Subject:

Re: FINALISE OF VEHICLE SLM 1686D (DOA: 20/12/2017)

ok thank you.

Ho

----Original Message----

From: siewsc@lkkauto.com Date: 24/07/2018 - 16:21 GMT+8

To:ccacpl@singnet.com.sg

Subject: FINALISE OF VEHICLE SLM 1686D (DOA: 20/12/2017)

Dear Mr Ho,

WITHOUT PREJUDISE

Offer final fig \$5,235.43 before excess \$1,250.00 & GST and 5 repair days

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 28 December, 2017 2:09 PM

To:

ccacpl@singnet.com.sg

Cc:

SUR

Subject:

VEHICLE SLM 1686D (DOA: 20/12/2017)

Dear Mr Ho,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle SLM 1686D (excess \$1,250/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

| 1 | AUDIT TRAIL | | | By |
|-----|-------------------------------|------------------------------|---|--------------------------------------|
| 10. | | Audit | Remarks | [R] Ho Too |
| 1 | | Clm Veh Model Changed | (204715) TOYOTA HARRIER 2.0 Premium (A). | Boon |
| 2 | 14:26 22 Dec 2017 14:26 | Clm Created | Reg No: SLM1686D. Policy No: DMPCSN3035061700. Acct Date: 2017/12/20. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Car City Auto Centre Pte Ltd (HQ). Created from SAS:MCCA17167768 | [R] Ho Too Boon [R] Ho Too |
| 3 | 22 Dec 2017 | Clm Submitted | 9579.47. | Boon |
| 4 | 14:31 22 Dec 2017 15:50 | Clm Registration Modified | Excess: -> 1250.00. | [I] Chong Boon Sen |
| 5 | 22 Dec 2017 15:50 | Adj Co Assigned | LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT | [I] Chong Boon Sen |
| 6 | 22 Dec 2017 15:50 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/01/04 | [I] Chong Boon Ser |
| 7 | 22 Dec 2017 15:50 | Adj Mandate Set | Approved:0.00. | [I] Chong Boon Ser |
| 8 | 22 Dec 2017 17:46 | Assignment 1st Accessed | | [A] Nivith Govindasar [A] SHIA |
| 9 | 27 Dec 2017 11:36 | | [None] -> MARCUS CHUA | CHAN [A] SHIA |
| 10 | 27 Dec 2017 | Adj Rpt Initiated | | CHAN [A] SHIA |
| 11 | 27 Dec 2017 | Adj Im. Advice Submitted | Next Rpt:Final Rpt.Due Date:2018/01/04 | CHAN |
| 12 | 27 Dec 2017 | | Cur.Req:8264.07:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR. | [A] SHIAI CHAN |
| 13 | 20 Dec 2017 | Adj Next Rpt Changed | 2010/01/01 | [I] Susar Teo |
| 14 | 13:23 28 Dec 2017 | Adj Mandate Set | Approved:8264.07. | [I] Susar Teo |

ACTIVITY

No record

| rimen billin | g for this case - | TT GITT GET CO. | 1 | Co Name | | | A |
|--------------|---------------------|-----------------|---|---|----------|-------|--------|
| Bill Ref No | Bill Date | Acc Type | Acc Name | (Branch) | Ref 1 | Ref 2 | Amount |
| 1676103 | 22/12/2017 14:26 | Motor | Car City Auto Centre Pte Ltd (HQ) | Car City Auto Centre Pte Ltd (HQ) | SLM1686D | | хх.хх |
| 1678933 | 27/12/2017 11:40 | Motor | LKK Auto Consultants Pte Ltd | LKK Auto Consultants Pte Ltd (HQ) | SLM1686D | | 10.70 |

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Chong Boon Sen

Date:

27 Dec 2017

Preliminary Advice

Vehicle No

: SLM1686D

Accident Date

: 20/12/2017

Make

: TOYOTA HARRIER

: DMPCSN3035061700

Assignment Date

Policy No.

Date of Inspection : 26/12/2017

: 22/12/2017

Excess

: S\$1,250.00

Est. Duration of Repair

: 5.00

Inspection At

: CAR CITY AUTO CENTRE PTE LTD (HQ)

BLK 9006 #01-198, TAMPINES STREET 93

SINGAPORE 528840

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 9,579.47 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 5,618.07 |
| Check Items (Estimated) | :S\$ | 2,646.00 |
| Total | :S\$ | 8,264.07 |

Lump Sum Repair

:S\$

Total Loss Consideration

| :S\$ | |
|------|----------------------|
| :S\$ | 102,000.00 |
| :S\$ | 70,167.00 |
| :S\$ | |
| :S\$ | 31,833.00 |
| | :S\$:S\$:S\$ |

Remarks

| (X | The vehicle is repairable at our adjusted amount. Velet us have your authorisation. | We have also | confirmed | excess | and policy | coverage. | Kindly |
|-----|---|--------------|-----------|--------|------------|-----------|--------|
| | let us have your authorisation. | | | | | | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of onies of this report will for a fee be made available upon application by interested parties.

| Singapore(GIA) for archiving and that copies of this report will for a 7. By the lodgement of this report to the insurers, you hereby consi aforesaid. | a fee be made available upon application by interested parties. ent to the archiving of this report at the centre and to copies of the report being made available |
|--|---|
| | ACCIDENT STATEMENT |
| Date Of Report | 21/12/2017 15:22 |
| Date Of Accident | 20/12/2017 18:00 |
| Exact Location Of Accident | T-JUNCTION PARLIAMENT PLACE / ST ANDREW'S ROAD |
| Country/State of Loss | SINGAPORE |
| D | ETAILS OF OWN VEHICLE |
| Vehicle Registration Number | SLM1686D |
| Insured/Policyholder | |
| Name Of Registered Owner | SEE KIM SIONG PETER |
| NRIC No | S7706539C |
| Email Address | SEE.PETER@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-91159668 |
| Alternative Phone No | OTHERS-91159668 |
| Vehicle Particulars | |
| Manufacturer | TOYOTA |
| Model | HARRIER-2.0 PREMIUM (A) |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| | |

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy

DMPCSN3035061700 Policy Number

Cover Note Number

Driver

SEE KIM SIONG PETER Name of Driver

NRIC No S7706539C Date Of Birth 16/03/1977 INDOOR Occupation Date Of Driving Pass 31/12/1997

19 YEARS AND 11 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-91159668 Mobile Number

Fax Number

Contact Number OTHERS-91159668

EMail Address SEE.PETER@GMAIL.COM Address

205 JALAN EUNOS #10-04

Postcode

419535

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle

Vehicle Registration Number of Driver's Own

OWNER SJH4722M

Insurance Company of Driver's Own Vehicle

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

NO

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

SERANGOON NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 50 SERANGOON AVE 2 #01-02, POSTCODE: 556129, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4880999 - FAX NO: 64883561

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER ATTACHED SKETCH PLAN AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB5387X

Vehicle Make/Model/Colour

SMRT TAXI (PURPLE CHEVROLET EPICA LT)

Details Of Properties

Vehicle Category

Name of Driver

TAN CHIN LEONG

NRIC/Passport Number

S7434222A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 23

Name SEE KIM SIONG, PETER Approximate Age Injuries Sustain Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance? Address Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any faise reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

21/12/2017

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| AS PER | POLICE REPORT T/20171220/2158 |
|---------|-------------------------------|
| 110 181 | 172017122072130 |
| | |
| | |
| | |
| 711 | |
| | |
| | |
| | |
| | |
| 100 | |
| | |
| | |
| | |
| | |
| 727 | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

DECLARATION

Date & Time:

I/We declare the foregoing particulars are true in every respect.

21/12/2017

Policyholder's Signature 11: SS AM

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No .:





T/20171220/2158

1 of 3

Report No. T/20171220/2158

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

Tel No: 1800-4880999

REPORT OF A TRAFFIC ACCIDENT

| Date/Time Report Made: 20/12/2017 20:46 | | | Vide Report No.: | Station Diary No.: 85 | |
|---|--------------|-------|---|----------------------------|--|
| Informa | nt's Partice | ulars | | | |
| Name of Informant: SEE KIM SIONG PETER | | | Address: 205 JALAN EUNOS #10-04 SINGAPORE 419535 | | |
| ID Type / ID No.: NRIC NO / \$7706539C | | | Contact No.: Home/Office: | Mobile: 91159668 | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Age: Date of Birth: Male 40 16/03/1977 | | | Type of Informant: Driver | | |
| Race: Chinese | | | Language: English | Institution / School Name: | |
| Occupation: EXECUTIVE DIRECTOR | | | Driving Licence Information: Class: Date of Expiry: | | |

| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 20/12/2017 18:00 | Type of Location | |
|---|--------------------------------------|------------------------------------|---|---|--|
| Location: Junction of Re PARLIAMENT SAINT ANDR | 76. HOGG TO BE TO THE TO THE TO SHOW | 6) | ⊗ | an and an | |
| Weather: Clear | | Road Surface: Dry | R | oad Speed Limit: | |
| Traffic Flow: Traffi | | Traffic Control: Not Controlled | 3% | Traffic Volume: Moderate | |
| Type of Collis Between Mov | ion: ring Vehicles - Head | To Rear | а | nyone conveyed by mbulance: | |

| Details of V | Details of Vehicle Involved | | | | | | |
|-------------------------------|-----------------------------|--------|-----------------------------|-------|---------------------|-----------------|--|
| Vehicle No. | Туре | Make | Model | Color | Condition | No of Passenger | |
| SHB5387X (Not Accurate) | Car | | | | Slightly Damaged | 1 | |
| SLM1686D (Not Accurate) | Car | ТОУОТА | HARRIER PREMIUM 2.0 A | Black | Slightly Damaged | 0 | |

| Details of V | ehicle Insurance | 为不是有关的关系,但是是 | | |
|--------------|-------------------|---------------------|-----------|-------------|
| Vehicle No. | Insurance Company | Insurance No | Effective | Expiry Date |





T/20171220/2158

2 of 3

Report No. T/20171220/2158

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

Tel No: 1800-4880999

CONTINUATION OF REPORT

| Name and Address of the State o | ehicle Insurance | | | |
|--|--|----------------------|------------|-------------|
| Vehicle No. | Insurance Company | Insurance No | Effective | Expiry Date |
| SLM1686D (Not Accurate) | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. | DMPCSN30350617 00 | 21/04/2017 | 29/06/2018 |

Brief Details.

On 20/12/2017 at about 1800hrs, I was driving my car, SLM 1686D, along Parliament Place. Everything was normal. I was behind a Taxi, SHB5387X. When I was about to enter St's Andrew Road, the Taxi in front suddenly jammed brake. I immediately jammed brake as well however it was too late. I hit onto the rear of the Taxi. We came down and take a look at the damage. my front car was dented and the Taxi rear bumper was dented as well. Both the Taxi driver and I exchange particular and there were a passenger in his car and the passenger said she was alright.

After which we went off. However a few hours later I felt some discomfort at my back thus I went to the doctor and took 3 days of MC. I'm lodging this report for insurance claim





T/20171220/2158

3 of 3

Report No. T/20171220/2158

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129 CONTINUATION OF REPORT

Tel No: 1800-4880999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now please fax a copy to 65474885 stating the report number as reference.

| Signature Of Officer Recording The Report: F / Sgt 2 TEO JING XIAN | Signature Of Informant: |
|---|-----------------------------|
| Signature Of Interpreter: Not applicable | Date/Time: 20/12/2017 20:46 |
| Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BINTE BOHARI | Classification Of Case: |
| Contact No.: 65476219 Authentication Stamp NP168 | * |

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

| Th | nis is to co | onfirm th | hat | See | 1/am | Stong | Peter | | | |
|-----------|--------------|-----------|--------|-----------|-----------|-----------|-----------------------|----------|---------------|----|
| NRIC/FIN | V_S170 | 65391 | , ha | s report | ed to the | Police | a non-ir | njury tr | affic acciden | t |
| which occ | urred at | Near | Pc | r/Yame | nt pl | nce | towa | rols | San | 6 |
| Andrew | 15 Page | ol. | | | - | | | | | |
| on _20\0 | 1117 | _ at | 6 | | am/pm | involvi | ng the fo | llowin | g vehicles: | |
| | * | | - | SLM | 16866 | 2 | | | | |
| | | | _ | SHB | 538= | 7× | | | | |
| | Then he | /she has | comp | lied with | n Sec 84 | (2) of ti | he Road | Traffic | Act, Cap 27 | 6. |
| | Rank/Na | ame of I | ssuing | Officer | :So | +2 | Teo I | ing Xi | an | |
| | Date: _ | 20/12/1 | 7_ | | Time | e:_191 | 49hvs | 11 | | |
| | S/D Ref | 76 | | | | Serange | oon NPC | 24 | A | |
| | Police P | ost/Unit | : | Seran | 200n | No: 50 | Serangoo Singapore | 556/29 | | |
| | 29 | | | | | 1ei: 18 | 00 488 09 | 99 / / | | |

Original – to be issued to informant Duplicate – to be submitted to Traffic Police

CONFIDENTIAL

Version as of 15 Jan 2002

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-----------------------------------|--|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 6539C |
| Vehicle Details | |
| Vehicle No.: | SLM1686D |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 26 Dec 2017 |
| Vehicle Make: | ТОУОТА |
| Vehicle Model: | HARRIER PREMIUM 2.0 A |
| Primary Colour: | Black |
| Manufacturing Year: | 2015 |
| Engine No.: | 3ZRB563107 |
| Chassis No.: | ZSU600045582 |
| Maximum Power Output: | 111.0 kW (148 bhp) |
| Open Market Value: | \$28,548.00 |
| Original Registration Date: | 30 Jun 2015 |
| First Registration Date: | 30 Jun 2015 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$21,968.00 10984 |
| Intended PARF Rebate Deta | ails |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Jun 2025 |
| PARF Rebate Amount: | \$16,476.00 |
| Intended COE Rebate Deta | ils |
| COE Expiry Date: | 29 Jun 2025 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$71,509.00 |
| COE Rebate Amount: | \$53,691.00 |
| Total Rebate Amount: | \$70,167.00 |

Enquire PARF/COE Rebate for Registered Vehicle

| | Cianana KIDIC |
|-------------------------------|---------------------------------------|
| wner ID Type: | Singapore NRIC |
| wner ID: | 6539C |
| ehicle Details | |
| ehicle No.: | SLM1686D |
| ehicle to be Exported: | Yes |
| ntended De-registration Date: | 30 Dec 2017 |
| ehicle Make: | TOYOTA |
| ehicle Model: | HARRIER PREMIUM 2.0 A |
| rimary Colour: | Black |
| 1anufacturing Year: | 2015 |
| ngine No.: | 3ZRB563107 |
| hassis No.: | ZSU600045582 |
| Maximum Power Output: | 111.0 kW (148 bhp) |
| pen Market Value: | \$28,548.00 |
| Original Registration Date: | 30 Jun 2015 |
| irst Registration Date: | 30 Jun 2015 |
| ransfer Count: | 1 |
| Actual ARF Paid: | \$21,968.00 |
| ntended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Jun 2025 |
| PARF Rebate Amount: | \$16,476.00 |
| ntended COE Rebate Details | |
| COE Expiry Date: | 29 Jun 2025 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |

THE UNLY PLACE FOR SMART CAR BOYERS

Car Make or Model

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

2011 Mercedes-Benz C180K Avantgarde.

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS



Post an Ad

DIRECT BUYERS & SELLER 100% FREE SETTLEMENT ON LOANS, INSURANCE & PAPERWORK

CONNECT



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login

Make

Ways of Selling



Very Low Mileage, Perfect Condition, Careful Lady Owner, Fully Inspected By C&C Direct Owner StarAd



V Browse by Category

Toyota Harrier

Model

Price Arry Depreciation

Red Date

Eng Cap

Mileage

Sort by Date Posted

Advanced Search

Veh Type

Submit (

Status

Available

✓ 20 results/page

Search Selection

11 vehicles

Toyota Harrier

\$115,000

\$12,960 /vr

04-Dec-2015

1.986 cc

25,274 km SUV

Available CORECT CHIEF

Alpine Entertainment System/Navigation. Front And Rear Recording Camera. Low Mileage.

Posted: 23-Dec-2017

Toyota Harrier 2.0A Elegance

\$103,800

\$13,050 /vr

05-Mar-2015

1,986 cc

SUV

Available

Details

Toyota Harrier 2.0A Elegance

Details

Classic Black | Only \$10,380 Down Payment. Up To 90% Flexible Loan Look No Further! We Provide Lowest Interest Rate In Town. Flexible Loan And High Trade In Are Available, Package With Unrivaled Warra...

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier,

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier,

Classic Credit Pte Ltd

Posted: 21-Dec-2017

Toyota Harrier 2.0A Elegance Easy Approval With Our Bank/ Flexible In House Financing Options! 20% Down Payment Available! Almost New Beautiful Pearl White Elegance Harrier

\$106,998

\$12,960 /vr

25-Jun-2015

1,986 cc

13.007 km

SHV

Available

With Built In Touch Panel OEM Multimedia Player Enable D... Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota Used Toyota

Posted: 20-Dec-2017



Toyota Harrier 2.0A Elegance

\$112,800

\$12,890 /vr

19-Oct-2015

1,986 cc

7,800 km

Available

Details

Elegant Silver SUV, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 16-Dec-2017

Car Aftermarket

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier,

Details

Car Buying Car Ownership Car Selling On The Move

Lifestyle

Bidded Carplates

Toyota Harrier 2.0A Elegance

\$117,500

12-Jun-2015

1,986 cc

63,618 km

SUV

10% Down Payment. 90% Loan Available. 3rd Generation Harrier With Improved Engine Function And Fuel Efficiency. Elegantly Designed With

Improvements Especially In Curves, Wide Lower Grille Which Is He...

Tags. 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier,

Popular Harrier SUV Equipped With 2L Engine. Spac Ious Cabin For 5 Adults To Lounge In Comfort, With Flat Rear Floor And Rear Aircon. Panoramic



Postert: 15-Dec-2017

Panoramic

512,940 /vr

15-Dec-2015

1,986 cc

26,000 km

Available

(OFFICE COMME)

Details

Available

OF THE OWNER OF THE OWNER, THE OW

Details

Roof To Give You Sense Of Spaciousness In The Cabin. Lar... Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier,

Posted: 09-Dec-2017

Toyota Harrier 2.0A Premium

Used Toyota



CAR CITY AUTO CENTRE PTE LTD **BLK 9006 TAMPINES** STREE 93

#01-198 SINGAPORE 528840

Claim Reference: CCA00329 Assessment Number: CCA00329

Version: CAR CITY/1

Date Calculated: 22/12/2017 03:22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary tem Full Report nd V1

Registration: SLM1686D Printed: 22/12/2017 11:22

Signature:

Date:

Summary Information

Claim

Location: Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) HO TOO BOON

Interim

China Taiping Insurance

(S) Pt CCA00329

DMPCSN3035061700

OD/18034

Currency:

Date of Incident:

Able to Authorise Repairs: TBA Repairs Authorised:

Estimated Repair Time: Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected: SGD

20/12/2017

TBA

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model:

Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Manufacture Year: Odometer:

Colour:

Engine Number: Fuel Level:

LEXUS

RX Series BASE MODEL 2426 01

SLM1686D

June 2015

ZSU600045582

2015 26461 Black

3ZRB563107

0%

Model Specs

FROM 07/2015 WINDSCREEN HEATED AUTO DIP D/MIRROR BLIND SPOT MIRROR

9-SPEAKER

ADAPTIVE HEADLAMPS

RAIN SENSOR

SEATS WITH MEMORY ST/WHEEL SWITCH CONT

HEAD-UP DISPLAY FRT/RR PARK DIST CON AUTO GEARBOX E-CVT TYRES 235/60 HR 18

DRIVE DYNAM SYS VDIM ACTIVE STABI CONTROL

ROOF RAILS PRODUCTION IN JAPAN

TWO COAT PEARL/MICA

WINDOWS DARKENED AUTO DIPPING MIRROR CHEQUE CARD ELECTRIC TAILGATE

XENON HEADLAMPS HEADLAMP WASHERS FRT CUSHION ELEC ADJ 2COMP GLASS ADHESIVE AUX-AUDIO CONNECTION

REARVIEW CAMERA 2.7 LTR 138KW PRE-CRASH SYSTEM WHEELS 7.5J X 18 ALU

FRONT DRIVE

PANORAMA SUNROOF SPORT BUMPER

PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Satisfactory

Fair

Fair

Place of Inspection: Pre-Accident Damage:

Brakes Pedal Travel:

Tyres Condition:

Satisfactory Repairer

Severity of Impact: Vehicle Status on

Inspection: Date of Inspection: Heavy Panel Roadworthy

21/12/2017

Claim Reference: CCA00329

Full Report - V1 Registration: SLM1686D


Assessment Number: CCA00329

Version: CAR CITY/1

Printed: 22/12/2017 11:22

Date Calculated: 22/12/2017 03:22

Tyres - Tread Depth (MM):



Addresses

Cost Summary

| Summ | ary | | | _ |
|------|---------------------------|----------------------|-------------|---|
| | Total Labour | | \$1,232.80 | |
| | Total Paint/Material | | \$211.67 | |
| | Total Parts | | \$7,933.00 | |
| | Total of Additional Costs | | \$202.00 | |
| | Repair Cost Exc GST: | | \$9,579.47 | |
| | Overall Discount (0.0%): | | - \$0.00 | |
| | Excess: | | -\$1,750.00 | |
| | After Deduction - | Grand Total Exc GST: | \$7,829.47 | |
| | THE DOGGETON | 7 % GST: | \$548.06 | |
| | | Grand Total Inc GST: | \$8,377.53 | |
| | | | | |

Repair Information

| LABOUR | Time Basis 10 WU = 1 | | 1 = \$46.00/HR ent = \$0.00/HR |
|-------------------|--|---------|-----------------------------------|
| Repair / | | 1000100 | |
| Guide Numb | er Repair Details | wu | Cost Price (\$) |
| B020 | RENEW FRONT BUMPER | 15.0 | 69.00 |
| | INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS | | |
| 750011) | R + R RADIATOR BADGE | 1.0 | 4.60 |
| 750011) | RENEW FRONT BUMPER REINFORCEMENT | 1.0 | 4.60 |
| B020) | | 5.0 | 23.00 |
| B040 | R + R BOTH HEADLAMPS | | 36.80 |
| B040 | R + R HEADLAMPS (BUMPER REMOVED) | 8.0 | 30.80 |
| | INCLUDES: ADJUST HEADLAMPS | | |
| B100 | R + R RIGHT FRONT WING | 5.0 | 23.00 |
| 0100 | (FRONT BUMPER, RIGHT HEADLAMP ASSY AND | | |
| | R/SILL MOULDING REMOVED) | | |
| | INCLUDES: WHEELHOUSE LINER R + R. | | |
| D141\ | R + R/RENEW FRONT UPPER END PANEL | 33.0 | 151.80 |
| B141) | | 4.0 | 18.40 |
| B125 | R + R RADIATOR PROTECTIVE PANEL | 12.0 | 55.20 |
| NO NUMBER | RENEW L/F SIDEMEMBER REINFORCEMENT FRT | | 55.20 |
| NO NUMBER | RENEW R/F SIDEMEMBER REINFORCEMENT FRT | 12.0 | 35.20 |

Claim Reference: CCA00329

Full Report - V1

Assessment Number: CCA00329

Registration: SLM1686D Printed: 22/12/2017 11:22

Version: CAR CITY/1

Date Calculated: 22/12/2017 03:22

| B110 RENEW L/FRT WING | 7.0 | 32.20 X |
|---|------------------|--------------|
| B110 RENEW L/FRT WING (FRONT BUMPER, LEFT HEADLAMP ASSY AND | | 112101211000 |
| L/SILL MOULDING REMOVED) | | |
| INCLUDES: WHEELHOUSE LINER AND REQUIRED | | |
| ATTACHED PARTS R + R. | | |
| B070 RENEW BONNET * | 6.0 | 27.60 |
| INCLUDES: R + R OR RENEW ATTACHED PARTS | | |
| B080 R + R L/BONNET HINGE | 1.0 | 4.60 |
| B080 R + R BONNET HINGE | 1.0 | 4.60 |
| NO NUMBER R + R LOCK CARRIER | 2.0 | 9.20 |
| B100 R + R L/DOOR SILL MOULDING | 3.0 | 13.80 |
| B100 R + R R/DOOR SILL MOULDING | 3.0 | 13.80 |
| NO NUMBER ADD/WORK FOR PARKING AID SENSOR | 2.0 | 9.20 |
| DRILLING | | |
| 002889 REFILL AIR CONDITIONING | 7.0 | 32.20 |
| M010) R + R AIR CONDITIONING CONDENSER | 2.0 | 9.20 |
| M020) R + R COOLING ASSEMBLY | 5.0 | 23.00 |
| NN BONNET CHROME R&R / NEW PARTS | 11 2.0* 4 | 9.20 乂 |
| 0742 REPAIR R/F WING | 18.0* /0 | 82.80 |
| 0302 CHECK R/FOG LAMP CARRIER | | |
| 0637 CHECK L/F FOG LAMP CPL | | |
| 0638 CHECK R/F FOG LAMP CPL | | |
| 0842 CHECK R/F WHEELHOUSE COVER | | |
| 9645 CHECK LOW TONE HORN | | |
| 9646 CHECK HIGH TONE HORN | | |
| LABOUR COST | 155.0 | |
| Total Work Units | 155.0 | 0.00 |
| Corrosion Protection External Labour | 0.0HRS 0.0HRS | 0.00 |
| Corrosion Protection Internal Labour | 15.5HRS | \$713.00 |
| Sub Total | 11.3HRS | \$519.80 |
| Paint Labour | 26.8HRS | \$1,232.80 |
| Total Labour | 20.0113 | \$1,232.00 |

| PAINT WORK | 1 | ime Basis 10 WU = 1 HR. Price | = \$46.00/HR |
|-------------|---------------------------------|-------------------------------|-----------------|
| Guide Numbe | r Description | WU | Cost Price (\$) |
| | - PAINTING OFF VEHICLE | | |
| | - TWO COAT PEARL/MICA | | |
| 340 | FRT BUMPER REINF SURFACE PAINT | 4.0 | |
| 471 | BONNET NEW PART PAINTING | 23.0 | |
| 741 | L/F WING NEW PART PAINTING | 11.0 | |
| 988 | LOCK CARRIER STRUT SURFACE PAIN | T 4.0 | |
| 1017 | LOCK CARRIER BRKT SURFACE PAINT | | |
| 1019 | L/F PANEL SURFACE PAINT | 4.0 | |
| 1020 | R/F PANEL SURFACE PAINT | 4.0 | |
| 1183 | L/RADIATOR BRACKET SURFACE PAIN | T 4.0 | |
| 1184 | R/RADIATOR BRACKET SURFACE PAIN | | |
| 277 | L/F BUMPER COVER NEW PART PAINT | | |
| 278 | R/F BUMPER COVER NEW PART PAINT | | |
| 283 | FRONT BUMPER NEW PART PAINT K1 | | |
| 742 | R/F WING REPAIR PAINTING >50% | 18.0 | |
| | BOUR COST - PAINT | | |
| | TIME(PAINT) | 97.0 | |

Claim Reference: CCA00329 Full Report - V1
Assessment Number: CCA00329 Registration: SLM1686D

Version: CAR CITY/1 Printed: 22/12/2017 11:22

Date Calculated: 22/12/2017 03:22

| Preparation Main Work Metal | 11.0 | |
|------------------------------------|---------|------------|
| Preparation Comp. Work Plastic | 5.0 | |
| Preparation Work Multi Layer Paint | 0.0 | |
| Total Work Units (10WU/HR) | 113.0 | |
| Total Paintwork Labour | 11.3HRS | \$519.80 |
| MATERIAL COST - PAINT | | Cost Price |
| New Part Painting | | \$99.07 |
| New Part Painting - Plastic K1R | | \$49.19 |
| Surface-/Blend Paint | | \$16.95 |
| Repair Painting | | \$19.36 |
| Material-Const Main Work Metal | | \$18.10 |
| Material-Const Comp. Work Plastic | | \$9.00 |
| Total Excluding Pearlescent Uplift | | \$211.67 |
| Pearlescent Uplift @ 0.0% | | \$0.00 |
| Total Paint Material Cost | | \$211.67 |

| | | Total Paint Material Cost | | | \$211.67 |
|------------|--------|---------------------------|------------------|--------|----------------------------|
| PARTS | | | | | Price Valid: 01/06/2015 |
| Guide N | lo Otv | Description | Part Number Su | pplier | Bet. Price (\$) |
| 277 | 10.Qty | L/F BUMPER COVER | 52128 48913 | PP | -0% Sel 32.00* |
| 277 278 | 1 | R/F BUMPER COVER | 52127 48916 | | 10% KJ 32.00* |
| 283 | 1 | FRONT BUMPER | 52119 4D927 | | - 0% 5.5 620.00* _ |
| 301 | 1 | L/FOG LAMP CARRIER | 52126 48060 | | 0% 17 28.00*× |
| 321 | 1 | L/INN BUMPER BRACKET | 52536 48020 | | -0% 31 110.00*- |
| 322 | 1 | R/INN BUMPER BRACKET | 52535 48030 | | 0% 47 110.00* ₺ |
| 327 | 1 | L/BUMP IMPACT DAMPER | 52612 48020 | | - 0% By 35.00*_ |
| 328 | 1 | R/BUMP IMPACT DAMPER | 52613 48020 | | 10% Ky 35.00* |
| 340 | 1 | FRT BUMPER REINF | 52131 48111 | | 10% 51 165.00* - |
| 344 | 1 | FRT IMPACT ABSORBER | 52611 48150 | | 0% 79. 7 65.00* |
| 350 | 1 | FRT BUMPER CLAMP KIT | USE SINGLE PARTS | | 0% 17 12.00* X |
| 381 | 1 | FRT BUMPER GRILLE | 53113 48040 | | - 0% Tora 180.00* - |
| 391 | 1 | FRT LWR BUMP GRILLE | 53112 48120 | | -0% Cm 155.00* |
| 401 | 1 | FRT LWR BUMPER COVER | 52411 48010 | | - 0% 73.4 160.00* |
| 410 | 1 | GRILLE | 53101 48581 | | -0% SNO 280.00* |
| 471 | 1 | BONNET | 53301 48140 | | -0% →> 680.00* |
| 475 | 1 | L/F HINGE | 53420 48090 | | 0% A 48.00*X |
| 476 | 1 | R/F HINGE | 53410 48090 | | 0% |
| 481 | 1 | BONNET INSULATION | 53341 48080 | | 0% 47 75.00*X |
| 493 | î | BONNET LOCK | 53510 48201 | | -0% TNI 80.00* - |
| 531 | 1 | LEFT BONNET STOP | 90541 15037 | | 0% 11 16.00* |
| 532 | 1 | RIGHT BONNET STOP | 90541 15037 | | 0% 11 - 16.00* |
| 561 | 1 | LEFT HEADLAMP ASSY | 81185 48B50 | | - 0% cre 1,050.00* 5 |
| 562 | 1 | RIGHT HEADLAMP ASSY | 81145 48B50 | | 0% 11,050.00* |
| 741 | 1 | L/F WING | 53812 48130 🕊 | | ×0% 12 - 420.00* - |
| 789 | 4 | L/F WING CLAMP KIT | 91635 G0616 | | 0% 1-1 18.00* X |
| 841 | 1 | L/F WHEELHOUSE COVER | 53806 48110 | | 0% 47 230.00* 0 |
| 988 | 1 | LOCK CARRIER STRUT | 53208 48060 | | - 0% Rd 105.00* |
| 1007 | 1 | L/RADIATOR AIR GUIDE | 53294 48110 | | 0% 1 60.00* 0% 1 60.00* |
| 1008 | ī | R/RADIATOR AIR GUIDE | 53293 48110 | | 0% 17 60.00* |
| 1016 | 1 | UPPER AIR GUIDE | 53295 48042 | | 00% 80 00* |
| 1017 | 1 | LOCK CARRIER BRKT | 53216 48070 | | 0% 180.00* |
| 1017 | 1 | L/F PANEL | 53203 48080 | | 0% / 95.00 / |
| 1020 | 1 | R/F PANEL | 53202 48070 | | 0% 7 95.00* |
| 1223 | 1 | L/F SIDE MEMBER END | 57114 48021 | | 0% A 85.00* C |
| 1223 | 1 | LI SIDE MEMBER LIND | 5/114 40021 | | 0.0 10 1 |

Claim Reference: CCA00329

Full Report - V1
Registration: SLM1686D

Assessment Number: CCA00329

Registration: SLM1686D

Version: CAR CITY/1

Printed: 22/12/2017 11:22

Date Calculated: 22/12/2017 03:22

| 1224 | | R/F SIDE MEMBER END | 57113 48021 | | 0% | 1 85.00 × X |
|-----------|-------|----------------------|-------------|----------|---------|-------------------------|
| 1224 | 1 | KIT SIDE MEMBER END | | | | |
| 4465 | 1 | CONDENSER | 88460 48280 | | 0% | 520.00 /. |
| 8781 | 1 | FRT ENG COMP PROTECT | 51441 48071 | | 0% | 11 65.00*X |
| 1000 | 1 | BONNET CHROME | Renew | | - 0% | 5 61(160.00* |
| 1000 | 1 | BUMPER RETAINER RH | Renew | 4064 | _0% | Ley 60.00* |
| 1000 | 1 | BUMPER RETAINER LH | Renew | 104/ | - 0% | Kel 60.00* |
| f: OEM F | Parts | | Sub Total | | | \$7,460.00 |
| g: Origin | | | Mark Up F | rom Cost | (5%) | \$373.00 |
| h: Secor | | 4 | Sundry Pa | | (Fixed) | \$100.00 |
| p: Parall | | | Total Par | | | \$7,933.00 |
| x: Excha | ange | | | | | S (70.00 S 1992 S 20.00 |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

| Description | | Betterment | | Price |
|---------------|------------|--------------|----|------------|
| AUDATEXS FEES | SPECIALIST | 0% | | \$42.00 |
| NUM PLATE & | SPECIALIST | | ku | \$50.00 40 |
| HOLDER | | | | * |
| ANTI-FREEZE | SPECIALIST | 0% | 11 | \$60.00 |
| AIR CON GAS | SPECIALIST | | 17 | \$50.00 |
| | | Total Extras | | \$202.00 |

Final Calculation

| Final Calculation | | |
|--|-------------|-------------|
| Total Parts | | \$7,933.00 |
| Labour | | |
| Total Panel/Mechanical | \$713.00 | |
| Total Paintwork | \$519.80 | |
| Total Labour | | \$1,232.80 |
| Additional Costs | | |
| Corr Prot Materials External | \$0.00 | |
| Corr Prot Materials Internal | \$0.00 | |
| Cost of Specialist | \$202.00 | |
| Total of Additional Costs | | \$202.00 |
| Total Paint/Material Costs | | \$211.67 |
| Repair Costs Excludes GST | | \$9,579.47 |
| Deductions | | |
| Deduction for Excess (Fixed) | -\$1,750.00 | |
| Total Deductions | | -\$1,750.00 |
| Grand Total Excludes GST (After Deduction) | _ | \$7,829.47 |
| GST @ 7 % | - | \$548.06 |
| Grand Total Includes GST (After Deduction) | | \$8,377.53 |

Assessment Notes

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93 Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

| PARTICULARS OF (| CLAIM | | |
|--|--|--|-------------------------------|
| Claim Type: Policy No: | OD (OWN DAMAGE) DMPCSN3035061700 | Ref. No: Date of Loss: | OD/18034 20/12/2017 |
| Vehicle Reg. No.: Driver Age/Info: TP Injury Involved? Insured/Claimant: Driver: | SLM1686D 40 / MALE YES SEE KIM SIONG PETER SEE KIM SIONG PETER | Driveable? Party At Fault: Third Party Involved? Contact No: | UNKNOWN YES +6591159668 |
| Make/Model: | TOYOTA HARRIER, 2.0 PREMIUM (A) | Vehicle Reg. Date: | 30/06/2015 |
| Vehicle Colour: Engine No: Odometer: | BLACK 3ZRB563107 26461 KM | Chassis No: | ZSU600045582 |

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

6

Description of Accident/Loss

Present Location:

AS PER ATTACHED SKETCH PLAN AND POLICE REPORT

CAR CITY AUTO CENTRE PTE LTD (HQ)

| COST OF CLAIMS | | Amount |
|------------------------------|------------------------------|----------|
| COST OF CLAIMS | - | 7,833.00 |
| Parts Miscellaneous Items | | 302.00 |
| | | 1,444.47 |
| Labour Delictured: Labour | | 0.0 |
| Paintwork Labour | | 0.00 |
| Towing | Calculated Gross Total (S\$) | 9,579.47 |
| | - Excess (S\$) | 1,750.00 |
| | (S\$) | 7,829.47 |
| | + GST 7.00% (S\$) | 548.06 |
| | Nett Amount (S\$) | 8,377.53 |

This claim is handled by: HO TOO BOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

9157.47

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Dec 2017)

Parts:

M1-SUV

TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Validity:

Print Code: Car City Auto Centre Pte Ltd/SLM1686D/22/12/2017 14:31 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

| Est | imat | es | on | Parts |
|-----|------|----|----|-------|
| | | | | |

| No. | Qty | Part No. | Particulars | %Disc | %Depr | | Amount |
|-----|---------|----------|-----------------------|-------|-------|------|-------------------|
| 1 | 1 | NA | *BONNET | 0.00 | 0.00 | 00 | *680.00 F |
| 2 | 1 | NA | *BONNET CHROME | 0.00 | 0.00 | SCR | *160.00 F |
| 3 | 1 | NA | *BONNET INSULATION | 0.00 | 0.00 | | *75.00 F xrm |
| 4 | 1 | NA | *BONNET LOCK | 0.00 | 0.00 | Twi | *80.00F / |
| 5 | 1 | NA | *BUMPER RETAINER LH | 0.00 | 0.00 | 131 | *60.00 F < |
| 6 | 1 | NA | *BUMPER RETAINER RH | 0.00 | 0.00 | 64 | *60.00 F |
| 7 | 1 | NA | *CONDENSER | 0.00 | 0.00 | | *520.00 F xxxx |
| 8 | 1 | NA | *FRONT BUMPER | 0.00 | 0.00 | 1015 | *620.00 F |
| 9 | 1 | NA | *FRT BUMPER CLAMP KIT | 0.00 | | | *12.00 F XM |
| 10 | 1 | NA | *FRT BUMPER GRILLE | 0.00 | 0.00 | -tn | *180.00 F |
| 11 | 1 | NA | *FRT BUMPER REINF | 0.00 | 0.00 | BA | *165.00 F |
| 12 | 1 | NA | *FRT ENG COMP PROTECT | 0.00 | 0.00 | | *65.00 F Xny |
| 13 | 1 | NA | *FRT IMPACT ABSORBER | 0.00 | 0.00 | 411 | *65.00 F |
| 14 | 1 | NA | *FRT LWR BUMP GRILLE | 0.00 | 0.00 | cut | *155.00 F |
| 15 | 1 | NA | *FRT LWR BUMPER COVER | 0.00 | 0.00 | Tin | *160.00 F |
| 16 | 1 | NA | *GRILLE | 0.00 | 0.00 | 1300 | *280.00 F |
| 17 | 1 | NA | *L/BUMP IMPACT DAMPER | 0.00 | 0.00 | 4 | *35.00 F |
| 18 | 1 | NA | *L/F BUMPER COVER | 0.00 | 0.00 | 1/4 | *32.00 F |
| 19 | 1 | NA | *L/F HINGE | 0.00 | 0.00 | | *48.00 F X/ |
| 20 | 1 | NA | *L/F PANEL | 0.00 | 0.00 | | *95.00 F XA |
| 21 | 1 | NA | *L/F SIDE MEMBER END | 0.00 | 0.00 | | *85.00 F KR |
| 22 | 1 | NA | *L/F WHEELHOUSE COVER | 0.00 | 0.00 | | *230.00 F XNN |
| 23 | 1 | NA | *L/F WING | 0.0 | 0.00 | | *420,00 FX |
| 24 | 1 | NA | *L/F WING CLAMP KIT | 0.0 | 0.00 | | *18.00 F |
| 25 | 1 | NA | *L/FOG LAMP CARRIER | 0.0 | 0.00 | | *28.00 F × ~~ |
| 26 | 1 | NA | *L/INN BUMPER BRACKET | 0.0 | 0.00 | 15/1 | *110.00 F |
| 27 | 1 | NA | *L/RADIATOR AIR GUIDE | 0.0 | 0.00 | | *60.00 F ×447 |
| 28 | 1 | NA | *LEFT BONNET STOP | 0.0 | 0.00 | | *16.00 F × 141 |
| 29 | 1 | NA | *LEFT HEADLAMP ASSY | 0.0 | 0.00 | CRA | *1,050.00 F |
| 30 | 1 | NA | *LOCK CARRIER BRKT | 0.0 | 0.00 | | *180.00 F Ann |
| 31 | 1 | NA | *LOCK CARRIER STRUT | 0.0 | 0.00 | 6/1 | *105.00 F |
| 32 | 1 | NA | *R/BUMP IMPACT DAMPER | 0.0 | 0.00 | BA | *35.00 F |
| 33 | 1 | NA | *R/F BUMPER COVER | 0.0 | | 15.4 | *32.00 F |
| 34 | 1 | NA | *R/F HINGE | 0.0 | 0.00 | | *48.00 FXA |
| 35 | 1 | NA | *R/F PANEL | 0.0 | 0.00 | | *95.00 F X R |
| 36 | 1 | NA | *R/F SIDE MEMBER END | 0.0 | 0.00 | | *85.00 F KR |
| 37 | 1 | NA | *R/INN BUMPER BRACKET | 0.0 | 0.00 | | *110.00 F X444 |
| 38 | 1 | NA | *R/RADIATOR AIR GUIDE | 0.0 | 0.00 | | *60.00 Fx 149 |
| 39 | 1 | NA | *RIGHT BONNET STOP | 0.0 | 0.00 | | *16.00 F X n h |
| 40 | 1 | NA | *RIGHT HEADLAMP ASSY | 0.0 | 0.00 | | *1,050.00 F x n ~ |
| 41 | 1 | NA | *UPPER AIR GUIDE | 0.0 | 0.00 | | *80.00 F x ^ 10 |
| | anchise | | | | | | 7.460.00 |

Sub Total (S\$) + Margin on L,N Items 5.00% (S\$) 7,460.00 373.00

Car City Auto Centre Pte Ltd/SLM1686D/22/12/2017 14:31. Not valid without Reference section. Generated using Merimen e-Claims IEAS

No. Qty Part No.

Particulars

%Disc %Depr

Amount

Total Parts (S\$)

7,833.00

Car City Auto Centre Pte Ltd/SLM1686D/22/12/2017 14:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

| Es No | | ates on Miscellaneous Items Particulars | | Amount |
|----------|-------|--|-----------------|---------------|
| Mis | cella | neous Items | | 600 0000 1000 |
| 1 | 1 | AIR CON GAS | | 50.00 |
| 2 | 1 | ANTI-FREEZE | | 60.00 KA |
| 3 | 1 | AUDATEX FEE | | 42.00 |
| 4 | 1 | NUM PLATE & HOLDER | | W 50.00 4 |
| 5 | 1 | SUNDRY PARTS | | Nec 100.00 / |
| | | | Sub Total (S\$) | 302.00 |

| Estimates | on | Labour |
|-------------|-----|--------|
| Lottillatoo | 011 | |

| No | Particulars | Lab.Type | | Amount |
|-----|-------------------------------|-------------------------|-----------------------|----------|
| Lab | our Items | | 2 3 5 2 K - 2 - 2 - 2 | |
| 1 | Total Paint Labour | New | 409.40 | 519.80 |
| 2 | Total Paint Materials | New | 174.43 | 211.67 |
| 3 | Total Panel/Mechanical Labour | New | 707.40 | 713.0 |
| | | Gross Labour Cost (S\$) | | 1,444.47 |

Car City Auto Centre Pte Ltd/SLM1686D/22/12/2017 14:31. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93 Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

(SUPPLEMENTARY)

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

| PARTICU | ARS OF | CLAIM |
|---------|--------|-------|
| | | |

Claim Type:

OD (OWN DAMAGE)

Ref. No:

OD/18034

Policy No:

DMPCSN3035061700

Date of Loss:

20/12/2017

Vehicle Reg. No.:

SLM1686D

Driveable?

UNKNOWN

Driver Age/Info:

40 / MALE

Party At Fault:

Third Party Involved? YES

TP Injury Involved?

YES

+6591159668

Insured/Claimant: Driver:

SEE KIM SIONG PETER SEE KIM SIONG PETER Contact No:

Make/Model:

TOYOTA HARRIER, 2.0 PREMIUM

Vehicle Reg. Date:

30/06/2015

Vehicle Colour:

(A)

BLACK

3ZRB563107

Chassis No:

ZSU600045582

Engine No: Odometer:

26461 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

6

Description of Accident/Loss AS PER ATTACHED SKETCH PLAN AND POLICE REPORT

Present Location:

CAR CITY AUTO CENTRE PTE LTD (HQ)

| COST OF CLAIMS | | Amount |
|---------------------|----------------------------|----------|
| Parts | | 273.00 |
| Miscellaneous Items | | 0.00 |
| Labour | | 0.00 |
| Paintwork Labour | | 0.00 |
| Towing | | 0.00 |
| | Gross Total (S\$) | 273.00 |
| | + GST 7.00% (S\$) | 19.11 |
| | Nett Amount (S\$) | 292.11 |
| | + Previous Estimates (S\$) | 8,377.53 |
| | Claim Total (S\$) | 8,669.64 |

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Jul 2018)

Parts:

M1-SUV

TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Validity:

Print Code: Car City Auto Centre Pte Ltd/SLM1686D/03/07/2018 15:02 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

| No. | timates on P Qty Part No. | Particulars | %Disc | %Depr | Amount |
|------|------------------------------|----------------------------|----------------------------|-------|-------------|
| - | 1 | *FRONT BUMPER LWR GRILLE & | epail 0.00 | 0.00 | *155.00 F & |
| 2 | i | | 0.00 | 0.00 | *105.00 F |
| F=Fr | anchise part. | • | Sub Total (S\$) | | 260.00 |
| | | + Margin | n on L,N Items 5.00% (S\$) | | 13.00 |
| | | | Total Parts (SS) | | 273.00 |

Car City Auto Centre Pte Ltd/SLM1686D/03/07/2018 15:02. Not valid without Reference section. Generated using Merimen e-Claims IEAS