

INS. CASH OWNER

CC /AIG1702

1 KB
10/01

ASSIGNMENT

Surveyor

DOI

Date / Time

Registered in Member

Pre-assign / CC / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II SS

Is driver the owner?

If NO, Driver Name / Age

Driver Tel No.

HP

D.O.A.

Nature of Accident

YES / NO

CVL YES / NO

Claim No.

Policy No.

Make / Model

Place of Accident

O/GIA REPORT YES / NO / IP GIA REPORT YES / NO

Insured Liability

Final? Yes / No



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS

Date / Time

STAGE

DATE / PIC

Non Reporting Incident

Non Reporting for 2 days

Non Reporting for 3 days

Notification for non-pickup

Call On 15/11/87 JID Hanan

After call to GIC

Documentation Check List: Handler Typist

Notification for non-pickup

After call to GIC

Authorisation to Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

15/11/87 10:39am

spoke to GIC 90079663, claimed the car was stolen for
show that her car didn't hit the car in front of
it. Will be explain further, but the car's condition
in English well, require for a mandarin speaking.
will find out later

update information

update information

update information

update information

update information

update information

PRELIMINARY ADVICE Date/Time

Sent By

Confirm by

Email ☐ Call ☐

FINALIZATION

Date/Time

Confirm with

days Reduction

Repair Cost

SS

FINAL SETTLEMENT

Date/Time

(Agreed / Assessed) HOA SIN No.

Final Liability

SS

Repair Cost

SS

Loss of Rental (LOR)

SS

days

Loss of Use (LOU)

SS

days

Loss of Income (LOI)

SS

days

LOR only ☐ LOU only ☐

SS

LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GLA/LTA Search

SS

Medical

SS

Disbursement

SS

Legal Cost

SS

e.g. Towal Independent

Total

SS

Global Sum SS

FINAL PAYMENT

Date/Time

Confirm with

Payee 1

SS

Name 1

Payee 2 (Strike if N.A.)

SS

Name 2

Payee 3 (Strike if N.A.)

SS

Name 3

Email ☐ Call ☐

1) Claim Status: Normal/Reject/Private Settle


2) Report Format

3) Survey fee

Project: [illegible]

Date: [illegible]

By: [illegible]
 Title: [illegible]
 Date: [illegible]



Section: [illegible]

BS [illegible] [illegible] [illegible]

Item: [illegible]
 Description: [illegible]
 Quantity: [illegible]
 Unit: [illegible]

Price: [illegible]
 Total: [illegible]
 Remarks: [illegible]

Page: [illegible]
 Date: [illegible]

Signature: [illegible]

Prepared By: [illegible]
 Checked By: [illegible]

Date: [illegible]
 Signature: [illegible]

Project: [illegible]
 Date: [illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave * #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No 19960719BR GST Reg No 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG17024366/Ahb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date 26-12-2017



Code : AIG

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SLQ 8970R	Veh. Inspected	SLP 7818K
	Policy No.		Coverage (%)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	26/12/2017

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer		Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.	
----	--

General Information

5.	Accident Date	21/12/2017	Inspection Date	22/12/2017
	Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT, WESTVILLE SINGAPORE 648541		

Remarks

5a.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	---



Third Party Insurer : AIG
 Insured's Veh No : SLQ897DR
 Date of accident : 21.12.2017

Messrs Grab Rentals Pte Ltd

Date : 21.12.2017

Estimate To Repair : Toyota Vios 1.5E CVT
 Vehicle No : SLP7818K
 Chassis No : MHFB29F3302012080

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
		LIST ITEMS		
			\$ 1,662.40	\$ 1,662.40
1	1 pc	bootlid	\$ 190.40	\$ 190.40
2	1 pc	bootlid lock	\$ 18.50	\$ 18.50
3	1 pc	bootlid lock striker	\$ 188.80	\$ 188.80
4	1 pc	bootlid weatherstrip	\$ 79.80	\$ 159.60
5	2 pc	bootlid hinge	\$ 234.30	\$ 234.30
6	1 pc	bootlid inner trim	\$ 4.30	\$ 17.20
7	4 pc	bootlid inner trim clips	\$ 4.30	\$ 12.90
8	3 pc	bootlid lock cable clips	\$ 4.30	\$ 12.90
9	3 pc	bootlid wire harness clips	\$ 44.10	\$ 44.10
10	1 pc	bootlid vios badge	\$ 59.80	\$ 59.80
11	1 pc	bootlid centre emblem badge	\$ 39.40	\$ 39.40
12	1 pc	bootlid E badge	\$ 164.70	\$ 164.70
13	1 pc	bootlid outer garnish	\$ 79.80	\$ 159.60
14	2 pc	rear licence plate lamp	\$ 694.70	\$ 694.70
15	1 pc	rear end panel	\$ 234.30	\$ 234.30
16	1 pc	rear end panel inner trim	\$ 4.30	\$ 17.20
17	4 pc	rear end panel inner trim clips	\$ 75.00	\$ 150.00
18	2 pc	rear luggage floor foam compartment	\$ 375.80	\$ 751.60
19	2 pc	rear lamp	\$ 238.90	\$ 238.90
20	1 pc	o/s rear lamp panel	\$ 9.50	\$ 57.00
21	6 pc	rear lamp clips holder	\$ 969.70	\$ 969.70
22	1 pc	o/s rear fender	\$ 395.10	\$ 395.10
23	1 pc	rear fender inner trim	\$ 4.30	\$ 17.20
24	4 pc	rear fender inner trim clips	\$ 45.10	\$ 45.10
25	1 pc	o/s rear fender air vent	\$ 504.90	\$ 504.90
26	1 pc	rear bumper	\$ 323.30	\$ 323.30
27	1 pc	rear bumper reinforcement	\$ 130.50	\$ 261.00
28	2 pc	rear bumper reflector	\$ 115.10	\$ 230.20
29	2 pc	rear bumper side retainer	\$ 4.30	\$ 43.00
30	10 pc	rear bumper clips	\$ 89.80	\$ 179.60
31	2 pc	rear bumper splashshield cover		\$ 8,077.40
				\$ 2,019.35
		Less 25%		\$ 6,058.05
		Balance c/f		\$ 6,058.05



Third Party Insurer : **AIG**
 Insured's Veh No : **SLQ8970R**
 Date of accident : **21.12.2017**

Messrs Grab Rentals Pte Ltd

Date : **21 12 2017**

Estimate To Repair Toyota Vios 1.5E CVT
 Vehicle No : **SLP7818K**
 Chassis No : **MHFB29F3302012080**

Pages : **2 of 2**

S/No	Quantity	Description	Unit price	Amount
		Balance b/f		\$ 6,058.05
		<u>SPECIAL NETT ITEMS</u>		
32	1 pc	rear licence plate	\$ 80.00	\$ 80.00
33	1 set	rear bumper parking sensor	\$ 500.00	\$ 500.00
				\$ 580.00
		<u>LABOUR & MISC. CHARGES</u>		
1		To check electrical lighting concerned.		\$ 60.00
2		To remove and refit rear windscreen glass.		\$ 180.00
3		To rust-proofing of the affected areas		\$ 180.00
4		To reinstall of rear bumper parking sensor.		\$ 150.00
5		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.		\$ 120.00
6		To drop rear exhaust box and renew the same.		\$ 120.00
7		To transfer of bootlid fittings, attachments and perform water seepage test.		\$ 120.00
8		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		\$ 1,300.00
9		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.		\$ 550.00
10		Putty and spray painting of the affected portion.		\$ 1,100.00
				\$ 3,640.00
		Grand Total		\$ 10,278.05

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Vic (LKKAuto)

From: Pegasus Engineering <claims@pegasusengrg.com.sg>
Sent: Tuesday, 14 August, 2018 10:16 AM
To: Vic (LKKAuto)
Subject: Re: LOD - THIRD PARTY CLAIM - SLP7818K YOUR REF S: Q8970R ON 21.12.2017
LKK REF CC6/AIG17024366/Ahb3
Attachments: 14082018100849.pdf

Without Prejudice

Dear Vic,

Enclosed the signed Dv for your process of payment.

Thanks & Regards,

Sharon Oo
Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

On Tue, Aug 14, 2018 at 9:29 AM, Vic (LKKAuto) <vic@lpph@lkkauto.com> wrote:

Without Prejudice

Dear Patricia,

Noted with thanks

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."


Best Regards,

Vic Alpeh - Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6847-2006 / email: vic@pehy@lkkauto.com / fax: 6847-4108

318-51, Pava Usi Industrial Park, Ulu Avenue 1, #02-25 / S1408933



Save the Earth. Print only when necessary.

This e-mail, any attachments, and any linked material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not forward this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: claims@pegasusengrg.com.sg [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, 14 August, 2018 9:26 AM

To: Vic (LKKAuto)

Cc: Admin A

Subject: RE: LOD - THIRD PARTY CLAIM - SLP7818K YOUR REF SLQ8970R ON 21.12.2017 LKK REF CC6/AIG17024366/Ahh3

Dear Vic,

As per tele conversation, we confirm acceptance at global sum of \$4835.00.

Loss of use should read as loss of rental.

Please forward DV.

Best regards,

Sharon (p)

From: Vic (LKKAuto) <vicalpel@lkkauto.com>
Sent: Monday, 13 August 2018 4:22 PM
To: Pegasus Engineering <claims@pegasusengrg.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpel@lkkauto.com>
Subject: RE: LOD - THIRD PARTY CLAIM - SLP7818K YOUR REF SLQ8970R ON 21.12.2017 LKK REF
CC6/AIG17024366/Ahb3

Without Prejudice

Dear Sharon,

We refer further to the below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we offer to settle your client's claim as below:

Cost of Repair (w/gst)	\$ 4,226.50
Loss of Use (\$66.95 Grab Rate x 9 days)	\$ 602.55
LTA Search Fee	\$ 6.00
TOTAL	\$ 4,835.05

If agreeable, kindly let the owner chop and sign the attached DV then forward back to us a copy for payment processing.

The above amount is to be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**.

Thank you

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters


Best Regards,

Vic Alpeh - Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2096 - email: vic@lkkauto.com - fax: 6741 2108

Blk 51, Pava Ubi Industrial Park, Ubi Avenue 1, #02-25 - S1408933



Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and is for the sole use of the intended recipient. Use or distribution by any other third recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, its attachments and any copies thereof. Thank you.

From: Pegasus Engineering (<mailto:claims@pegasusengrg.com.sg>)

Sent: Friday, 27 April, 2018 6:03 PM

To: Asher Sng (LKKAuto); Admin A; Vic (LKKAuto)

Subject: LOD - THIRD PARTY CLAIM - SLP7818K YOUR REF SLO8970R ON 21.12.2017

Dear LKK,

Refer to the above accident

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

Thanks & Regards

Sharon Ow (co)

Pegasus Engineering & Trading Pte Ltd

51 Defu Lane 10

Singapore 539216

Tel : 6858 1846

Fax : 6487 6070

Email : claims@pegasusengrg.com.sg



GREAT AMERICAN INSURANCE COMPANY

UEN: T15FC0029B GST REG. NO: M303700811
3 TEMASEK AVENUE, #16-01 CENTENIAL TOWER
SINGAPORE 039190
TEL: +65 6804 6800
FAX: +65 6235 2610

CERTIFICATE OF INSURANCE

This Certificate is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) and Part IV of the Road Transport Act, 1987 (Malaysia).

Policy Details

Certificate Number	MOVVC010005176-00-001	Cover	Commercial Vehicle (Comprehensive)
Policyholder Name	Grab Rentals Pte. Ltd.	Chassis Number	MHFB29F3302012080
NCD Entitlement	N/A	Engine Number	2NRX160014
Hire Purchase	TOKYO CENTURY LEASING (SINGAPORE) PTE. LTD.	Registration Number	SLP7618K
Period of Insurance	From 19/06/2017 (00:00) to 19/06/2018 (23:59) (Both Dates Inclusive)		

Persons or Classes of Persons entitled to Drive

a) Any person who is driving on the Policyholder's order or with their permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle, has been vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to Use

- a) Use in connection with Policyholder's business
 - b) Use for carriage of passengers (other than for hire and reward) in connection with the Policyholder's business
- This Policy does not cover:
- a) Use for racing, pace making, reliability trial or speed testing

* Limitations rendered operative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

All Claims Excess	SGD 2,000.00
Windscreen Excess	SGD 100.00
ADDITIONAL EXCESS	Please refer overleaf

Driver Details

Named Driver (s) Grab Leasing Drivers or Grab's employees

Name of Intermediary Citrine System (S) Pte Ltd

Date of Issue 18/07/2017

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).)

Signed for and on behalf of
Great American Insurance Company

Authorised Signatory
.gch



To Whom It May Concern:

Dear Sir/ Madam,

Accident on 21/04/2017 at about 17:30

along Leong Joo Lay Road Leong Joo Lay Road

1. We refer to the above-mentioned accident and wish to inform that Grab Rentals Pte Ltd (~~Grab Rentals 2 Pte Ltd~~) is the registered owner of the vehicle registration number SZ 7701 (the "private hire"). The vehicle was hired to Benjamin Benjamin Benjamin Benjamin NRIC S 8812345 as a registered hirer of Grab Rentals Pte Ltd (~~Grab Rentals 2 Pte Ltd~~) at the time of occurrence of the aforementioned accident at a rental rate of S 14.95 per day (inclusive of GST) with effect from 21/04/2017 to 26/04/2018.
2. The company ~~collect~~ do not collect rental from the hirer from 21/04/2017 to 21/04/2017 when the said vehicle is undergoing repair. A replacement vehicle ~~was~~ was not given from 21/04/2017 to 26/04/2018.
3. Please liaise with our appointed workshop, Pegasus Engineering Trading Pte Ltd directly for any settlement of claims in respect of the said accident. We hereby authorized all agreed settlement payment made in favor of Pegasus Engineering Trading Pte Ltd.

Yours faithfully,


Tan Chee Wei

Sr. Operation Associate

GR0102



9A Lok Yang Singapore 628628
c/o 51 Defu Lane 10 Singapore 539216

Tel. 6858 1846 / HP 9628 6508
Fax: 6858 0877

Our Ref _____

Date _____

Your Ref _____

WITHOUT PREJUDICE

Claims Department -Executive In Charge

AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam

ACCIDENT INVOLVING _____

Refer to the above accident and please acknowledge receipt of this letter within 14 days

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf -

☐ Original survey report / _____ copies of photographs _____

☐ Original Tax-Invoice number _____ ☐ police report / police result

☐ Certificate Of Insurance _____ ☐ Vehicle search result

☐ Authorization To Act - Owner/Hirer ☐ _____

*Survey under insurance instruction / Independent surveyor / No survey

a) Cost of repair (inclusive GST) \$ _____

b) Survey fees / Photographs as per request \$ _____

c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees \$ _____

d) Loss of rental _____ days @ \$ _____ \$ _____

e) Loss of earnings / rental fees _____ days @ \$ _____ \$ _____

f) Administrative charges to negotiate settlement \$ _____
(Waive if 100% offer made within acknowledge timeframe)

g) _____ \$ _____

Total \$ _____

=====


* Driver's injury and other losses exclude in this claim

If you are agreeable to the above, please forward a charge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days

Yours faithfully,

Sharon Ouy

Email: claims@pegasuseng.com.sg



Auto
Consultants
Pte Ltd

51, UBI AVENUE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : 6651 6256/3561 FAX : 6651 6741 1105

Our Ref: CC6/AIG17024366/Abb3

13 FEBRUARY 2018

SL 1253
8 BUTTERWORTH LANE
#01-09
SINGAPORE 439423

Dear Sir/Madam,

ACCIDENT INVOLVING SLQ 8970R / SLP 7818K / OTHERS ON 21/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

/

Vic Alpeh

Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 / email: yicalpeh@lkkauto.com / fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 S(408933)

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM OWNER OF VEHICLE NUMBER _____

ACCIDENT INVOLVING _____

ALONG/AT _____

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to **PEGASUS ENGINEERING & TRADING PTE LTD.**

Name Grab Rentals Pte Ltd

Co Reg No 2016172006

Address 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact 6655 0005

Date

Signature

Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PEGASUS ENGINEERING & TRADING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,835.00** (Global Sum - all in) for vehicle no. **SLP 7818K** that was damaged pursuant to the accident which occurred on **21/12/2017** (date) along **BRAS BASAH ROAD** (location) involving vehicle no/s **SLO 8970R**. This is pursuant to the inspection conducted on **22/12/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRAB RENTALS PTE LTD** ("the third party claimant") of vehicle no. **SLP 7818K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLP 7818K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of _____ (month) **2018** (year)

Signed by appointed surveyor



Signed by "the workshop" (with chop)



Grab Rentals Pte Ltd
18 Sui Ming Lane
#01-08 Midview City
Singapore 573960

Vehicle Model : TOYOTA VIOS 1.5E CVT
Vehicle No : SLP7818K
Chassis No : MHFB29G3302012080

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : 5LQ8970R
Date of accident : 21.12.2017

Tax Invoice No : IV18/04-1172
Invoice Date : 21.04.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	5 3,950.00
Sub Total	\$ 3,950.00
GST (7.00%)	\$ 276.50
Total	\$ 4,226.50

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD

Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusenrg.com.sg

Enquire Vehicle & Owner Information (Vehicle No. SLQ8970R As At 21 Dec 2017 / 15:34:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: PET(LING)SLP7818K

Current Owner Details

Owner ID Type: Business
Owner ID: 53335093W
Owner Name: S11253
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No: 8
Registered Street Name: BUTTERWORTH LANE
Registered Unit No.: # 01 - 09
Registered Building Name: -
Registered Postal Code: 439423

Current Vehicle Details

Vehicle No.: SLQ8970R
Make Description/Model: CITROEN / C4 PICASSO 1.6 BLUEHD1 EAT6
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE LTD.



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (\$)
01	Toyota Prius 1.798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,


Tay Chen Wee
Grab Rental Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

05/01/2018

CLAIM SUBFOLDER TRACKING

Case No.	Submitted	Not Submitted	Est. Received	Accepted	Est. Accepted	Est. Rejected	Status
Mail	26 Dec 2017		27 Dec 2017 00:00	S\$3,950.00 Est. Estimates	S\$3,950.00 view Rpt		Pending for Survey Report Cancel Case
	Est. Rpt		Est. Adj. Rpt				

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SL1253 , Co. Reg. No : 51335092W								
Main Claimant:	GRAB RENTALS PTE LTD. , Co. Reg. No : 201617709G								
Vehicle Reg. No:	SLP7818K	Date of Loss:	11/12/2017 15:00:59 [6 Months and 2 Days From 1st Reg Date (Main yr)]						
Claim Type:	TP / 03101862135G	Policy/Power Rate No.:	1770022378						
Vehicle Reg. No (Insured):	SLQ8970R	Policy No (Claimant):	MOMVC000005175-00-000						
Repaier:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEHU LANE 10, SINGAPORE Tel: 68581845								
Handling Insurance:	ATG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419 3000 ... [Handled by Wui, Shawn-K3] Share/Save With PA 3.com								
Claimant's Insurance:	Great American Insurance Company (HQ) Tel: 6804 5047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) Tel: 6756 3561 ... [Handled by ADRIAN LING]. [Final Rpt due 05/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*SLP781BK (0310186213SG)
[SLQ8970R]
TP

Pegasus Engineering & Trading Pte Ltd

View [View in French](#) 

! per page

Thumbprint Print

1. ☐ 2. ☒ 3. ☒

Thumbnail Print

3 per page ☐ ☒

Thumbnail Print

[illegible]

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_doc... 20/8/2018

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ8970R (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLP7818K (TP veh)		
Date of Accident:	21/12/2017		

Global Sum Settlement	☒ [X]	Yes	☐ []	No	
Repair Estimate		\$		11,254.31	
Final Repair Cost		\$		4,835.00	
Loss of Use		\$			9.00 days at \$66.95 per day
Rental (if any)		\$			days
LTA / GIA Search Fee		\$			
Others		\$			
		\$			
Final Settlement Sum (Global Sum)		\$		4,835.00	
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)					
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop:		BOLA Applicable Yes/ No BOLA Scenario No			
BOLA Liability _____ (%)		Assessed Liability (*) _____ 0 _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	Pegasus Engineering & Trading Pte Ltd	\$	4,835.00
2)		\$	
3)		\$	

JOANNE LEE KHANG MIN

20 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report; Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel. 6256-3561 Fax. 6844-8805 Email: sur@lkkauto.com.assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024366/AHB3Q2

Date: 20/08/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte Ltd	Policy No.	1700032378
Claimant Vehicle No:	SLP7818K	Insured Vehicle No:	SLQ8970R
Date of Loss:	21/12/2017	Nature of Claim:	TP
		Claim No	031018621350

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No	SLP7818K		
Make & Model	TOYOTA VIOS. 1.5 E (A)	Engine No:	2NRX160014
Reg. Date:	19/06/2017 (Man. Year: 2017)	Chassis No	MHFB29F3302012080
Colour:	Silver	Odometer:	20724 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition	Steering (Serviceable):	Yes	Footbrake (Serviceable)	Yes
Handbrake (Serviceable):	Yes	Engine Modification	No	Pre-accident Condition

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size	195/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

Note: above values represent the remaining tyre tread depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,638.05	3,343.15	3,294.90	49.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,630.00	2,250.00	57.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,518.05	4,973.15	5,544.90	52.72
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	10,518.05	3,950.00	6,568.05	62.45
+ GST 7.00/7.00% (S\$)	736.26	276.50	459.76	62.45
Nett Amount (S\$)	11,254.31	4,226.50	7,027.81	62.45
+ Loss of Use (9.0 x S\$66.95/day) (S\$)		602.55		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		4,835.05		
Global Sum Settlement (S\$)		4,835.00		

INSPECTION

Date of Assignment:	22/12/2017
Date Inspected:	22/12/2017 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair 6.0 days

Adjuster: ADR AN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and under the inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,662.40 FL	*762.50 FL
2	1		*BOOTLID LOCK	Damaged	190.40 FL	*190.40 FL
3	1		*BOOTLID LOCK STRIKER	Not Necessary	18.50 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Cut	188.80 FL	*188.80 FL
5	2		*BOOTLID HINGE	Not Necessary	159.60 FL	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	234.30 FL	*- FL
7	4		*BOOTLID INNER TRIM CLIPS	Not Necessary	17.20 FL	*- FL
8	3		*BOOTLID LOCK CABLE CLIPS	Not Necessary	12.90 FL	*- FL
9	3		*BOOTLID WIRE HARNES CLIPS	Not Necessary	12.90 FL	*- FL
10	1		*BOOTLID VIOS BADGE	Necessary	44.10 FL	*44.10 FL
11	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	59.80 FL	*59.80 FL
12	1		*BOOTLID E BADGE	Necessary	39.40 FL	*39.40 FL
13	1		*BOOTLID OUTER GARNISH	Not Necessary	164.70 FL	*- FL
14	2		*REAR LICENCE PLATE LAMP	Not Necessary	159.60 FL	*- FL
15	1		*REAR END PANEL	Dented	694.70 FL	*694.70 FL
16	1		*REAR END PANEL INNER TRIM	Deformed	234.30 FL	*234.30 FL
17	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	17.20 FL	*17.20 FL
18	2		*REAR LUGGAGE FLOOR FOAM COMPARTMENT	Not Necessary	150.00 FL	*- FL
19	2		*REAR LAMP	Cracked	751.60 FL	*751.60 FL
20	1		*O/S REAR LAMP PANEL	Repair	238.90 FL	*- FL
21	3		*REAR LAMP CLIPS HOLDER	Not Necessary	57.00 FL	*- FL
22	1		*O/S REAR FENDER	Repair	969.70 FL	*- FL
23	1		*REAR FENDER INNER TRIM	Not Necessary	395.10 FL	*- FL
24	4		*REAR FENDER INNER TRIM CLIPS	Not Necessary	17.20 FL	*- FL
25	1		*O/S REAR FENDER AIR VENT	Not Necessary	45.10 FL	*- FL
26	1		*REAR BUMPER	Deformed	504.90 FL	*504.90 FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	323.30 FL	*323.30 FL
28	2		*REAR BUMPER REFLECTOR	Not Necessary	261.00 FL	*- FL
29	2		*REAR BUMPER SIDE RETAINER	Necessary	230.20 FL	*230.20 FL
30	10		*REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
31	2		*REAR BUMPER SPLASHIELD COVER	Not Necessary	179.60 FL	*- FL
32	1		*REAR LICENCE PLATE	Bent	80.00 FS	*60.00 FS
33	1		*SET REAR BUMPER PARKING SENSOR	Damaged	500.00 FS	*220.00 FS

F=F franchise part, S=SpecNet, L=ListItemDisc

Sub Total (\$\$) **8,657.40** **4,364.20**- List Item Discount on L Items 25.00/25.00% (\$\$) **2,019.35** **1,021.05**Total Parts (\$\$) **6,638.05** **3,343.15**

Report was unsubmitted during this print-out

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	40.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER, TO ENABLE REPAIR	New	120.00	60.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	120.00	0.00
7	TO TRANSFER OF BOOTLIF FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	120.00	50.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,300.00	800.00
9	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	550.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,100.00	600.00
Gross Labour Cost (\$\$)			3,880.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >