

22/03/2002

ASS. REC. BY:

REF:

CS/MS617024419 / Attbel

Special Instruction:

Surveyor:

Hollman

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MWH

Date/Time:

26/2207 1pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFC 68006

Insured:

GW 74503

at Workshop m/s

Premium

Tel:

6768 9828

of

55 Ubi Rd 1

Policy No:

A2AD16314TMV

Claim No:

542275

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22.12.2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFC 68006 - X
	GW 74503 - X
	Submit preli advise.
	Convert to OD claim.

REF: MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Premium Auto
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFE68006 Yr Regd: 18 May 2013
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi S5 cc 2995
 Colour: white A.C. Insured / Std / NI / NA
 Sp. Reading: 69804 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8T6DA052116
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 255/35 8R19
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIF / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 26-12-17
 Survey held at W/S 5:20pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?



Preli. Report

29/12 Typist

Final Report

Date/Time: File Return to?

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: 300

Transportation

3-PS \$

Photos

Other

TOTAL

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Weaving \$

Report Format: TPLump Sum / I.B.I. \$ —10300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024419/Gtb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 7450J	Veh. Inspected	SFC 6800G
Policy No.	A29016314TMV	Coverage (\$)	0.00
Claim No.	542275	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	26/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/12/2017	Inspection Date	27/12/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017		26 Dec 2017 13:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	MILLAND TRADING, Co. Reg. No.: 40075700A		[Created by insurer]
Main Claimant:	KHOO YU HUNG, ID: S7344196Z		
Vehicle Reg. No.:	SFC6800G		
Claim Type:	TP / 542275	Date of Loss:	22/12/2017 14:00 - :59
Vehicle Reg. No. (Insured):	GW7450J	Policy/Cover Note No.:	A29016314TMV (Third Party Only) Coverage: 16/10/2017 - 15/10/2018
		Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		
Driver/Custodian (Insured):	LIM ENG CHEONG (), NRIC: S0096326G, Tel: +6597710283		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Denise Tay (LKKAuto)

From: Claims Department <claims@premiumauto.com.sg>
Sent: Thursday, 28 December, 2017 6:33 PM
To: SUR
Cc: 'Claims Department'
Subject: OD CLAIM FOR SFC 6800 G

Dear all,

The above mention vehicle was surveyed by Guo Qiang on 26/12/2017 for MSIG.
Now the owner has converted to claim AIG.

Kindly inform Guo Qiang to adjust the labour to AIG rate and submit to AIG for approval.
We will also forward the GIA report asap for your perusal.

Best Regards,
Claims Advisor

Kee Siang


Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4196Z

Vehicle Details

Vehicle No.: SFC6800G
Vehicle to be Exported: No
Intended De-registration Date: 27 Dec 2017
Vehicle Make: AUDI
Vehicle Model: S5 SPORTBACK 3.0 TFSI QU
Primary Colour: White
Manufacturing Year: 2013
Engine No.: CGW063327
Chassis No.: WAUZZZ8T6DA052116
Maximum Power Output: 245.0 kW (328 bhp)
Open Market Value: \$65,537.00
Original Registration Date: 18 Mar 2013
First Registration Date: 18 Mar 2013
Transfer Count: 0
Actual ARF Paid: \$65,537.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Mar 2023
PARF Rebate Amount: \$49,152.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2023
COE Category: B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$92,667.00
COE Rebate Amount:	\$48,329.00
Total Rebate Amount:	\$97,481.00

The information contained herein is correct as at 27 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/12/2017 21:09
Date Of Accident	22/12/2017 14:00
Exact Location Of Accident	CARPARK AT MOHD SULTAN RD/RIVER VALLEY RD OF ST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFC6800G
Insured/Policyholder	
Name Of Registered Owner	KHOO YU HUNG
NRIC No	S7344196Z
Email Address	KHOORYH@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97818310
Alternative Phone No	OFFICE-97818310
Vehicle Particulars	
Manufacturer	AUDI
Model	S5 SB 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100333826-04000
Cover Note Number	
Driver	
Name of Driver	KHOO YU HUNG
NRIC No	S7344196Z
Date Of Birth	06/12/1973
Occupation	INDOOR
Date Of Driving Pass	22/12/2003
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97818310
Fax Number	
Contact Number	OFFICE-97818310
EMail Address	KHOORYH@YAHOO.COM

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/17 at 2pm I was parked and waiting in my car (SFC6500E) at carpark M077 off Mahal Subram / River Valley Road, when a Toyota Lite Ace van driven by Mr. Lim Eng Cheong (NRIC 500963266) reversed quickly into the lot next to me. He was very close to my car, and by the time I could start my engine to avoid the horn he had been turned off of the lot and knocked into the front right side of my car.

Mr. Lim was apologetic and admitted his mistake and provided a note in the airport.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Lim Eng Cheong
NRIC: 500963266

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





HQ/LINE TEL: (65) 6419 3000
FAX: (65) 6415 3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100333826-04000

OWN DAMAGE EXCESS S\$2000.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SFC6800G

1) VEHICLE REGISTRATION NO.

KHOO YU HUNG (QIU YUHONG)

2) NAME OF INSURED

18 Mar 2017

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

17 Mar 2018

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :N.A

a) The Insured.

The Insured may also drive a motor car not belonging to him or hired (under a hire purchase agreement or otherwise) by him or his employer or business partner.

All drivers who are below the age of 23 are excluded in this Policy.

All drivers who are below the age of 28, above the age of 65 or with less than 2 years' driving experience are subject to an Excess of S\$5,000.00.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Nova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER Cheng Jin Choo Shirley

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 15 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE

37344196Z

KHOO YU HUNG
(QIU YUHONG)

Issue Date: 06 Dec 1973
Expiry Date: 19 Mar 2004

1001169789G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7344196Z**

丘育弘

Name
KHOO YU HUNG
(QIU YUHONG)

Race
CHINESE

Date of birth
06-12-1973

Sex
M

Country of birth
SINGAPORE

S7344196Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

16 Aug 1994

NP 428A

Licence No: **S7344196Z**

3446301

S7344196Z

NRIC No: **S7344196Z**

Date of issue
22-12-2003

11F MOUNT SINAI LANE #05-30
SINGAPORE 277055

NRIC No: **S7344196Z** Date: **28/09/2018**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1253/2017/JT
Date : 23-Dec-17

Vehicle not workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr. Khoo Yu Hung
Address : 11F Mount Sinai Lane
#05-30
Singapore 277055
Telephone : HP +65 9781 8310
Type of Claim : Third Party Claims
Policy No. : 2100333826-04000
Vehicle No : **SFC 6800 C**
Model Code : Audi S5 SB 3.0 TFSi qu
Model / Year : Mar-13
Engine No : CGW 063327
Chassis No : WAUZZZ8T6DA052116
Mileage :
Date In : 22-Dec-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Dec-17
Place of Accident : Carpark at Mohd Sultan Rd / River Valley Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFC 6800 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/
2	To dismantle and renew front bumper, RHS front fender and RHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,100.00	1200
3	To respray front bumper and RHS front fender.	\$ 1,700.00	1200
4	To renew RHS Front rim and carry out wheel alignment.	S/N \$ 280.00	240
5	To carry out diagnostic checks.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 4,752.00	

Tow Vehicle from accident scene to
PA

S/N \$ 280.00 ?

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFC 6800 G.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER / <i>ll</i>	\$ 2,429.00	
2	AIR GRILLE - RHS <i>X NN</i>	\$ 291.00	
3	FRONT BUMPER GUIDE - RHS <i>?</i>	\$ 36.00	
4	FRONT FENDER - RHS <i>/ blue</i>	\$ 900.00	
5	FRONT FENDER INNER BRACKET - RHS <i>?</i>	\$ 49.00	
6	FRONT FENDER OUTER BRACKET - RHS <i>?</i>	\$ 49.00	
7	FRONT FENDER BRACE - RHS <i>?</i>	\$ 102.00	
8	FRONT WHEEL HOUSE LINER - RHS <i>?</i>	\$ 157.00	
9	WHEEL HOUSE LINER ATTACHMENT PARTS - RHS <i>?</i>	\$ 38.00	
10	HEADLIGHT - RHS <i>?</i>	\$ 2,298.00	
11	HEADLIGHT MOUNTING - RHS <i>?</i>	\$ 106.00	
12	HEADLIGHT BRACKET - RHS <i>?</i>	\$ 89.00	
13	ALUMINIUM RIM - RHS <i>X NN</i>	\$ 892.00	
14	SUNDRIES <i>?</i>	\$ 400.00	
TOTAL SPARE PARTS		:	\$ 7,836.00
TOTAL LABOUR CHARGES		:	\$ 4,752.00
GRAND TOTAL		:	\$ 12,588.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

12267

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Guo Qing - 82880282
Surveyed Date : 26/12/17
Authorised Date :
Excess Cost : before paint photos.
Liability :
Remarks : 5 Days. Not authorise.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017		26 Dec 2017 13:00 Edit Adj Rpt	S\$6,641.00 Edit Estimates	S\$6,641.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS			[Created by Insurer]
Insured:	MILLAND TRADING, Co. Reg. No.: 40075700A		
Main Claimant:	KHOO YU HUNG, ID: S7344196Z		
Vehicle Reg. No.:	SFC6800G	Date of Loss:	22/12/2017 14:00 - :59
Claim Type:	TP / 542275	Policy/Cover Note No.:	A29016314TMV (Third Party Only) Coverage: 16/10/2017 - 15/10/2018
Vehicle Reg. No. (Insured):	GW7450J	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 27/12/2017]		
Driver/Custodian (Insured):	LIM ENG CHEONG (), NRIC: S0096326G, Tel: +6597710283		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SFC6800G (542275)**
[GW7450J]
TP
KHOO YU HUNG
Dec 22 2017 2:00PM
[MILLAND TRADING]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail
1	26/12/17 13:01	Accident Statement Addm. #1 <small>From: SC - Reg. No: GW7450J, Claimant: MILLAND TRADING</small>	Load HTM <input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
2	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
3	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
4	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
5	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
6	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
7	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
8	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
9	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
10	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
11	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
12	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
13	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
14	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
15	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
16	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
17	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
18	29/12/17 15:34	General View	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail
1	26/12/17 13:01	TPD SFC6800G GIA REPORT.	Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024419/GTBE2

Date: 05/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29016314TMV
 Claimant Vehicle No : SFC6800G Insured Vehicle No : GW7450J
 Date of Loss: 22/12/2017 Nature of Claim: TP Claim No: 542275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFC6800G**
 Make & Model: AUDI S5 SPORTBACK, 3.0 TFSI QUATTRO (A) Engine No: CGW063327
 Reg. Date: 18/03/2013 (Man. Year: 2013) Chassis No: WAUZZZ8T6DA052116
 Colour: White Odometer: 69804 km
 Engine Capacity: 2995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35Z R19 Rear Tyre Size: 255/35Z R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,116.00	3,329.00	4,787.00	58.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	3,312.00	1,440.00	30.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,868.00	6,641.00	6,227.00	48.39
+ GST 7.00/7.00% (S\$)	900.76	464.87	435.89	48.39
Nett Amount (S\$)	13,768.76	7,105.87	6,662.89	48.39

INSPECTION

Date of Assignment: 26/12/2017
 Date Inspected: 26/12/2017 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$3,604.00 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 05 Jan 2018)
Parts: 143 **AUDI S5 SPORTBACK 3.0 TFSI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFC6800G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOW VEHICLE FROM ACCIDENT SCENE TO PREMIUM AUTOMOBILES	* Check	280.00 FS	*- FS
2	1		*FRONT BUMPER	Deformed	2,429.00 FS	*2,429.00 FS
3	1		*AIR GRILLE - RHS	Not Necessary	291.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE - RHS	* Check	36.00 FS	*- FS
5	1		*FRONT FENDER - RHS	Buckled	900.00 FS	*900.00 FS
6	1		*FRONT FENDER INNER BRACKET - RHS	* Check	49.00 FS	*- FS
7	1		*FRONT FENDER OUTER BRACKET - RHS	* Check	49.00 FS	*- FS
8	1		*FRONT FENDER BRACE - RHS	* Check	102.00 FS	*- FS
9	1		*FRONT WHEEL HOUSE LINER - RHS	* Check	157.00 FS	*- FS
10	1		*WHEEL HOUSE LINER ATTACHMENT PARTS - RHS	* Check	38.00 FS	*- FS
11	1		*HEADLIGHT - RHS	* Check	2,298.00 FS	*- FS
12	1		*HEADLIGHT MOUNTING - RHS	* Check	106.00 FS	*- FS
13	1		*HEADLIGHT BRACKET - RHS	* Check	89.00 FS	*- FS
14	1		*ALUMINIUM RIM - RHS	Not Necessary	892.00 FS	*- FS
15	1		*SUNDRIES	* Check	400.00 FS	*- FS
					Total Parts (S\$)	8,116.00 3,329.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,200.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,700.00	1,200.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,752.00	3,312.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >