

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

*28/12
Confirmed with
Marcus
US \$ 4900.00*

*not added
note
1/5 \$ 4900
6 days
26/12/17*

Quotation No : QO17/12-1192	Quotation Date : 23/12/2017	Terms : 30 DAYS
Vehicle No : SLN8984S	Chassis No : JM6BN22A8H0152828	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED VEHICLE NO: GBG7035T, DATE OF ACCIDENT: 22.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	N/S REAR LAMP	1 Cne	519.0000	519.00 ✓
2	REAR LAMP CLIPS HOLDER	3 n1	10.0000	30.00 ✓
3	REAR END PANEL	1 Sdy	556.0000	556.00 ✓
4	REAR END PANEL INNER TRIM	1 qwi	96.0000	96.00 ✓
5	REAR END PANEL INNER TRIM CLIPS	4 n1	5.0000	20.00 ✓
6	REAR BUMPER	1 D.S	1,075.0000	1,075.00 ✓
7	REAR BUMPER REINFORCEMENT	1 3rd	538.0000	538.00 ✓
8	REAR BUMPER SIDE RETAINER	2 n/sbu	46.0000	92.00 ✓ 46
9	REAR BUMPER SIDE HOLDER	2 n/sbu	74.0000	148.00 ✓ 74
10	REAR BUMPER SIDE HOLDER RIVETS	4 11	6.0000	24.00 ✓
11	REAR BUMPER CLIPS	8 nu	5.0000	40.00 ✓
12	N/S REAR BUMPER REFLECTOR	1 gne	55.0000	55.00 ✓
13	REAR BUMPER TOW COVER	2 n/smis	18.0000	36.00 ✓ 18
14	BOOTLID	1 SUC	958.0000	958.00 ✓
15	BOOTLID LOCK TOP	1 qwi	198.0000	198.00 ✓
16	BOOTLID LOCK STRICKER BOTTOM	1 11	35.0000	35.00 ✓
17	BOOTLID WEATHERSTRIP	1 qwi	130.0000	130.00 ✓
18	BOOTLID INNER TRIM	1 11	121.0000	121.00 ✓
19	BOOTLID LOCK CABLE CLIPS	3 11	4.3000	12.90 ✓
20	BOOTLID MAZDA REAR LOGO	1 nu	54.0000	54.00 ✓
21	BOOTLID 3 EMBLEM	1 nu	64.0000	64.00 ✓
22	BOOTLID EMBLEM MAZDA	1 nu	75.0000	75.00 ✓
23	BOOTLID OUTER GARNISH	1 11	235.7000	235.70 ✓

C/F 0.00

Page 1 of 2

4506
3604.60

4496
3546.80

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/12-1192	Quotation Date : 23/12/2017	Terms : 30 DAYS
Vehicle No : SLN8984S	Chassis No : JM6BN22A8H0152828	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED VEHICLE NO: GBG7035T, DATE OF ACCIDENT: 22.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	BOOTLID INNER TRIM CLIPS	6	5.0000	30.00
25	LESS 20% (ITEM 1- 24)	1	-1,028.5200	-1,028.52
26	REAR BUMPER PARKING SENSOR	1 set	450.0000	450.00
27	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	180.0000	180.00
28	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	120.0000	120.00
29	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
30	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	80.0000	80.00
31	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,200.0000	1,200.00
32	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total 7,404.08
 GST(7.00%) 518.29
 Total (SGD) 7,922.37

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216