KIM CHWEE AUTO PTE LTD

VEHICLENO: YP3878J

QTY

PARTICULAR

AMOUNT SS

SPECIAL	NICTT	ITER AC	
SPELIAL	INFII	I I FIVI	•

1PCS	TAILLAMP O/S CM 220		\$265.00
1PCS	REAR LICENSE PLATE LAMP 11		\$105.00 X
1PCS	REAR LICENSE PLATE Sung	*	4 1./ . 1
1PCS	TAILGATE WOODEN BOARD N		\$2,200.00 🗶
1PCS	TAILGATE 60KM/H STICKER 11	and the second	\$20.00 ×
1PCS	24 PAX STICKER		\$20.00 %
1PCS	TAILGATE WOODEN LOWER MEMBER		
1PCS	TAILGATE STEP WOODEN BOARD		4050 00 00000000
1PCS	REAR HORIZONTAL WOODEN BOARD O/S A A		\$1,500.00 4005.
1PCS	REAR ALUMINIUM PANEL O/S		\$300.00 2005.
1PCS	TAILGATE LOWER METAL PLATE 🔨		\$600.00 ×
1PCS	REAR SAFETY BAR BUMPER AA		\$1,200.00 9
	,	TOTAL:	\$8,291.00

LABOUR CHARGES:

TO CHECK WIRING \$50.00 20 TO SPRAY RUST PROOFING **イイ \$50.00 ×** LABOUR TO LIFT UP CARGO DECK FOR REPLACING WOODEN BOARD \$380.00 \$600 LABOUR FOR PANEL BEATING TO PUTTY & SPRAY PAINTING \$600.00 200

\$10,057.00

LK# Auto Consultants hence notify the Repairer of the following:

TOTAL:

- To resurvey the prelatter spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: