

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
GREAT AMERICAN INSURANCE COMPANY			Ref:	CS/GAI17024497/7	Γ1vbn2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date :	25-01-2018		
Code : GAI 1. Policy Particulars :- THIRD PARTY CLAIM						
1.	Insured Veh.	PUBLIC LIABILITY			SKR 1655D	
	Policy No.	T ODLIC LIABILITY	Covera	spected	0.00	
	Claim No.	CLENECR000000052	Exces		0.00	
	Assign From	JOANNA ONG	Assign		23/12/2017	
2.	Assign From	Vehicle Partic			20,12,2017	
۷.	Make & Model	TOYOTA ALTIS	c.c	Condition	1598	
	Engine No.	HIDDEN	Year o	f Pog	2015	
	Chassis No.	MR053REH104523346	Colour		BLACK	
	Odometer	57652	Steerin		IN ORDER	
	Brakes	IN ORDER	Modifi		SPORTS RIM	
	General	GOOD	Iviouiii	cation	OF ORTO TRIM	
3.	03113131					
0.	Size Make Balance					
	R/H Front Tyre	205/55 R16	DUNLO	P	6 mm	
	L/H Front Tyre	205/55 R16	DUNLO	P	6 mm	
	R/H Rear Tyre	205/55 R16	DUNLO	P	6 mm	
	L/H Rear Tyre	205/55 R16	DUNLO	P	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT,REAR PORTION,O/S BODY AND ROOFTOP.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/10/2017	Inspec	tion Date	10/01/2018	
	Survey held at	BORNEO MOTORS (S) PTE LTD				
		2 PANDAN CRESCENT SINGAPORE 128462				
5a.	Remarks					
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					