

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way,  
AIG Building #09-16  
Singapore 079120  
Attn: Motor Claims Department

*Not Authorised*  
*6/12/17*  
*Running After paint*  
*4 days*  
**ESTIMATE**

Date : 26/12/2017  
Vehicle No : SFD8376X  
Veh Make/Model : Honda Accord 2.4L  
YOM : 2008  
Chassis No : MRHCP26308P020377  
Date of Accident : 24/12/2017

| No                          | Qty | Description                                                                                             | Amount \$   |
|-----------------------------|-----|---------------------------------------------------------------------------------------------------------|-------------|
| <b>List Items:-</b>         |     |                                                                                                         |             |
| 1                           | 1   | Front bumper                                                                                            | \$ 620.50   |
| 2                           | 1   | Front bumper side retainer - RH                                                                         | \$ 18.00    |
| 3                           | 10  | Front bumper clips                                                                                      | \$ 30.00    |
| 4                           | 1   | Front bumper reinforcement                                                                              | \$ 253.90   |
| 5                           | 1   | Front grille                                                                                            | \$ 114.40   |
| 6                           | 1   | Front grille chrome                                                                                     | \$ 132.60   |
| 7                           | 6   | Front grille clips                                                                                      | \$ 22.80    |
| 8                           | 1   | Support panel                                                                                           | \$ 600.60   |
| 9                           | 1   | RH headlamp                                                                                             | \$ 621.70   |
| 10                          | 1   | Front RH fender                                                                                         | \$ 607.70   |
| 11                          | 1   | Front RH fender splash shield                                                                           | \$ 116.40   |
| 12                          | 8   | Front RH fender splash shield clips                                                                     | \$ 30.40    |
| <b>Total - List Item</b>    |     |                                                                                                         | \$ 3,169.00 |
| <b>Less 20%</b>             |     |                                                                                                         | \$ 633.80   |
| <b>Total</b>                |     |                                                                                                         | \$ 2,535.20 |
| <b>Special Nett Items:-</b> |     |                                                                                                         |             |
| 1                           | 1   | Front RH tyre                                                                                           | \$ 380.00   |
| 2                           | 1   | Front RH wheel rim                                                                                      | \$ 513.60   |
| <b>Total - SN Item</b>      |     |                                                                                                         | \$ 893.60   |
| <b>Labour Charges:-</b>     |     |                                                                                                         |             |
| 1                           |     | Spray painting on all affected area.                                                                    | \$ 1,000.00 |
| 2                           |     | Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area. | \$ 1,200.00 |
| 3                           |     | To apply anti rust treatment.                                                                           | \$ 150.00   |
| 4                           |     | To check wiring system & light.                                                                         | \$ 80.00    |
| 5                           |     | To check & adjust wheel alignment.                                                                      | \$ 120.00   |
| <b>Total - L/C</b>          |     |                                                                                                         | \$ 2,550.00 |
| <b>Sub-Total</b>            |     |                                                                                                         | \$ 5,978.80 |
| <b>7% GST</b>               |     |                                                                                                         | \$ 418.52   |
| <b>Total</b>                |     |                                                                                                         | \$ 6,397.32 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: