# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Ernest Tay Date: 29 Dec 2017

# **Preliminary Advice**

Insured Vehicle No : PA5204B

TP Vehicle No : SHC6940L Accident Date : 21/12/2017

Make : KIA OPTIMA 1.7(A) Assignment Date : 22/12/2017

Date of Inspection : 26/12/2017 Est. Duration of Repair : 2 days

Inspection At : Premier Automotive Services Pte Ltd

23 Changi South Avenue 2, #01-02

Singapore 486443

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,123.30
Revised Amount	:S\$	907.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	907.40

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: We have not authorized repairs.