



陳林摩多私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SHC5109C
Date of Accident : 22 November 2017

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Cheng Sze Ying

Date : 19 December 2017

Estimate To Repair SFJ2660H - Honda Civic 1.6L VTI Auto
Chassis No : JHMFD46208S201331

LKK
31/01/18

S/No	Quantity	Description	Amount
01		LABOUR & MISC. CHARGES	
		Putty and spray painting of n/s front fender, n/s front door, n/s rear door and n/s rear fender.	\$ 1,200.00
			\$ 1,200.00
		Total	\$ 1,200.00

700

Not Authorized
done

take photo after repair
31/1/18
2 day.

P/P \$700

Confirmed with Marcus
PBP \$700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: