

2003/2007

ASS. REC. BY:

REF: CS/MSG17024584 / Uqd35

Special Instructions

Surveyor

Marcus

ASSIGNMENT (Office)

Mennen

From (Person): Winnie Chua

of MSIG

Date/Time: 27/12/17 @ 2.41pm

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 7583 Y

Insured:

at Workshop m/s

Tan Him Motor

Tel:

6868 5151

of

51 Defu Lane 10

Policy No:

A28617679QMX

Claim No:

542294

Sum Insured:

Excess:

+ 500

Make of Veh:

D.O.A. 25/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.27pm @ 27/12/17

Person Contacted:

Sharon

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKB 7583Y - X

28/12/17 @ 3.01pm Verdict to Winnie Chua via Mennen. (pending parts prices)

28/12/17 @ 4.17pm 2nd verdict to Winnie Chua via Mennen.

28/12/17 @ 5.26pm Saw Wei informed C/A via Mennen.

28/12/17 @ 5.43pm Informed Cayman C/A to ex: \$500 by email.

REF: MSIG

MSIG

ASSIGNMENT

From: Date: 28/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKB 7583 Y
at Workshop m/s Tan Kim Motor
of 51 Dehune 10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value:

CAC Accident Report Consistent? : Yes or No

G/A PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1.3% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

21A 2x83 / 3yrs 6mth. Rep 9500

nett 14026

awaiting parts prices.

3/1/18 confirmed final by 2158.80 with million.
(Red 1250.40, 3yrs)

RECEIVED 10 JAN 2018.

Date/Time. File Pass to?

☐

Preli. Report

1) 10/1/18

☐

Final Report

Date/Time. File Return to?

2)

Report Format:

WEP-00

Lump Sum / I.B.I. (\$) 2158.80

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Ins \$

☐

Week-end \$

Survey Fee

Transportation

Photo

Other

200

10

Veh No: SKB 7583 Y Yr Regn: 6 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Hyundai Elantra 159 /

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 38593 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDH41CMCU173948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 195/55 R 15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 25/12/17

D.O.I. 28/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R.

The U/C / Chassis frame / Body Structure affected due to collision

Survey Department Check List (Case Handler)

Reference No: C9/MS4/702454/UG23
Policy Type: OD / TP / TP RES / TL / EVA

SKB 75834

Case Handler

Typist

Admin (Nivitha): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)				
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor (Nivitha): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓	
C Regn Month/Year	✓	
N Vehicle Type	✓	
N Make & Model	✓	
C Engine Capacity. (C.C)	✓	
N Colour	✓	
C Odometer. (Sp.Reading)	✓	
C Chassis No	✓	
N General Condition	✓	
N Steering	✓	
N Brake	✓	
N Modification (Modi)	✓	
C Tyre Size	✓	
N Tyre Make	✓	
C Tyre Balance	✓	
C Date of Inspection	✓	
N Survey held	✓	
N Des.of Damages	✓	

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓	
--	---	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	✓	
C Market Value for OD cases	✓	
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)		
C Days of repair	✓	
C Finalised Amount		
C Re-inspection Cases to Finalize within 5 Days		

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	✓	
---------------------------	---	--

Check By: [Signature] 10/01/18
Case Handler Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17024584/Uqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 28-12-2017	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKB 7583Y
Policy No. A28617679QMX		Coverage (\$)		0.00
Claim No. 542294		Excess (\$)		0.00
Assign From MERIMEN (WINNIE CHUA)		Assign Date		28/12/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 25/12/2017		Inspection Date 28/12/2017		
Survey held at TAN LIM MOTOR PTE LTD				
51 DEFU LANE 10				
SINGAPORE 539216				
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2017 Sendback Est	27 Dec 2017 10:34 S\$2,250.00	27 Dec 2017 14:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG BUAY HUAT, ID: S1524603J, Tel: +6596857281, Email: NOEMAIL		
Vehicle Reg. No.:	SKB7583Y	Date of Loss:	25/12/2017 19:00 - :59
Claim Type:	OD / 542294	Policy/Cover Note No.:	A28617679QMX (Comprehensive) Coverage: 25/12/2017 - 24/12/2018
		Excess:	
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/12/2017]		
Driver/Custodian:	NG BUAY HUAT (55 / Male), NRIC: S1524603J, Tel: +6596857281		
Adj Asg. Remarks:	Car in already. Please survey car by today. Please revert.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 28 December, 2017 5:43 PM
To: caymen@tlmotor.com.sg
Cc: SUR
Subject: VEHICLE SKB 7583Y (YOUR REF: 542294)

Dear Caymen,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SKB 7583Y (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	26 Dec 2017 11:55	Cim Veh Model Changed	(200329) HYUNDAI ELANTRA 1.6 (A).		[R] Sharon Ow Lee Yong
2	26 Dec 2017 11:55	Cim Created	Reg No: SKB7583Y. Policy No: A28617679QMX. Acct Date: 2017/12/25. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Tan Lim Motor Pte Ltd (Defu). Created from SAS:MTLM17168915		[R] Sharon Ow Lee Yong
3	27 Dec 2017 10:34	Cim Submitted	2250.00.		[R] Sharon Ow Lee Yong
4	27 Dec 2017 14:41	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in already. Please survey car by today. Please revert.		[I] Winnie Chua Ping Ping
5	27 Dec 2017 14:41	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/28		[I] Winnie Chua Ping Ping
6	27 Dec 2017 14:41	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Winnie Chua Ping Ping
7	27 Dec 2017 17:21	Assignment 1st Accessed			[A] Nivitha Govindasamy
8	28 Dec 2017 14:48	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] Nivitha Govindasamy
9	28 Dec 2017 14:57	Adj Rpt Initiated			[A] SHIAU CHAN
10	28 Dec 2017 14:59	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/26		[A] SHIAU CHAN
11	28 Dec 2017 14:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/26		[A] SHIAU CHAN
12	28 Dec 2017 15:01	Adj Mandate Request	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING FOR PARTS PRICES. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
13	28 Dec 2017 16:13	Adj Mandate Request Cancelled			[A] SHIAU CHAN
14	28 Dec 2017 16:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/26		[A] SHIAU CHAN
15	28 Dec 2017 16:17	Adj Mandate Request	Cur.Req:2209.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
16	28 Dec 2017 17:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/26. Mandate Remarks: a if c		[I] Lui Siew Wei
17	28 Dec 2017 17:26	Adj Mandate Set	Approved:2209.20:a if c		[I] Lui Siew Wei

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1677499	26/12/2017 11:55	Motor	Tan Lim Motor Pte Ltd (HQ)	Tan Lim Motor Pte Ltd (Defu)	SKB7583Y		xx.xx
1680334	28/12/2017 14:57	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKB7583Y		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 28 Dec 2017

Preliminary Advice

Vehicle No : SKB7583Y
Make : HYUNDAI ELANTRA
Assignment Date : 27/12/2017
Date of Inspection : 28/12/2017
Inspection At : TAN LIM MOTOR PTE LTD (DEFU)
51 DEFU LANE 10
SINGAPORE 539216

Accident Date : 25/12/2017
Policy No. : A28617679QMX
Excess : S\$500.00
Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,409.20
Revised Amount	:S\$	2,209.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,209.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	24,831.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,169.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

12/28/2017

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 28 Dec 2017

Attn: Winnie Chua Ping Ping

Preliminary Advice

Vehicle No : SKB7583Y
Make : HYUNDAI ELANTRA
Assignment Date : 27/12/2017
Date of Inspection : 28/12/2017
Inspection At : TAN LIM MOTOR PTE LTD (DEFU)
51 DEFU LANE 10
SINGAPORE 539216

Accident Date : 25/12/2017
Policy No. : A28617679QMX
Excess : S\$500.00
Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,250.00 (LABOUR ONLY)
Revised Amount	:S\$	1,050.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,050.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	24,831.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,169.00

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
PENDING FOR PARTS PRICES.
WE HAVE NOT AUTHORISE REPAIR.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 11:14
Date Of Accident	25/12/2017 19:15
Exact Location Of Accident	MSCP OF BLOCK 712A ANG MO KIO CENTRAL 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB7583Y
Insured/Policyholder	
Name Of Registered Owner	NG BUAY HUAT
NRIC No	S1524603J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96857281
Alternative Phone No	OFFICE-96857281

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28617679 QMX
Cover Note Number	

Driver

Name of Driver	NG BUAY HUAT
NRIC No	S1524603J
Date Of Birth	16/07/1962
Occupation	INDOOR
Date Of Driving Pass	22/05/1980
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96857281
Fax Number	
Contact Number	OFFICE-96857281
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 26/12/17


Driver's Signature
(If driver is not the policyholder)
Date & Time: 26/12/17 @ 11:25h


Reporting Centre Personnel's Signature
Name: Sharon
NRIC/FIN No.: S72671408H

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4603J
Vehicle Details	
Vehicle No.:	SKB7583Y
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	G4FGBU237916
Chassis No.:	KMHDH41CMCU173948
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$11,215.00
Original Registration Date:	25 Jun 2011
First Registration Date:	25 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$11,215.00 <i>5607</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2021
PARF Rebate Amount:	\$7,289.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,244.00
COE Rebate Amount:	\$17,542.00
Total Rebate Amount:	\$24,831.00

The information contained herein is correct as at 28 Dec 2017

OK

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKB7583Y
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Chassis No. :	KMHDH41CMCU173948
Propellant :	Petrol
Engine No. :	G4FGBU237916
Engine Capacity :	1591 cc
Maximum Power Output :	95.6 kW (128 bhp)
Maximum Laden Weight :	1680 kg
Unladen Weight :	1267 kg
Year Of Manufacture :	2011
Original Registration Date :	25 Jun 2011
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$50,244.00
COE Expiry Date :	24 Jun 2021
Road Tax Expiry Date :	24 Jun 2018
PARF Eligibility Expiry Date :	24 Jun 2021
Inspection Due Date :	24 Jun 2018

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS
SGCARMART
APP DOWNLOAD

All Car Make or Model Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

A-Assurance
 Assurance in Insurance

Car Insurance Expiring?
 We get you the cheapest insurance renewal

Click to get quote


 Username / Email Add
 password Submit Q
 f Connect Sign Up New Account
 Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New Toyota C-HR Hybrid 1.8A G.


 Immediate COE Registration.
 New Unregistered. 3 Days
 Delivery! Hurry Book Now!
 Apex Trading Pte Ltd StarAd

PRIME MOTOR & LEASING

 With over 200 units of vehicles
 to choose from, ranging from
 all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

13 vehicles

Hyundai Elantra

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Elantra		Any	Any	2011	Any	Any	Any	Available
	Hyundai Elantra	Hyundai Elantra 1.6A Elite (OPC)	\$35,700	\$8,060 /yr	26-Jul-2011	1,591 cc	80,000 km	Sedan	Available
Mint Condition Hyundai Elantra Elite Edition! Best Value Korean Luxury Sedan! High Trade In, Minimum Down Payment And Attractive Loan Packages Available! Call To Arrange For Viewing And Test Drive Now...									
Pang's Motor Trading Pte Ltd									
Posted: 26-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite	\$40,800	\$9,820 /yr	08-Jun-2011	1,591 cc	90,000 km	Sedan	Available
One Of The Best Looking Korean Made Model To Own In Town! Low Mileage Done! Stock Paintwork! Stock Condition! Full Agent Maintained! Tip Top Condition! Accident Free! Not To Be Missed! Trade In Or Hig...									
Excel Motoring									
Posted: 26-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite	\$44,700	\$10,210 /yr	14-Sep-2011	1,591 cc	124,000 km	Sedan	Available
Elegant And Beautiful Red! Very Low Mileage Done With Full Service History At Komoko Motors! Very Well Maintained By Meticulous Owner! No Modifications Done! See To Believe! Buy With A Peace Of Mind F...									
Posted: 23-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite Sunroof	\$45,800	\$9,910 /yr	18-Nov-2011	1,591 cc	86,000 km	Sedan	Available
1 Owner Only. Agent Maintained Unit. Excellent Condition. Flexible Loan Arrangement. In House Loan Available Too. Act Now.									
Posted: 23-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
Car Buying Car Selling Car Aftermarket									
Car Ownership On The Move Lifestyle Buy Tyres Online! Latest Special Offers from Tyrespac!									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite Sunroof	\$44,800	\$10,200 /yr	14-Sep-2011	1,591 cc	135,000 km	Sedan	Available
Beautiful Metallic Silver, 1 Careful Owner, Well Maintain, Seldom Used, Accident Free, Just Serviced, Undergone A 120 Points Safety Check By Our In House Mechanics Peace Of Mind! Can Loan Up To 80%. D...									
Jia Leong Trading Enterprise									
Posted: 22-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite	\$43,800	\$10,010 /yr	09-Sep-2011	1,591 cc	131,000 km	Sedan	Available
Low Down Payment, In House Finance Available, 1 Owner, Owner Upgrading, Very Good Fuel Efficient, Sporty Luxury Look No, Contact Us For Further Viewing Now.									
Posted: 22-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									
	Hyundai Elantra	Hyundai Elantra 1.6A Elite	\$41,800	\$10,180 /yr	18-Jul-2011	1,591 cc	71,000 km	Sedan	Available
Beautiful Metallic Navy Blue, 1 Careful Owner, Well Maintained By Previous Owner And Agent Maintained. Very Spacious And Big Boot Space. Ideal For Those Who Fancy Spacious And Comfort Interior Yet Pow...									
Posted: 22-Dec-2017 Tags: 2011 Hyundai Elantra, 2011 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai									

Compare



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD012122017
Policy No:	A28617679QMX	Date of Loss:	25/12/2017
Vehicle Reg. No.:	SKB7583Y	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG BUAY HUAT	Contact No:	+6596857281
Driver:	NG BUAY HUAT		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	25/06/2011
Vehicle Colour:	Blue	Chassis No:	KMHDH41CMCU173948
Engine No:	G4FGBU237916		
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	25/12/2017 @ 1915HRS. WHILE REVERSING INTO A PARKING LOT, ACCIDENTALLY HIT ONTO A PILLAR ON MY RIGHT.		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

Not Admitted
due to negligent behaviour
4 Ly. 28/12/17 Excess?
28/12/17 Crown

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	2,250.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	2,250.00
- Excess (S\$)	500.00
(S\$)	1,750.00
+ GST 7.00% (S\$)	122.50
Nett Amount (S\$)	1,872.50

This claim is handled by: SHARON OW LEE YONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2017)
 Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SKB7583Y/27/12/2017 10:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*o/s front fender 3.5m ✓	0.00	0.00	160 -
2	1		*o/s front fender inner cowling 11 9	0.00	0.00	-
3	1		*o/s front fender inner cowling clip 11 X	0.00	0.00	-
4	1		*o/s front fender air guide rear 11 X	0.00	0.00	-
5	1		*o/s front fender air guide rear clip 11 X	0.00	0.00	-
6	1		*o/s front door 3.5m ✓	0.00	0.00	390 -
7	1		*o/s front door hinge top Buy ✓	0.00	0.00	25 -
8	1		*o/s front door hinge bottom Buy ✓	0.00	0.00	25 -
9	1		*o/s front door checker / arrestor 11 ✓	0.00	0.00	28 -
10	1		*o/s front door window glass channel weatherstrip 11 X	0.00	0.00	-
11	1		*o/s front door outer weatherstrip moulding 11 X	0.00	0.00	-
12	1		*o/s front door side mirror - glass } 3.5m ✓	0.00	0.00	380 -
13	1		*o/s front door side mirror - cover }	0.00	0.00	-
14	1		*o/s front door side mirror - motor assy }	0.00	0.00	-
15	1		*o/s front door power window motor 11 X	0.00	0.00	-
16	1		*o/s front door regulator 11 X	0.00	0.00	-
17	1		*o/s front door weatherstrip 11 X	0.00	0.00	-
18	1		*o/s front door inner trimboard 11 X	0.00	0.00	-
19	1		*o/s front door inner lock 11 X	0.00	0.00	-
20	1		*o/s front door inner lock stricker 11 X	0.00	0.00	-
21	1		*o/s front door visor 11 X	0.00	0.00	-
22	1		*o/s rocker panel 11 X	0.00	0.00	-
23	1		*o/s front windscreen shield A pillar 11 X	0.00	0.00	-
24	1		*o/s front door window frame malt black sticker 11 X	0.00	0.00	-
Sub Total (\$\$)						0.00
+ Margin on L,N Items 15.00% (\$\$)						0.00
Total Parts (\$\$)						0.00

Tan Lim Motor Pte Ltd/SKB7583Y/27/12/2017 10:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1008
 11088
 2158.80

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check steering geometry and computer wheel alignment.	New 11	120.00 X
2	To rust-proofing of the affected areas.	New 11	80.00 X
3	To perform water seepage test, windnoise and test-drive.	New 11	250.00 X
4	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 450	950.00
5	Putty and spray painting of the affected portion.	New 600	850.00
Gross Labour Cost (\$\$)			2,250.00

Tan Lim Motor Pte Ltd/SKB7583Y/27/12/2017 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

1050

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3409.00



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail: info@minghee.com

Website: http://www.minghee.com

TAX INVOICE

INV NO : 8092303

DATE	28/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Oh Meng Heng
CUSTOMER REF.		OUR REF.	50299

CO REG NO. 198905613E

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ROUTE
UBI2

TIME: 11:34

ACCOUNT NUMBER:

TAN LIM MOTOR PTE LTD

51, DEFU LANE 10,

SINGAPORE 539216

539216

Telephone No : 68585151,

DELIVER TO:

TAN LIM MOTOR PTE LTD

51, DEFU LANE 10,

SINGAPORE 539216

SKB7583Y=====HUA



PART NO.	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HY87620-3X080	1L-14F	1 PC	380.00	380.00

PARTICULARS

MIRROR ASSY, DR RH

Exclusive Distributor

HDK

C.V. JOINT
MADE IN JAPAN

Stockists

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL

BEAR INTEREST AT JOB'S PREVAILING

LENDING RATE

*CASH INVOICE MUST BE

PAID WITHIN 7 DAYS

FROM DATE OF INVOICE

TOTAL

SIN

380.00

ADD GST

7%

26.60

AMOUNT DUE

SIN

406.60

SIGN & COMPANY'S STAMP



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司

MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092269

DATE	28/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Oh Meng Heng
CUSTOMER REF.		OUR REF.	50174

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER:

TAN LIM MOTOR PTE LTD

51, DEFU LANE 10,

SINGAPORE 539216

ROUTE

UB11

DELIVER TO:

TAN LIM MOTOR PTE LTD

51, DEFU LANE 10,

SINGAPORE 539216

>>>SKB7583Y-----HUA



539216

Telephone No : 68585151,

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HY66321-3X000	FENDER, FR RH	3G-05C	1 PC	160.00	160.00
2 HY76004-3X500	PANEL ASSY-FR DR RH	3G-02A	1 PC	390.00	390.00
3 HY79320-2E000 H	HINGE, DR UPR RH	1L-02B	1 PC	25.00	25.00
4 HY79420-3K000 H	HINGE ASSYRR DR UPR RH	1L-03B	1 PC	25.00	25.00
5 HY87620-3X060	MIRROR ASSY, DR RH	1L-04H	1 PC	175.00	175.00

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT UOB'S PREVAILING
LENDING RATE
*CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

Exclusive Distributor

HDK

CVT-SHIFT
MADE IN JAPAN

Stockists



SIGN & COMPANY'S STAMP

GOODS RECEIVED IN GOOD ORDER
AND CONDITION

TOTAL SIN 775.00
ADD GST 7% 54.25
AMOUNT DUE SIN 829.25

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.
Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.
Tel: 6298 3888 Fax: 6297 0863 (Accounts)
E-mail : info@minghee.com
Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092280

DATE	28/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Oh Meng Heng
CUSTOMER REF.		OUR REF.	50219

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO.198905613E

ACCOUNT NUMBER:

TAN LIM MOTOR PTE LTD
51, DEFU LANE 10,
SINGAPORE 539216

Telephone No : 68585151,

539216

DELIVER TO:

TAN LIM MOTOR PTE LTD
51, DEFU LANE 10,
SINGAPORE 539216

SKB7583Y==HUA



PART NO. 1 HY79390-3X000
CHECKER ASSY-FR DOOR RH

PARTICULARS

LOC	QUANTITY	UNIT PRICE	AMOUNT
1S-01E	1 PC	28.00	28.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT LOB'S PREVAILING
LENDING RATE

*CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor



Stockists



TOTAL	SIN	28.00
ADD GST	7%	1.96
AMOUNT DUE	SIN	29.96

DATE
ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017 Sendback Est	27 Dec 2017 10:34 S\$2,250.00	27 Dec 2017 14:41 Edit Adj Rpt	S\$2,158.80 Edit Estimates	S\$2,158.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	NG BUAY HUAT, ID: S1524603J, Tel: +6596857281, Email: NOEMAIL								
Vehicle Reg. No.:	SKB7583Y	Date of Loss:	25/12/2017 19:00 - :59						
Claim Type:	OD / 542294	Policy/Cover Note No.:	A28617679QMX (Comprehensive) Coverage: 25/12/2017 - 24/12/2018						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/01/2018]								
Driver/Custodian:	NG BUAY HUAT (55 / Male), NRIC: S1524603J, Tel: +6596857281								
Adj Asg. Remarks:	Car in already. Please survey car by today. Please revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (28/12/2017): Alert - Adj Mandate Approved (S\$2209.20) - SKB7583Y - Claim Handler: Winnie Chua...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKB7583Y (542294)

OD

Dec 25 2017 7:00PM

[NG BUAY HUAT]

Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	26/12/17 11:37	Accident Statement							1 Load HTM		
2	27/12/17 10:34	Repairer Estimates							1 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	28/12/17 14:59	Adjuster Immediate Advice							1 Load HTM		
2	28/12/17 16:17	Adjuster Immediate Advice							1 Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
2	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
3	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
4	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
5	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
6	26/12/17 11:33	Accident Photo [Linked Accident Report Documents]							1 Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	28/12/17 15:51	Chassis Number							1 Load JPG	☒	
2	28/12/17 15:51	General View							1 Load JPG	☒	
3	28/12/17 15:51	General View							1 Load JPG	☒	
4	28/12/17 15:51	General View							1 Load JPG	☒	
5	28/12/17 15:51	General View							1 Load JPG	☒	
6	28/12/17 15:51	General View							1 Load JPG	☒	
7	28/12/17 15:51	General View							1 Load JPG	☒	
8	28/12/17 15:51	General View							1 Load JPG	☒	
9	28/12/17 15:51	General View							1 Load JPG	☒	
10	28/12/17 15:51	General View							1 Load JPG	☒	
11	28/12/17 15:51	General View							1 Load JPG	☒	
12	28/12/17 15:51	General View							1 Load JPG	☒	
13	28/12/17 15:51	General View							1 Load JPG	☒	
14	28/12/17 15:51	General View							1 Load JPG	☒	
15	28/12/17 15:51	General View							1 Load JPG	☒	
16	28/12/17 15:51	General View							1 Load JPG	☒	
17	28/12/17 15:51	General View							1 Load JPG	☒	
18	28/12/17 15:51	General View							1 Load JPG	☒	
19	28/12/17 15:51	General View							1 Load JPG	☒	
20	28/12/17 15:51	General View							1 Load JPG	☒	
21	28/12/17 15:51	General View							1 Load JPG	☒	

22	28/12/17 15:51	General View	1	Load JPG	☒
23	28/12/17 15:51	General View	1	Load JPG	☒
24	28/12/17 15:51	General View	1	Load JPG	☒
25	28/12/17 15:51	General View	1	Load JPG	☒
26	28/12/17 15:51	General View	1	Load JPG	☒
27	28/12/17 15:51	Odometer Reading	1	Load JPG	☒
28	28/12/17 15:51	General View	1	Load JPG	☒
29	28/12/17 15:51	General View	1	Load JPG	☒
30	28/12/17 15:51	General View	1	Load JPG	☒
31	28/12/17 15:51	General View	1	Load JPG	☒
32	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
33	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
34	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
35	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
36	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
37	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
38	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
39	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
40	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
41	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
42	10/01/18 11:25	Reinspection Photo	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)			
1	26/12/17 11:28	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	26/12/17 11:28	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	27/12/17 14:48	Drivers Driving License	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 16:20	WORKSHOP ESTIMATE	1	Load PDF	
2	28/12/17 17:18	SUPPLIER INVOICE	1	Load PDF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	26/12/17 11:37	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	26/12/17 11:33	Accident Photo	1	Load JPG	☒
2	26/12/17 11:33	Accident Photo	1	Load JPG	☒
3	26/12/17 11:33	Accident Photo	1	Load JPG	☒
4	26/12/17 11:33	Accident Photo	1	Load JPG	☒
5	26/12/17 11:33	Accident Photo	1	Load JPG	☒
6	26/12/17 11:33	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	26/12/17 11:28	Sketch Plan	1	Load TIF	
2	26/12/17 11:28	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
^ v			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17024584/UQD3S2

Date: 11/01/2018

REFERENCE

Insured/Claimant:	NG BUAY HUAT	Policy No:	A28617679QMX	Claim No:	542294
Date of Loss:	25/12/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB7583Y	Engine No:	G4FGBU237916
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMCU173948
Reg. Date:	25/06/2011 (Man. Year: 2011)	Odometer:	38593 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	1,108.80	-1,108.80	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,050.00	1,200.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,250.00	2,158.80	91.20	4.05
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	1,750.00	1,658.80	91.20	5.21
+ GST 7.00/7.00% (S\$)	122.50	116.12	6.38	5.21
Nett Amount (S\$)	1,872.50	1,774.92	97.58	5.21

INSPECTION

Date of Assignment:	27/12/2017	Present Location:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	28/12/2017	Inspected At:	Tan Lim Motor Pte Ltd (Defu)
			51 Defu Lane 10
			Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2018)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB7583Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*o/s front fender (WCP)	Badly Dented	-	*160.00 F
2	1		*o/s front fender inner cowling (NPA)(WCP)	Not Necessary	-	-
3	1		*o/s front fender inner cowling clip (NPA)(WCP)	Not Necessary	-	-
4	1		*o/s front fender air guide rear (NPA)(WCP)	Not Necessary	-	-
5	1		*o/s front fender air guide rear clip (NPA)(WCP)	Not Necessary	-	-
6	1		*o/s front door (WCP)	Badly Dented	-	*390.00 F
7	1		*o/s front door hinge top (WCP)	Bent	-	*25.00 F
8	1		*o/s front door hinge bottom (WCP)	Bent	-	*25.00 F
9	1		*o/s front door checker / arrestor (WCP)	Twisted	-	*28.00 F
10	1		*o/s front door window glass channel weatherstrip (NPA)(WCP)	Not Necessary	-	-
11	1		*o/s front door outer weatherstrip moulding (NPA)(WCP)	Not Necessary	-	-
12	1		*o/s front door side mirror - glass (WCP)	Broken	-	*380.00 F
13	1		*o/s front door side mirror - cover (WCP)	Broken	-	-
14	1		*o/s front door side mirror - motor assy (WCP)	Broken	-	-
15	1		*o/s front door power window motor (NPA)(WCP)	Not Necessary	-	-
16	1		*o/s front door regulator (NPA)(WCP)	Not Necessary	-	-
17	1		*o/s front door weatherstrip (NPA)(WCP)	Not Necessary	-	-
18	1		*o/s front door inner trimboard (NPA)(WCP)	Not Necessary	-	-
19	1		*o/s front door inner lock (NPA)(WCP)	Not Necessary	-	-
20	1		*o/s front door inner lock stricker (NPA)(WCP)	Not Necessary	-	-
21	1		*o/s front door visor (NPA)(WCP)	Not Necessary	-	-
22	1		*o/s rocker panel (NPA)(WCP)	Repair	-	-
23	1		*o/s front windscreen shield A pillar (NPA)(WCP)	Not Necessary	-	-
24	1			Not Necessary	-	-

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*o/s front door window frame malt black sticker (NPA)(WCP)			
F=Franchise part.						
Sub Total (S\$)					0.00	1,008.00
+ Margin on L,N Items 15.00/10.00% (S\$)					0.00	100.80
Total Parts (S\$)					0.00	1,108.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check steering geometry and computer wheel alignment.	New	120.00	-
2	To rust-proofing of the affected areas. (NOT INSURED)	New	80.00	-
3	To perform water seepage test, windnoise and test-drive.	New	250.00	-
4	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	950.00	450.00
5	Putty and spray painting of the affected portion.	New	850.00	600.00
Gross Labour Cost (S\$)			2,250.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >