

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: RN.deb.0725.16.AMG

Date: 20th February 2018

Our Ref: CS1/LAW17024585/T1tbn2

## M/s TAN KOK QUAN PARTNERSHIP

1 WALLICH STREET #07-02 GUOCO TOWER Singapore 078881

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

**FBJ 8980S** 

INSURED VEHICLE: BHP 812 ACCIDENT DATE: 21/02/2015

We thank you for your instruction on 15/11/2017.

We acknowledge receipt of the following documents:-

- a) Survey report of FBJ 8980S by L.H.Teo Appraisal Services.
- b) Final Repair Bill of FBJ 8980S from A.S.Phoon Pte Ltd.
- c) Singapore Accident Statement of Vehicles FBJ 8980S.
- d) Malaysia Police Report of vehicle BHP 812.
- e) Colour damaged vehicle photographs of FBJ 8980S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: FBJ 8980S

Make & Model

: Honda NC750XA

Year of Registration

: 2014

Chassis Number

: JH2RC72B2EK007640

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.