LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

8 Shenton Way #24-01 51 Ubi Ave 1 #01-25 AXA Tower Paya Ubi Industrial Park Singapore 068811 Singapore 408933

Attn: Khor Saw Theng Date: 29 Dec 2017

Preliminary Advice

Insured Vehicle No : XB7761X

TP Vehicle No : SGE5875A Accident Date : 23/12/2017

Make : HONDA CITY Assignment Date : 27/12/2017

Date of Inspection : 27/12/2017 Est. Duration of Repair : 6 days

Inspection At : Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S front body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,023.52
Revised Amount	:S\$	3,687.60
Check Items (Estimated)	:S\$	1,045.92
Total	:S\$	4,733.52

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.