

# Hiap Hong Motor Repair

Blk 2 Kaki Bukit Ave 2#02-13 Singapore 417921  
 Tel: 6745 9633 Fax: 6747 8602 Email: hiap.hong.motor@gmail.com  
 Company Reg. No. 42051700-J

Date: 26 December 2017

The Motor Claims Department  
 MSIG Insurance (Singapore) Pte Ltd  
 4 Shenton Way  
 #21-01 SGX Centre 2  
 Singapore 06887  
 Fax: +65 6225 6371

YACON

## REPAIR QUOTATION FOR SJP8168U HONDA CITY 1.5 SV CVT

	Qty	(\$)	Discount	(\$)
633-20 LH rear door <i>dent</i>	1	906.80	20%	725.44
LH rear door hinge <i>Lower Bit</i>	2	88.00	20%	70.40
LH rear door sash pillar black sticker set	1	51.80	20%	41.44
LH rear door inner lock <i>New</i>	1	252.20	20%	201.76
155-20 LH rear door glass regulator c/w motor <i>Repl</i>	1	390.20	20%	312.16
51 LH rear door weatherstrip <i>new</i>	1	112.10	20%	89.68
LH rear door checker	1	46.70	20%	37.36
LH rocker panel garnish <i>new</i>	1	420.60	20%	336.48
LH rocker panel garnish clip <i>new</i>	12	45.60	20%	36.48
656-30 LH front door <i>Dented</i>	1	906.80	20%	725.44
199-20 LH front door inner lock <i>Dented</i>	1	268.70	20%	214.96
LH front door sash pillar black sticker set	1	48.10	20%	38.48
LH front door glass regulator c/w motor <i>new</i>	1	397.20	20%	317.76
48-70 LH front door weatherstrip <i>new</i>	1	112.10	20%	89.68
LH door centre pillar <i>Repl</i>	1	615.00	20%	492.00
<b>Total Cost of parts</b>				<b>3,729.52</b>

2272 48

### LABOUR

To check door wiring and central locking system functions.

60:00 30

To remove, transfer and install front door glass.

90:00 80

To remove, transfer and install rear door glass.

90:00 80

To apply anti-rust undercoating.

150:00 50 1790

Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.

1,500:00 700

Spray painting charges to putty and spray all affected parts/areas front door, rear door, rocker panel, rear fender, door centre pillar, etc.

1,500:00 850

**Total Cost of labour** 3,390.00

**Total Repair Cost** 7,119.52

LKK Auto Consultants hence notify the Repairer of the following:  
 yours faithfully  
 • To resurvey before/after spray painting  
 • To do NOT damaged parts during resurvey  
 • Parts prices are subject to confirmation  
 • Third party claims are "Without Prejudice" basis  
 Chua Meng Liang (Signature)  
 • Supplementary claims must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lj  
 28/12/17  
 H/S 0628p

bill 406248  
 H/S 3250