

ASS. REC. BY:

REF:

CS/CTL7024632/Tigbert

Special Instruction:

Surveyor: Taufikh Masimen

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTLDate/Time: 28/12/07 5:16pm

Estimated Cost:

Bill to:

 TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 5273B

Insured:

at Workshop m/s

Sng Ah Tee Motor

Tel:

6268 6183

of

Blk 3 Pioneer Road Nuth #01-18

Policy No:

DMCVSN 303 2291702

Claim No:

2017 0001921 - SUM 17007283col

Sum Insured:

Excess:

\$0 2000

Make of Veh:

(Client's Record)

D.O.A.

21-12-2017CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/12/07 5:37pm

Person Contacted:

SamanthaVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>YN 5273B - X</u>
<u>29/12/17 @ 2.57pm</u>	<u>revert to Chong Boon Sen via Masimen.</u>
<u>07/11/18 @ 4.06pm</u>	<u>M/iced informed C/A S Exp: \$ 2000 via Masimen</u>
<u>07/11/18 @ 11.23am</u>	<u>informed Samantha C/A S Exp: \$ 2000 by email.</u>

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 40
 (Client's Record)
 Make of Veh: _____

Veh No: YN5273B Yr Regn: 2014 May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi Canter FEB21 c.c. 2998
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: — T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FEB21CA00016
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/85R15
 R: — (D)

X	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Bal. or Market Value: \$73K. * Freezer Truck
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 8 mm R/Bal. 8/8 mm
 L/Bal. 8 mm L/Bal. 8/8 mm
 D.O.A. _____ D.O.I. 28/12/17 @ 1750
 Survey held at: Sing Wh Tee
 Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction * Battery weak
4/5 @ 7950, 7 days, e-mail to Shouou. (Red to 4470.05, 36%)

RECEIVED 16 JUL 2018

Date/Time. File Pass to? : Preli. Report
11/6/18 : Final Report
 Date/Time. File Return to? _____

Days Of Repair: 7
 Resurvey No. of Trip: 1

Report Format: MEK-00
 Lump Sum / I.B. (\$) 7950

Add Fee: Site Insp (\$))
 Interview (\$))
 Tech. Invs (\$))
 Weekend (\$))

Survey Fee:	220
Transportation:	
Photos:	
Others:	
TOTAL	220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17024632/T1qb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-12-2017



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 5273B
Policy No.	DMCVSN3032291702	Coverage (\$)	0.00
Claim No.	20170001921	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/12/2017	Inspection Date	28/12/2017
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2017 15:28 Sendback Est	28 Dec 2017 15:38 S\$12,420.05	28 Dec 2017 17:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	AH BEE FROZEN FOOD, Co. Reg. No.: 07127700E		
Vehicle Reg. No.:	YN5273B	Date of Loss:	21/12/2017 09:00 - :59
Claim Type:	OD / 20170001921	Policy/Cover Note No.:	DMCVSN3032291702 (Comprehensive) Coverage: 30/05/2017 - 29/05/2018
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/01/2018]		
Driver/Custodian:	CHIA SONG PUAY (60 / Male), NRIC: S1203190D, Tel: +6596166364		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, 16 July 2018 10:45 AM
To: Taufikh (LKKAuto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: YN5273B - FINALISE

Hi

confirm.
thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Monday, July 16, 2018 10:00 AM
To: 'Sharon Sng'
Cc: 'Shiau Chan (LKKAuto)'
Subject: RE: YN5273B - FINALISE

Hi Sharon,

COR I/s\$7950 , 7 days.

Regards
Taufikh
Lkk Auto

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Wednesday, 13 June 2018 5:45 PM
To: 'Shiau Chan (LKKAuto)'; 'Taufikh (LKK Auto)'
Subject: FW: YN5273B - FINALISE

REMINDER

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Saturday, May 5, 2018 3:20 PM
To: 'Taufikh (LKK Auto)'
Subject: YN5273B - FINALISE

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 3 January, 2018 11:33 AM
To: SAMANTHA TAN
Cc: SUR; Sharon Sng
Subject: VEHICLE YN 5273B (DOA: 21/12/2017)

Dear Samantha,

As instructed by our client, please proceed to repair the insured vehicle YN 5273B. (excess \$2,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	27 Dec 2017 15:22	Clim Veh Model Changed	(203313) MITSUBISHI CANTER 3.0 D FEB21 (M).	[R] Samantha Tan
2	27 Dec 2017 15:22	Clim Created	Reg No: YN5273B. Policy No: DMCVSN3032291702. Acct Date: 2017/12/21. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer). Created from SAS:MSAT17167525	[R] Samantha Tan
3	28 Dec 2017 15:38	Clim Submitted	12420.05.	[R] Samantha Tan
4	28 Dec 2017 17:16	Clim Registration Modified	Excess: -> 2000.00.	[I] Chong Boon Sen
5	28 Dec 2017 17:16	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
6	28 Dec 2017 17:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/09	[I] Chong Boon Sen
7	28 Dec 2017 17:16	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
8	28 Dec 2017 17:16	Clim Registration Modified	Excess: 2000.00 -> 0.00.	[I] Chong Boon Sen
9	28 Dec 2017 17:36	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
10	28 Dec 2017 17:45	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
11	29 Dec 2017 14:48	Adj Rpt Initiated		[A] SHIAU CHAN
12	29 Dec 2017 14:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/09	[A] SHIAU CHAN
13	29 Dec 2017 14:56	Adj Mandate Request	Cur.Reg:11690.05:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	02 Jan 2018 16:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/09. Mandate Remarks: PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$11,690.05. RE-INSPECTION OF VEHICLE REQUIRED. Excess is WAIVED.	[I] Alfred Toh
15	02 Jan 2018 16:03	Adj Mandate Set	Approved:11690.05:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$11,690.05. RE-INSPECTION OF VEHICLE REQUIRED. Excess is WAIVED.Reinsp:Adj decides.	[I] Alfred Toh
16	02 Jan 2018 16:06	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/01/09. Mandate Remarks: PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$11,690.05.BEFORE EXCESS OF \$2,000.00. RE-INSPECTION OF VEHICLE REQUIRED	[I] Alfred Toh
17	02 Jan 2018 16:06	Adj Mandate Set	Approved:11690.05:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$11,690.05.BEFORE EXCESS OF \$2,000.00. RE-INSPECTION OF VEHICLE REQUIRED	[I] Alfred Toh
18	02 Jan 2018 16:06	Clim Registration Modified	Excess: 0.00 -> 2000.00.	[I] Alfred Toh

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1679290	27/12/2017 15:22	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	YN5273B		xx.xx
1681352	29/12/2017 14:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	YN5273B		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: YN5273B	Accident Date	: 21/12/2017
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3032291702
Assignment Date	: 28/12/2017	Excess	: S\$0.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 7.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,420.05
Revised Amount	:S\$	7,584.80
Check Items (Estimated)	:S\$	4,105.25
Total	:S\$	11,690.05

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	3,207.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,793.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7700E
Vehicle Details	
Vehicle No.:	YN5273B
Vehicle to be Exported:	No
Intended De-registration Date:	31 Dec 2017
Vehicle Make:	MINI
Vehicle Model:	CANTER FEB21CR3SDEB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4P10B00838
Chassis No.:	FEB21CA00016
Maximum Power Output:	-
Open Market Value:	\$28,936.00
Original Registration Date:	30 May 2014
First Registration Date:	30 May 2014
Transfer Count:	0
Actual ARF Paid:	\$1,447.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,003.00
COE Rebate Amount:	\$3,207.00
Total Rebate Amount:	\$3,207.00

The information contained herein is correct as at 22 Dec 2017

OK



Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Username / Email Add
password
Connect Sign Up New Account
Forgot Password

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Year Coe 2008 Toyota Altis 1.6A



\$2500 Downpayment Monthly
From \$688 Onwards, Lowest
3.68%P.A@Gv Cars Financing.
GV Credit Pte Ltd StarAd

AutoInn
An Inspiration For Car Buyers
click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

MITSUBISHI FEB21

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MITSUBISHI FEB21	Any	Any	2014	Any	Any	Any	Available
	Mitsubishi Fuso Canter FEB21	\$59,800	\$9,500 /yr	14-Apr-2014	2,998 cc	41,000 km	Truck	Available
Fuel Type: Diesel Almost New Mitsubishi FEB21! No VPC Needed! Class 3 License Allowed! New Paint, Only Require Class 3 License. High Loan, High Trade-In! Call Us To Arrange For A Viewing! ABWIN (1994) Pte Ltd Posted: 28-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
	Mitsubishi Fuso Canter FEB21	\$62,800	\$9,260 /yr	10-Oct-2014	2,998 cc	-	Truck	Available
Fuel Type: Diesel Tip Top Condition 15Ft Wooden Deck, Power Engine, Powerful Aircon, New Paint Work, No Repair Needed, High Trade And Up To 100% Loan, Call Now For Viewing And Test Drive. Car (S) Pte Ltd Posted: 28-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
	Mitsubishi Fuso Canter FEB21	\$59,800	\$9,140 /yr	15-Jul-2014	2,998 cc	-	Truck	Available
Fuel Type: Diesel High Trade-in And Flexible Loan Available. So Call For Test Drive Appointment Today Posted: 27-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
	Mitsubishi Fuso Canter FEB21	\$76,800	\$11,810 /yr	30-Jun-2014	2,998 cc	-	Truck	Available
Fuel Type: Diesel Class 3 With 14 Feet Freezer Truck. Well Taken Care By Owner. Posted: 26-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
Car Buying	Car Selling	Car Aftermarket						
Car Ownership	On The Move	Lifestyle						
	Mitsubishi Fuso Canter FEB21	-	N.A	23-Dec-2014	2,998 cc	6,016 km	Truck	Available
Fuel Type: Diesel Auction Closing Time: 31st Dec 2017 at 11:00 PM Non GST Registered. 1 Key Available. Road Tax Expiry On 22/12/2017. Mileage Of 6016Km. Financing Up To 100% Possible Subject To Credit Approval. Call Us To Enquire. Posted: 20-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
	Mitsubishi Fuso Canter FEB21	\$62,800	\$10,200 /yr	24-Feb-2014	2,998 cc	-	Truck	Available
Fuel Type: Diesel High COE Paper! Mitsubishi Canter Feb 21 14ft Truck, Manual Transmission Condition As Good As New, Full Canopy With Checker Plate. Non VPC And Wooden Base. Goods And Labour Transportation. Test Drive ... ABWIN (1994) Pte Ltd Posted: 19-Dec-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi								
Mitsubishi Fuso Canter FEB21	\$61,500	\$9,790 /yr	11-Apr-2014	2,998 cc	150,900 km	Truck	Available	ae: Diesel



Think One Automobile & Trading

Posted: 13-Dec-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi



Mitsubishi Fuso Canter FEB21
Fuel Type: Diesel

\$61,500

\$9,790 /yr

11-Apr-2014

2,998 cc

91,589 km

Truck

Available

Think One Automobile & Trading

Posted: 12-Dec-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21
Fuel Type: Diesel

\$59,800

\$9,130 /yr

18-Jul-2014

2,998 cc

-

Truck

Available

No Need For VPCI Class 3 Can Drive! Negotiable! High Loan Low Interest! Call Fast For An No Obligation Discussion!

Net Link Partners Pte Ltd

Posted: 11-Dec-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21
Fuel Type: Diesel

\$66,800

\$10,110 /yr

07-Aug-2014

2,998 cc

-

Truck

Available

Near New Condition Complete With Retractable Canopy,high Loan 100% Available

Posted: 06-Nov-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21
Fuel Type: Diesel

\$62,500

\$9,270 /yr

24-Sep-2014

2,998 cc

45,800 km

Truck

Available

14 Feet Lorry With Box. Vehicle In Good Condition Inside Out. No Repairs Needed, Well Maintained, Full Service Records. Low Mileage. Low Deprecation! Call Now To Arrange Viewing.

Posted: 02-Nov-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi

Details

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used MITSUBISHI FEB21, MITSUBISHI FEB21 Singapore, used MITSUBISHI FEB21 Singapore, used MITSUBISHI FEB21, used vehicles Singapore or even buy used MITSUBISHI FEB21 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement



LIFESTYLE TIPS FOR A HEALTHY LIFESTYLE
» Your guide to healthcare, food, homes, property and many more!

Username / Email Add
password
Connect » Sign Up New Account » Forgot Password

MITSUBISHI FEB21 Price Range Depreciation 2014 Vehicle Type Advanced Search

Home » Used Cars » OK2 Pte Ltd » Mitsubishi Fuso Canter FEB21

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Rental
For Private & Commercial Vehicles
Rental From **\$50/Day**



Mitsubishi Fuso Canter FEB21

Overview Financial Accessories Similar Research Photos Map PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$76,800	
Depreciation	\$11,810 /yr	?
	View models with similar depreciation	
Reg Date	30-Jun-2014	
	(6yrs 6mths COE left)	
Manufactured	2013	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,998 cc	
Curb Weight	2,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Class 3 With 14 Feet Freezer Truck. Well Taken Care By Owner.	
COE	\$53,891	?
OMV	\$29,262	?
ARF	\$1,464	?
Dereg Value	\$35,051 as of today (change)	?
No. of Owners	2	?
Type of Veh	Truck	
Category	Premium Ad Car	
Availability	Available	PREMIUM AD

Add to Shortlist Add to Compare Add a Note

Posted on: 26-Dec-2017 | Last Updated on: 26-Dec-2017

Tags: Mitsubishi Fuso, Mitsubishi Fuso, 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi

Upfront Payment [» more Financial info](#)


Transfer Fee	\$25		?
Down Payment	\$7,680 (change)	Maximum 90% Loan	?
1st Instalment	\$1,082		?
Total Upfront Payment	\$8,787 (excluding insurance)		?

Estimates based on 90% loan at 3.4% interest rate. Check with seller for exact figure.

Items for Mitsubishi Fuso [» View All](#)

	Wheel Cylinder Sb Wc23122r \$109		Wheel Cylinder Sb Wc23055r \$109
--	--	--	--

Compare



Price Analysis

Seller Information

Company	OK2 Pte Ltd » dealer's pricelist » 21 vehs sold 66 vehs available
Address	68 Kaki Bukit Avenue 6 #02-20 Search cars nearby this location
Location	Ark @ KB
Office No	67457076
Contact Person(s)	KK Ong 90054103 Yong 82336292 Wee 94888998


Useful Services

STA VEHICLE INSPECTION
Make sure of this car condition with STA Evaluation.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

	Reverse Camera From \$400		Wheel Cylinder Sb Wc23056r \$109
	Bidded Carplate For Sale \$45,000	View All	

Hua Kian Motor Workshop is a specialist workshop for Commercial Vehicles.

Similar New Cars	Similar Cars For Lease	Similar Used Cars
		
Mitsubishi Fuso Canter (PI) From : \$97,000		Mitsubishi Fuso Canter (PI) From : \$100,000

Recommended for you

1-6 of 18



The Macallan Quest Collection for Global Travel Retail



Peugeot 3008 is a chic and slick crossover



Five ways to properly wash your car



KATC Autotrans offers added car assurance



Looking after your car's cooling system



Two ERP gantries to charge \$1 more

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/12/2017 10:24
Date Of Accident	21/12/2017 09:15
Exact Location Of Accident	WEST COAST HIGHWAY BETWEEN L/P 59 & 61
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN5273B
Insured/Policyholder	
Name Of Registered Owner	AH BEE FROZEN FOOD
Co Reg No	07127700E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96166364
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21CR3SDEB
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3032291702
Cover Note Number	

Driver

Name of Driver	CHIA SONG PUAY
NRIC No	S1203190D
Date Of Birth	29/12/1956
Occupation	OUTDOOR
Date Of Driving Pass	25/05/2011
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96166364
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 133 LORONG AH SOO #09-430
Postcode	530133
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 21/12/2017 AT AROUND 0915HRS, I WAS TRAVELLING ALONG WEST COAST HIGHWAY TOWARDS JURONG AND I WAS ON EXTREME RIGHT 1ST LANE. WHILE DRIVING SUDDENLY I NOTICES VEHICLE IN FRONT WAS STOP THEN I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO VEHICLE B REAR PORTION .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK2608X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EDWARD C C CHOW
NRIC/Passport Number	S6967965Z
Contact Number	91718288
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to ACCIDENT CIRCUMSTANCES

Claim own policy
 Claim third party
 Claim OD / TP at other works hop _____
 For record purpose
 Policy No. DWCVSN303291702
 Insurer CHINA Veh.No. 4N5273B

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3032291702	Date of Loss:	21/12/2017
Vehicle Reg. No.:	YN5273B	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AH BEE FROZEN FOOD		
Driver:	CHIA SONG PUAY		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21 (M)	Vehicle Reg. Date:	30/05/2014
Vehicle Colour:	WHITE		
Engine No:	30052014	Chassis No:	FEB21CA00016
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Description of Accident/Loss: ON 21/12/2017 AT AROUND 0915HRS, I WAS TRAVELLING ALONG WEST COAST HIGHWAY TOWARDS JURONG AND I WAS ON EXTREME RIGHT 1ST LANE. WHILE DRIVING SUDDENLY I NOTICES VEHICLE IN FRONT WAS STOP THEN I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO VEHICLE B REAR PORTION .

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	9,560.05
Miscellaneous Items	0.00
Labour	2,860.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,420.05
+ GST 7.00% (S\$)	869.40
Nett Amount (S\$)	13,289.45

This claim is handled by: **SAMANTHA TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjung 97495749
Revert
Ex \$ 0
28/12/17 @ 1750.
Lump sum
Resurvey after repair
7 days.
Sun @ lkkauto.com

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Dec 2017)**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YN5273B)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt *550.00 F
3	2		*FRT BUMPER SIDE GARNISH	0.00	0.00	mis *360.00 F
4	2		*FRT BUMPER BRACKET	0.00	0.00	bt *220.00 F
5	1		*FRT GRILLE	0.00	0.00	con *580.00 F
6	1		*FRT GRILLE CENTER RETAINER	0.00	0.00	bt *17.00 F
7	1		*FRT HORN COVER	0.00	0.00	bt *100.00 F
8	1		*FRT HORN	0.00	0.00	bt *90.00 F
9	1		*FRT HEATER PIPE	0.00	0.00	? *80.00 F X n
10	10		*FRT GRILLE CLIP	0.00	0.00	con *50.00 F
11	1		*FRT PANEL COMPLETE	0.00	0.00	bt *1,400.00 F
12	1		*FRT PANEL FUSO LOGO	0.00	0.00	con *70.00 F
13	2		*FRT CORNER PANEL LH - con, RH - X n	0.00	0.00	con *520.00 F 260
14	6		*FRT CORNER PANEL CLIP	0.00	0.00	con *24.00 F
15	2		*FRT HEADLAMP	0.00	0.00	con *680.00 F
16	2		*FRT SIGNAL LAMP	0.00	0.00	con *300.00 F
17	1		*FRT WIPER GARNISH	0.00	0.00	? *820.00 F X n
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	mis *35.00 F
19	1		*FRT WINDSCREEN RUBBER	0.00	0.00	con *260.00 F
20	1		*ERP BRACKET	0	0.00	con *26.00 FS X
21	1		*FRT AIR CON HIGH PRESSURE PIPE	0.00	0.00	? *95.00 F X n
22	1		*FRT AIR CON LOWER PRESSURE PIPE	0.00	0.00	bt *180.00 F
23	1		*AIR CON BLOWER ASSY	0.00	0.00	? *2,150.00 F con
24	1		*AIR INTAKE BOX	0.00	0.00	? *480.00 F X n

F=Franchise part. S=SpcNett.

Sub Total (S\$)	9,107.00
+ Margin on L,N Items 5.00% (S\$)	453.05
Total Parts (S\$)	9,560.05

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK STRAIGHTEN FRT CHASSIS FRAME,WELD,REMOVE & FIX ON ABOVE PARTS	New	1,400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00
3	TO REMOVE & REFIX FRT WINDSCREEN	New	100.00
4	TO REFILL AIRCON GAS	New	100.00
5	.TO REMOVE & REFIX FRT DASHBOARD	New	180.00
6	TO REMOVE & REFIX FLOORMAT	New	80.00
Gross Labour Cost (S\$)			2,860.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3032291702	Date of Loss:	21/12/2017
Vehicle Reg. No.:	YN5273B	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AH BEE FROZEN FOOD		
Driver:	CHIA SONG PUAY		
Make/Model:	mitsubishi canter, 3.0 D FEB21 (M)	Vehicle Reg. Date:	30/05/2014
Vehicle Colour:	WHITE	Chassis No:	FEB21CA00016
Engine No:	30052014		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	ON 21/12/2017 AT AROUND 0915HRS, I WAS TRAVELLING ALONG WEST COAST HIGHWAY TOWARDS JURONG AND I WAS ON EXTREME RIGHT 1ST LANE. WHILE DRIVING SUDDENLY I NOTICES VEHICLE IN FRONT WAS STOP THEN I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO VEHICLE B REAR PORTION .		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS		Amount
Parts		9,560.05
Miscellaneous Items		0.00
Labour		2,860.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	12,420.05
	+ GST 7.00% (S\$)	869.40
	Nett Amount (S\$)	13,289.45

This claim is handled by: **SAMANTHA TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanpin 97495749
Revert
Ex \$ 0
21/12/17 @ 1750.
Lump sum
Resumy after repair
7 days.
Sun @ khanto.com

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Dec 2017)
Parts: N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YN5273B)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt ✓ *20.00 PS
2	1		*FRT BUMPER	0.00	0.00	bt ✓ *550.00 F/
3	2		*FRT BUMPER SIDE GARNISH	0.00	0.00	mis ✓ *360.00 F/
4	2		*FRT BUMPER BRACKET	0.00	0.00	bt ✓ *220.00 F/
5	1		*FRT GRILLE	0.00	0.00	con ✓ *580.00 F/
6	1		*FRT GRILLE CENTER RETAINER	0.00	0.00	bt ✓ *17.00 F/
7	1		*FRT HORN COVER	0.00	0.00	bt ✓ *100.00 F/
8	1		*FRT HORN	0.00	0.00	bt ✓ *90.00 F/
9	1		*FRT HEATER PIPE	0.00	0.00	? *80.00 FX
10	10		*FRT GRILLE CLIP	0.00	0.00	acc ✓ *50.00 F/
11	1		*FRT PANEL COMPLETE	0.00	0.00	bt ✓ *1,400.00 F/
12	1		*FRT PANEL FUSO LOGO	0.00	0.00	acc ✓ *70.00 F/
13	2		*FRT CORNER PANEL LH - con, RH - ?	0.00	0.00	con ✓ *520.00 F/ (\$76)
14	6		*FRT CORNER PANEL CLIP	0.00	0.00	acc ✓ *24.00 F/
15	2		*FRT HEADLAMP	0.00	0.00	con ✓ *680.00 F/
16	2		*FRT SIGNAL LAMP	0.00	0.00	con ✓ *300.00 F/
17	1		*FRT WIPER GARNISH	0.00	0.00	? *820.00 FX
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	mis ✓ *35.00 F/
19	1		*FRT WINDSCREEN RUBBER	0.00	0.00	acc ✓ *260.00 F/
20	1		*ERP BRACKET	0	0.00	? *26.00 PS
21	1		*FRT AIR CON HIGH PRESSURE PIPE	0.00	0.00	? *95.00 FX
22	1		*FRT AIR CON LOWER PRESSURE PIPE	0.00	0.00	bt ✓ *180.00 F/
23	1		*AIR CON BLOWER ASSY	0.00	0.00	? *2,150.00 F/ photo
24	1		*AIR INTAKE BOX	0.00	0.00	? *480.00 FX

F=Franchise part, S=SpcNett.

Sub Total (S\$)	\$7326.00	9,107.00
+ Margin on L,N Items 5.00% (S\$)	add 5% = \$3692.30	453.05
Total Parts (S\$)	Swell \$46.00	9,560.05

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK STRAIGHTEN FRT CHASSIS FRAME,WELD,REMOVE & FIX ON ABOVE PARTS	New	1,400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00
3	TO REMOVE & REFIX FRT WINDSCREEN	New	100.00
4	TO REFILL AIRCON GAS	New	100.00
5	.TO REMOVE & REFIX FRT DASHBOARD	New	180.00
6	TO REMOVE & REFIX FLOORMAT	New	80.00
Gross Labour Cost (\$\$)			2,860.00

↑ CHASSIS. \$1100 ✓
 * 2900
 800 ✓
 ✓
 ✓
 ✓
 50.
 2330

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$10068.30
 less 20% = \$8054.64
 ≈ \$8050/-
 Lnp sum
 ok? 1/15 permf.
 Shann S/S 2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2017 Sendback Est	28 Dec 2017 15:38 S\$12,420.05	28 Dec 2017 17:16 Edit Adj Rpt	S\$7,950.00 Edit Estimates	S\$7,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	AH BEE FROZEN FOOD , Co. Reg. No.: 07127700E		
Vehicle Reg. No.:	YN5273B	Date of Loss:	21/12/2017 09:00 - :59 [42 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM17D07283C01	Policy/Cover Note No.:	DMCVSN3032291702 (Comprehensive) Coverage: 30/05/2017 - 29/05/2018
		Excess:	S\$2,000.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Bk3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/01/2018]		
Driver/Custodian:	CHIA SONG PUAY (60 / Male), NRIC: S1203190D, Tel: +6596166364		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> CHINA_TAIPING (02/01/2018): Alert - Adj Mandate Approved (S\$11690.05) - YN5273B - Claim Handler: Chong Boon ... CHINA_TAIPING (02/01/2018): Alert - Adj Mandate Approved (S\$11690.05) - YN5273B - Claim Handler: Chong Boon ... 		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

YN5273B (SNM17D07283C01)
OD
Dec 21 2017 9:00AM
[AH BEE FROZEN FOOD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View In Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	22/12/17 09:55	Accident Statement					Load HTM		
2	28/12/17 15:38	Repairer Estimates					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	29/12/17 14:54	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
2	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
3	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
4	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
5	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
6	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
7	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
8	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
9	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
10	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
11	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
12	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
13	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
14	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
15	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
16	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
17	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
18	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
19	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
20	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
21	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
22	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
23	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
24	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail Print
25	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
26	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
27	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
28	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
29	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
30	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
31	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
32	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
33	22/12/17 09:54	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
2	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
3	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
4	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
5	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
6	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
7	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
8	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
9	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
10	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
11	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
12	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
13	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
14	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
15	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
16	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
17	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
18	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
19	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
20	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
21	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
22	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
23	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
24	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
25	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
26	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
27	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
28	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
29	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
30	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
31	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
32	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
33	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
34	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
35	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
36	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>
37	16/07/18 12:02	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
38	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
39	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
40	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
41	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
42	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
43	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
44	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
45	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
46	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
47	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
48	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
49	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
50	16/07/18 12:02	General View	Load JPG	<input checked="" type="checkbox"/>
51	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	16/07/18 12:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/12/17 09:54	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	22/12/17 09:55	CI,IC,DL [Linked Accident Report Documents]	Load TIF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 14:55	WORKSHOP ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/12/17 09:55	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	22/12/17 09:54	Accident Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
				<input checked="" type="checkbox"/>
7	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
23	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
24	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
25	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
26	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
27	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
28	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
29	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
30	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
31	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
32	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
33	22/12/17 09:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/12/17 09:54	Sketch Plan	Load TIF	
2	22/12/17 09:55	CI,IC,DL	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117024632/T1QBE2

Date: 20/07/2018

REFERENCE

Insured/Claimant: AH BEE FROZEN FOOD Policy No: DMCVSN3032291702
Date of Loss: 21/12/2017 Nature of Claim: OD Claim No: SNM17D07283C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN5273B**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M) Engine No: 4P10B00838
Reg. Date: 30/05/2014 (Man. Year: 2013) Chassis No: FEB21CA00016
Colour: White Odometer: 0 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$73,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,560.05	7,712.30	1,847.75	19.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	2,330.00	530.00	18.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,420.05	10,042.30	2,377.75	19.14
Approved Total (Overridden) (S\$)		7,950.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	12,420.05	5,950.00	6,470.05	52.09
+ GST 7.00/7.00% (S\$)	869.40	416.50	452.90	52.09
Nett Amount (S\$)	13,289.45	6,366.50	6,922.95	52.09

INSPECTION

Date of Assignment: 28/12/2017 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected: 28/12/2017 Inspected At: Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 20 Jul 2018)
Parts:	N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN5273B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	20.00 FS	*20.00 FS
2	1	*FRT BUMPER (WCP)	Bent	550.00 F	*550.00 F
3	2	*FRT BUMPER SIDE GARNISH (WCP)	Missing	360.00 F	*360.00 F
4	2	*FRT BUMPER BRACKET (WCP)	Bent	220.00 F	*220.00 F
5	1	*FRT GRILLE (WCP)	Cracked	580.00 F	*580.00 F
6	1	*FRT GRILLE CENTER RETAINER (WCP)	Bent	17.00 F	*17.00 F
7	1	*FRT HORN COVER (WCP)	Bent	100.00 F	*100.00 F
8	1	*FRT HORN (WCP)	Bent	90.00 F	*90.00 F
9	1	*FRT HEATER PIPE (WCP)	Not Necessary	80.00 F	*- F
10	10	*FRT GRILLE CLIP (WCP)	Necessary	50.00 F	*50.00 F
11	1	*FRT PANEL COMPLETE (WCP)	Bent	1,400.00 F	*1,400.00 F
12	1	*FRT PANEL FUSO LOGO (WCP)	Necessary	70.00 F	*70.00 F
13	1	*FRT CORNER PANEL (WCP)	N/S Cracked / O/S NotNecessary	520.00 F	*260.00 F
14	6	*FRT CORNER PANEL CLIP (WCP)	Necessary	24.00 F	*24.00 F
15	2	*FRT HEADLAMP (WCP)	Cracked	680.00 F	*680.00 F
16	2	*FRT SIGNAL LAMP (WCP)	Cracked	300.00 F	*300.00 F
17	1	*FRT WIPER GARNISH (WCP)	Not Necessary	820.00 F	*- F
18	1	*FRT SIDE MIRROR (ROUND) LH (WCP)	Missing	35.00 F	*35.00 F
19	1	*FRT WINDSCREEN RUBBER (WCP)	Necessary	260.00 F	*260.00 F
20	1	*ERP BRACKET	Not Necessary	26.00 FS	*- FS
21	1	*FRT AIR CON HIGH PRESSURE PIPE (WCP)	Not Necessary	95.00 F	*- F
22	1	*FRT AIR CON LOWER PRESSURE PIPE (WCP)	Bent	180.00 F	*180.00 F
23	1	*AIR CON BLOWER ASSY (WCP)	Cracked	2,150.00 F	*2,150.00 F
24	1	*AIR INTAKE BOX (WCP)	Not Necessary	480.00 F	*- F

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	9,107.00	7,346.00
				+ Margin on L,N Items 5.00/5.00%	(S\$)	453.05	366.30
					Total Parts (S\$)	9,560.05	7,712.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK STRAIGHTEN FRT CHASSIS FRAME,WELD,REMOVE & FIX ON ABOVE PARTS	New	1,400.00	1,100.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	800.00
3	TO REMOVE & REFIX FRT WINDSCREEN	New	100.00	100.00
4	TO REFILL AIRCON GAS	New	100.00	100.00
5	.TO REMOVE & REFIX FRT DASHBOARD	New	180.00	180.00
6	TO REMOVE & REFIX FLOORMAT	New	80.00	50.00
Gross Labour Cost (S\$)			2,860.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >