

REF:

ALH

CC3/ALH17024642/7Hbn2

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s Premium Anto

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 1000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$148K

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: STC 68006 Yr Regn: 18 May 2013Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Audi S5 C.C. 2995Colour: white A/C: Insured / Std / NI / NASp. Reading: 69804 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ8T6DA052116Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35 8R19R: 11BS / DU / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. \_\_\_\_\_ D.O.I. 26-12-17Survey held at: W/S 5:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s FrtThe ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

STC 68006 - CG/MSH17024642/7Hbn2

DUA: 22122017

29/12 - Report via messaging.

31/01 - Authorise repair Victor Koh

23/1 - email premium authorise repair excess \$10000

6854.24; (Red: 6838.76; 53%)

RECEIVED 18 APR 2018

Date/Time: File Pass to?

☐ : Preli. Report1) AD4 Typist☒ : Final Report

Date/Time: File Return to?

2) \_\_\_\_\_

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RE - SI

Photo: \_\_\_\_\_

Other: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)Report Format: ODLump Sum / I.B.I: \$ 5854.24

TOTAL

200

10

210



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17024642/Gtb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-12-2017	
		Code : AIG	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SFC 6800G
<b>Policy No.</b>	2100333826	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	26/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b>	22/12/2017	<b>Inspection Date</b>	29/12/2017
<b>Survey held at</b>	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
<b>5a. Remarks</b>			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

## ▶ AUDI S5 Used Vehicle List (14 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Audi S5 Coupe 3.0A TFSI Quattro S-Tronic</b>	<b>\$215,000</b>	<b>\$23,480 /yr</b>	<b>27-Feb-2015</b>	<b>2,995 cc</b>	<b>32,000 km</b>		<b>Available</b>
Fully Serviced And Warranty By Audi Agent Till Feb 2020, Low Mileage, Excellent Condition. 3 x Service Package (Oil Change) Remaining. New Set Of Michelin PSS Tires, No Dealers Please. Viewing By Appo...							
Office No. - - Terence Tan - 97684148							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$142,800</b>	<b>\$22,120 /yr</b>	<b>05-Dec-2012</b>	<b>2,995 cc</b>	<b>79,000 km</b>	<b>Cars Connect</b>	<b>Available</b>
Wow! Check This Out! Facelifted Model, 1 Single Owner, Agent's Unit, Agent Maintained By Premium, Low Mileage, Highest COE Of \$93990, High Paper Value At All Times With Fixed Depreciation, Excellent P...							
Office No. - - Mr Yoon - 96869684   Ms Ong - 98414262							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$108,888</b>	<b>\$18,480 /yr</b>	<b>17-Feb-2012</b>	<b>2,995 cc</b>	<b>115,000 km</b>		<b>Available</b>
Well Kept By Owner And Fully Maintained By Audi. Direct Buyers Only Please.							
Office No. - - Cheong - 94388415							
<b>Audi S5 Cabriolet 3.0A TFSI Quattro</b>	<b>\$96,800</b>	<b>\$16,660 /yr</b>	<b>30-Jun-2011</b>	<b>2,995 cc</b>	<b>87,000 km</b>	<b>Hui Hua Credit Pte Ltd</b>	<b>Available</b>
Excellent Condition, Well Taken Care By The Previous Owner. Powerful And Sporty. Call To View Now Before It Is Too Late! In House Loan Available.							
Office No. - 64666611 Jarryl Ng - 85888000   Alex Chng - 86661188   Max Siah - 93801243   Jian Rong - 91830337							
<b>Audi S5 Cabriolet 3.0A TFSI Quattro</b>	<b>\$111,800</b>	<b>\$21,270 /yr</b>	<b>10-Jun-2011</b>	<b>2,995 cc</b>	<b>55,000 km</b>	<b>Faster Auto Trading</b>	<b>Available</b>
1 Owner, Low Mileage Done Only 55,000Km, Full Serviced Histories With Agent, Flexible Bank Loan Interest Rate, High Trade In.							
Office No. - 64761970 Yi De - 97480900   Jimmy - 91010213   Thomas - 96645002							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$93,800</b>	<b>\$17,990 /yr</b>	<b>30-May-2011</b>	<b>2,995 cc</b>	<b>80,000 km</b>	<b>Autocars Premium Pte Ltd</b>	<b>Available</b>
Definitely The Best Condition Unit In The Market. Upgraded Rims. 100% Accident Free. Cheapest In The Market. Feel The Roar Beneath The Award Winning V6 Engine With Turbo. Don't Miss This Offer. Hurry!...							
Office No. - 67345595 Eugene - 86600667   Louis - 97778960							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$91,800</b>	<b>\$16,780 /yr</b>	<b>23-May-2011</b>	<b>2,995 cc</b>	<b>97,000 km</b>	<b>SG Carline Pte Ltd</b>	<b>Available</b>
Nice Bidded Number Plate. Beautiful Condition, Extremely Popular Luxury Executive Sedan That Blends Perfectly For Business And Leisure. High Paper Value. Low Mileage, Immaculate Condition. Cheapest In...							
Office No. - 64766427 Marcus Heng - 88581850   Leta - 90299553							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$93,800</b>	<b>\$20,280 /yr</b>	<b>31-Dec-2010</b>	<b>2,995 cc</b>	<b>108,000 km</b>		<b>Available</b>
Well Maintained, Wear And Tear Replaced Recently. Service History Record At Premium Automobiles Available. Text/Whatsapp For Viewing. No Dealers/Consignment Please, Thank You.							
Office No. - - Tan - 91185829							
<b>Audi S5 Sportback 3.0A TFSI Quattro</b>	<b>\$88,888</b>	<b>\$18,860 /yr</b>	<b>30-Dec-2010</b>	<b>2,995 cc</b>	<b>79,000 km</b>	<b>A1 Motoring Pte Ltd</b>	<b>Available</b>
\$5k Down Payment Drive Away With Balloon Scheme At \$1.8k Monthly Installment. Accidentally Free Car With Low Mileage. Call Arrange Viewing For This Beauty. Why Wait? Call Us Now!							
Office No. - 62646526 Chua - 91691940   Tang - 87999466   Chong - 90263577   Roy - 87999711							
<b>Audi S5 Sportback 3.0A TFSI</b>	<b>\$93,800</b>	<b>\$20,790 /yr</b>	<b>21-Dec-2010</b>	<b>2,995 cc</b>	<b>65,000 km</b>	<b>A&amp;L Automobile Pte Ltd</b>	<b>Available</b>

## View Received Message

This mail is associated with :

**\*SFC6800G (5790274434SG)**

OD

Dec 22 2017 2:00PM

[KHOO YU HUNG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 03/01/2018 11:46 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$6341.00) - SFC6800G - Claim Handler: Chan, Kian Meng

Approved:6341.00:Re-inspection to be done for damage check and supplementary items / labour.

### DOCUMENTS SUMMARY

There are no documents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 3 January, 2018 1:02 PM  
**To:** 'Claims Department'  
**Cc:** SUR  
**Subject:** RE: Automatic reply: OD CLAIM FOR SFC 6800 G  
**Attachments:** sfc 6800g EST.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFC 6800G (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Department [mailto:claims@premiumauto.com.sg]  
**Sent:** Wednesday, 3 January, 2018 12:11 PM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Cc:** 'Claims Dept' <claims@premiumauto.com.sg>  
**Subject:** RE: Automatic reply: OD CLAIM FOR SFC 6800 G

Hi Denise,

Kindly assist to check has AIG given the approval.

Thank you

Best Regards,  
Claims Advisor

**Kee Siang**

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 m. +65 8777 0600

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223

# Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 4196Z

## Vehicle Details

Vehicle No.: SFC6800G  
Vehicle to be Exported: No  
Intended De-registration Date: 27 Dec 2017  
Vehicle Make: AUDI  
Vehicle Model: S5 SPORTBACK 3.0 TFSI QU  
Primary Colour: White  
Manufacturing Year: 2013  
Engine No.: CGW063327  
Chassis No.: WAUZZZ8T6DA052116  
Maximum Power Output: 245.0 kW (328 bhp)  
Open Market Value: \$65,537.00  
Original Registration Date: 18 Mar 2013  
First Registration Date: 18 Mar 2013  
Transfer Count: 0  
Actual ARF Paid: \$65,537.00 32768.5

## Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 17 Mar 2023  
PARF Rebate Amount: \$49,152.00

## Intended COE Rebate Details

COE Expiry Date: 17 Mar 2023  
COE Category: B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$92,667.00
COE Rebate Amount:	\$48,329.00
Total Rebate Amount:	\$97,481.00

The information contained herein is correct as at 27 Dec 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/12/2017 21:09
Date Of Accident	22/12/2017 14:00
Exact Location Of Accident	CARPARK AT MOHD SULTAN RD/RIVER VALLEY RD OF ST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFC6800G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KHOO YU HUNG
NRIC No	S7344196Z
Email Address	KHOOYH@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97818310
Alternative Phone No	OFFICE-97818310

### Vehicle Particulars

Manufacturer	AUDI
Model	S5 SB 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100333826-04000
Cover Note Number	

### Driver

Name of Driver	KHOO YU HUNG
NRIC No	S7344196Z
Date Of Birth	06/12/1973
Occupation	INDOOR
Date Of Driving Pass	22/12/2003
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97818310
Fax Number	
Contact Number	OFFICE-97818310
Email Address	KHOOYH@YAHOO.COM



Address

11F MOUNT SINAI LANE  
#05-30

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

ON 22/12/17 AT 2PM, I WAS PARKED AND WAITING IN MY CAR (SFC 6800 E) AT CARPARK M0077 OFF MOHD SULTAN/RIVER VALLEY ROAD, WHEN A TOYOTA LITE ACE VAN DRIVEN BY MR LIM ENG CHEONG (NRIC:S00963266) REVERED QUICKLY INTO THE LOT NEXT TO ME. HE WAS VERY CLOSE TO MY CAR, AND BY THE TIME I COULD START MY ENGINE TO SOUND THE HORN, HE HAD TURNED OUT OF THE LOT AND KNOCKED INTO THE FRONT RIGHT SIDE OF MY CAR. MR LIM WAS APOLOGETIC AND ADMITTED HIS MISTAKE AND PROVIDED A NOTE ON SIDE AS PROOF.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GW7450J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/17 at 2pm, I was parked and waiting in my car (SFC6800G) at carpark M0077 off Mahal Sultan / River Valley Road, when a Toyota Lite Ace van driven by Mr Lim Eng Cheong (NRIC: S00963266) reversed quickly into the lot next to me. He was very close to my car, and by the time I could start my engine to sound the horn, he had ~~had~~ turned out of the lot and knocked into the front right side of my car.

Mr Lim was apologetic and admitted his mistake and provided a note on site as proof.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Lim Kee Seng  
NRIC/FIN No.: G65556914

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/17 at 2pm, I was parked and waiting in my car (SFC6800G) at carpark M0077 off Mahal Sutra / River Valley Road, when a Toyota Lite Ace van driven by Mr Lim Eng Cheong (NRIC: 500963266) reversed quickly into the lot next to me. He was very close to my car, and by the time I could start my engine to sound the horn, he had ~~had~~ turned out of the lot and knocked into the front right side of my car.

Mr Lim was apologetic and admitted his mistake and provided a note on site as proof.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Lim Kee Seng  
NRIC/FIN No.: G6552569M

THIRD PARTY STATMENT

I, LIM ENG

CHEONG (S00963269)

Knocked into

SFC 6800 G

at car park M0077

on 22/12/17 2pm

do  
22/12/17

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7344196Z**

Name: **KHOO YU HUNG**  
(QIU YUHONG)

Birth Date: 06 Dec 1973  
Issue Date: 19 Mar 2004

001169789G



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7344196Z**

Name: **KHOO YU HUNG**  
(QIU YUHONG)  
丘育弘

Race: **CHINESE**

Date of birth: **06-12-1973** Sex: **M**

Country of birth: **SINGAPORE**

S7344196Z





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

16 Aug 1994

NP 428A



3446301



NRIC No: **S7344196Z**



Date of issue: **22-12-2003**

**11F MOUNT SINAI LANE #05-30**  
**SINGAPORE 277055**

NRIC No: **S7344196Z** Date: **26/09/2016**



## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MLX.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100333826-04000

OWN DAMAGE EXCESS S\$2000.00 (1)  
WINDSCREEN EXCESS S\$100.00  
(for policies with effect from 1st November 2002)

SUM INSURED Market Value  
INSURING WITH COE/PARF Yes  
SFC6800G

1) VEHICLE REGISTRATION NO.

KHOO YU HUNG (KHU YU HONG)

2) NAME OF INSURED

18 Mar 2017

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

17 Mar 2018

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE \*  
SUBJECT TO AGE CONDITION :N.A

a) The Insured

The Insured may also drive a motor car not belonging to him or hired (under a hire purchase agreement or otherwise) by him or his employer or business partner.

All drivers who are below the age of 23 are excluded in this Policy.

All drivers who are below the age of 28, above the age of 65 or with less than 2 years' driving experience are subject to an Excess of S\$5,000.00.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE \*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Crest (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER Cheng Jin Choo Shirley

HIRE PURCHASE COMPANY DBS BANK LTD  
/ EMPLOYER'S LOAN

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued At Singapore 15 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200  
PREMIUM RELEASING - AP  
281 ALEXANDRA ROAD  
AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

AUTHORISED REPRESENTATIVE



# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1253/2017/JT
Date	:	23-Dec-17

Vehicle not workshop. Kindly arrange for survey.

## MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name	:	Mr. Khoo Yu Hung
Address	:	11F Mount Sinai Lane #05-30 Singapore 277055
Telephone	:	HP +65 9781 8310
Type of Claim	:	Third Party Claims
Policy No.	:	2100333826-04000
Vehicle No	:	<b>SFC 6800 C</b>
Model Code	:	Audi S5 SB 3.0 TFSi qu
Model / Year	:	Mar-13
Engine No	:	CGW 063327
Chassis No	:	WAUZZZ8T6DA052116
Mileage	:	
Date In	:	22-Dec-17
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Dec-17
Place of Accident	:	Carpark at Mohd Sultan Rd / River Valley Road



# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SFC 6800 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/ ✓
2	To dismantle and renew front bumper, RHS front fender and RHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,100.00	1200 <del>1000</del> 1000 ✓
3	To respray front bumper and RHS front fender.	\$ 1,700.00	1200 1100 ✓
4	To renew RHS Front <del>rim</del> and carry out wheel alignment.	S/N \$ 280.00	240 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 4,752.00	

~~Tax vehicle from accident scene to~~ S/N \$280.00 ?  
DA

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SFC 6800 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / <i>ll</i>	\$ 2,429.00	1943.20
2	AIR GRILLE - RHS <i>X NN</i>	\$ 291.00	
3	FRONT BUMPER GUIDE - RHS <i>X NN</i>	\$ 36.00	
4	FRONT FENDER - RHS / <i>buc</i>	\$ 900.00	720
5	FRONT FENDER INNER BRACKET - RHS <i>X NN</i>	\$ 49.00	
6	FRONT FENDER OUTER BRACKET - RHS <i>X NN</i>	\$ 49.00	
7	FRONT FENDER BRACE - RHS <i>X MC</i>	\$ 102.00	81.60
8	FRONT WHEEL HOUSE LINER - RHS <i>X NN</i>	\$ 157.00	
9	WHEEL HOUSE LINER ATTACHMENT PARTS - RHS <i>X NN</i>	\$ 38.00	
10	HEADLIGHT - RHS <i>X</i>	\$ 2,298.00	
11	HEADLIGHT MOUNTING - RHS <i>X NN</i>	\$ 106.00	
12	HEADLIGHT BRACKET - RHS <i>X</i>	\$ 89.00	
13	ALUMINIUM RIM - RHS <i>X NN</i>	\$ 892.00	
14	SUNDRIES <i>X MC</i>	\$ 400.00	13.44
TOTAL SPARE PARTS		: \$ 7,836.00	
TOTAL LABOUR CHARGES		: \$ 4,752.00	
GRAND TOTAL		: <u>\$ 12,588.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Guo Qiy - 82880282

26/12/17

before paint photos.

5 Days

NOT authorise

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1253/2017/JT  
Date : 23-Dec-17

Vehicle not workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Guo Qiang  
5 days - ok - jb - 15 Mar 18

Attn: Motor Claims Dept  
Tel: 6841 0055 - Fax 6841 6315

Owner's Name : Mr. Khoo Yu Hung  
Address : 11F Mount Sinai Lane  
#05-30  
Singapore 277055  
Telephone : HP +65 9781 8310  
Type of Claim : Third Party Claims  
Policy No. : 2100333826-04000  
Vehicle No : **SFC 6800 C**  
Model Code : Audi S5 SB 3.0 TFSi qu  
Model / Year : Mar-13  
Engine No : CGW 063327  
Chassis No : WAUZZZ8T6DA052116  
Mileage :  
Date In : 22-Dec-17  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 22-Dec-17  
Place of Accident : Carpark at Mohd Sultan Rd / River Valley Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SFC 6800 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, RHS front fender and RHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper and RHS front fender.	\$ 1,700.00	\$ 1,100.00
4	To renew RHS Front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 240.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,752.00	\$ 3,012.00

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SFC 6800 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,429.00	\$ 1,943.20
2	AIR GRILLE - RHS	\$ 291.00	
3	FRONT BUMPER GUIDE - RHS	\$ 36.00	
4	FRONT FENDER - RHS	\$ 900.00	\$ 720.00
5	FRONT FENDER INNER BRACKET - RHS	\$ 49.00	
6	FRONT FENDER OUTER BRACKET - RHS	\$ 49.00	
7	FRONT FENDER BRACE - RHS	\$ 102.00	\$ 81.60
8	FRONT WHEEL HOUSE LINER - RHS	\$ 157.00	
9	WHEEL HOUSE LINER ATTACHMENT PARTS - RHS	\$ 38.00	
10	HEADLIGHT - RHS	\$ 2,298.00	
11	HEADLIGHT MOUNTING - RHS	\$ 106.00	
12	HEADLIGHT BRACKET - RHS	\$ 89.00	
13	ALUMINIUM RIM - RHS	\$ 892.00	
14	Added parts - see attached	\$ 105.00	\$ 84.00
15	SUNDRIES	\$ 400.00	\$ 13.44
TOTAL SPARE PARTS		\$ 7,941.00	\$ 2,842.24
TOTAL LABOUR CHARGES		\$ 4,752.00	\$ 3,012.00
GRAND TOTAL		\$ 12,693.00	\$ 5,854.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Estimate No.** PA/TP/1253/2017/JT  
**Date** 5-Jan-18  
**Service Advisor** JB  
**Pages** ONE  
**Regn No** SFC6800G  
**Model No** S5 SB 3.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	V6T EMBLEM FOR FENDER / <i>MEC</i>	\$ 105.00	\$ 84.00 (A)
		<u>\$ 105.00</u>	
<b>TOTAL</b>		<b>\$ 105.00</b>	<b>\$ 84.00</b>

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		29 Dec 2017 09:19 <a href="#">Edit Adj Rpt</a>	<b>S\$5,854.24</b> <a href="#">Edit Estimates</a>	<b>S\$5,854.24</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	KHOO YU HUNG, ID: S7344196Z, Tel: +6597818310, Email: khooyh@yahoo.com								
Vehicle Reg. No.:	SFC6800G	Date of Loss:	22/12/2017 14:00 - :59 [57 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5790274434SG	Policy/Cover Note No.:	2100333826-04000 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/01/2018]								
Driver/Custodian:	KHOO YU HUNG (44 / Male), NRIC: S7344196Z, Tel: +6597818310								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (03/01/2018): Alert - Adj Mandate Approved (S\$6341.00) - SFC6800G - Claim Handler: Chan, Kian ...</li> <li>AIG_SG (02/01/2018): Alert - Adj Mandate Maintained - SFC6800G - Claim Handler: Chan, Kian Meng</li> <li>AIG_SG (29/12/2017): SFC6800G / OD / 22/12/2017 / Coverage &amp; Excess update</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFC6800G (5790274434SG)  
OD  
Dec 22 2017 2:00PM  
[KHOO YU HUNG]  
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			Use Viewer		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	29/12/17 11:05	Adjuster Immediate Advice													1			Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	29/12/17 10:35	General View													1			Load JPG		
2	29/12/17 10:35	General View													1			Load JPG		
3	29/12/17 10:36	General View													1			Load JPG		
4	29/12/17 10:36	General View													1			Load JPG		
5	29/12/17 10:36	General View													1			Load JPG		
6	29/12/17 10:36	General View													1			Load JPG		
7	29/12/17 10:36	General View													1			Load JPG		
8	29/12/17 10:36	General View													1			Load JPG		
9	29/12/17 10:36	General View													1			Load JPG		
10	29/12/17 10:36	General View													1			Load JPG		
11	29/12/17 10:36	General View													1			Load JPG		
12	29/12/17 10:36	General View													1			Load JPG		
13	29/12/17 10:36	General View													1			Load JPG		
14	29/12/17 10:36	General View													1			Load JPG		
15	29/12/17 10:36	General View													1			Load JPG		
16	29/12/17 10:36	General View													1			Load JPG		
17	29/12/17 10:36	General View													1			Load JPG		
18	29/12/17 10:36	General View													1			Load JPG		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	29/12/17 10:36	WORKSHOP ESTIMATE													1			Load PDF		
2	29/12/17 10:36	Driver's Driving License													1			Load PDF		
3	29/12/17 10:45	Certificate of Insurance													1			Load PDF		
4	29/12/17 10:45	Singapore Accident Statement													1			Load PDF		
5	03/01/18 08:49	ESTIMATE													1			Load PDF		
6	19/04/18 09:24	WORKSHOP INVOICE													1			Load PDF		
7	19/04/18 09:24	DISCHARGE VOUCHER													1			Load PDF		

## Linked Accident Report Documents

			<b>View</b> Use Viewer		
<b>Assessment Reports</b>			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/12/17 21:34	Accident Statement	1	Load HTM	
2	28/12/17 18:52	Addendum Sheet	1	Load JPG	<input checked="" type="checkbox"/>
3	28/12/17 19:16	Accident Statement Addm. #1	1	Load HTM	
			3 per page		<input checked="" type="checkbox"/>
<b>Photos/Images</b>					
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>

4	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	22/12/17 21:26	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	22/12/17 21:28	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
14	22/12/17 21:28	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					1 per page <input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/12/17 21:28	THIRD PARTY STATMENT	1	Load JPG	<input checked="" type="checkbox"/>
2	22/12/17 21:30	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
3	22/12/17 21:30	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

Our File No: CC3/AIG17024642/GTBN2

Date: 19/04/2018

## REFERENCE

Insured/Claimant: KHOO YU HUNG Policy No: 2100333826-04000  
Date of Loss: 22/12/2017 Nature of Claim: OD Claim No: 5790274434SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFC6800G  
Make & Model: AUDI S5, 3.0 TFSI QUATTRO (A)  
Reg. Date: 18/03/2013 (Man. Year: 2013)  
Colour: White  
Engine Capacity: 2995 cc  
Market Value/New Car Price: S\$148,000.00  
Sum Insured (S\$): Market Value/New Car Price

Engine No: CGW063327  
Chassis No: WAUZZZ8T6DA052116  
Odometer: 69804 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Footbrake (Serviceable): Yes  
Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 255/35ZR19  
Front Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm  
Rear Tyre Size: 255/35ZR19  
Rear Left Side: Pirelli 6 mm  
Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,920.00	2,842.24	5,077.76	64.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	3,012.00	1,740.00	36.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,672.00	5,854.24	6,817.76	53.80
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	11,672.00	4,854.24	6,817.76	58.41
+ GST 7.00/7.00% (S\$)	817.04	339.80	477.24	58.41
Nett Amount (S\$)	12,489.04	5,194.04	7,295.00	58.41

## INSPECTION

Date of Assignment: 29/12/2017

Date Inspected: 26/12/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,429.00 FS	*1,943.20 FS
2	1	*AIR GRILLE-RHS	Not Necessary	291.00 FS	*- FS
3	1	*FRONT BUMPER GUIDE-RHS	Not Necessary	36.00 FS	*- FS
4	1	*FRONT FENDER-RHS	Buckled	900.00 FS	*720.00 FS
5	1	*FRONT FENDER INNER BRACKET-RHS	Not Necessary	49.00 FS	*- FS
6	1	*FRONT FENDER OUTER BRACKET-RHS	Not Necessary	49.00 FS	*- FS
7	1	*FRONT FENDER BRACE-RHS	Necessary	102.00 FS	*81.60 FS
8	1	*FRONT WHEEL HOUSE LINER-RHS	Not Necessary	157.00 FS	*- FS
9	1	*WHEEL HOUSE LINER ATTACHMENT PARTS-RHS	Not Necessary	38.00 FS	*- FS
10	1	*HEADLIGHT-RHS	Not Necessary	2,298.00 FS	*- FS
11	1	*HEADLIGHT MOUNTING-RHS	Not Necessary	106.00 FS	*- FS
12	1	*HEADLIGHT BRACKET-RHS	Not Necessary	89.00 FS	*- FS
13	1	*ALUMINIUM RIM-RHS	Not Necessary	892.00 FS	*- FS
14	1	*SUNDRIES	Necessary	400.00 FS	*13.44 FS
15	1	*V6T EMBLEM FOR FENDER	Necessary	84.00 FS	*84.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>7,920.00</b>	<b>2,842.24</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,700.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			<b>4,752.00</b>	<b>3,012.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >