

INS. CASE OWNER:

CC 9 / AXA1702

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/ Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

MKS

QUAR

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

S\$

22,253.67

Loss of Rental (LOR):

S\$

days)

Loss of Use (LOU):

S\$

1,400 (\$100 x 14 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

395.90

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

24,049.51

Global Sum S\$:

24,045.XX

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

24,045

Name 1:

CITY AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA17024665/Gjb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 29-12-2017		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 7715U	Veh. Inspected	SKV 6527L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/12/2017	Inspection Date	28/12/2017	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

587.60			
224.20			
166.40			
87.70			
24.02			
67.60			
31.12			
1,956.20			
367.70			
796.80			
32.80			
66.79			
785.60			
212.50			
122.70			
179.60			
25.60		30.00	
792.40		60.00	
187.20		1,400.00	
1,345.70	40.00	1,600.00	
158.68	1,174.80	100.00	
8,218.91	25.00	40.00	
75% 80%	35.00	180.00	(REVISED)
6,575.13	1,274.80	3,410.00	= 11,259.93

\$ 10,848.98

29,851.93 TOTAL


15/2/2018

856.40			
856.40			
781.12			
170.00			
326.20			
456.30			
476.33			
256.22			
102.50			
102.50			
400.75			
1,718.70			
1,718.70			
45.70			
755.43			
67.50			
76.80			
179.40			
246.73			
1,349.00			
1,295.10			
129.75			
487.52			
298.60			
107.80			
157.80			
269.70			
48.90			
48.90			
176.45			
9,089.30			
23,052.50			
75% 80%			(CHECK)
18,442.00	150.00	=	18,592.00

\$ 17,439.38

...CLAIM SUBFOLDER...(New Assignment)

BI Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		28 Dec 2017 13:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Main Claimant:	TOKYO CENTURY LEASING (SINGAPORE PTE LTD), Co. Reg. No.: 197901535G								
Vehicle Reg. No.:	SKV6527L	Date of Loss:	21/12/2017 12:00 - :59						
Claim Type:	TP / C0464740	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHB7715U	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/01/2018]								
Driver/Custodian (Insured):	YEO KIM LAI (), NRIC: S1122970J								
Adj Asg. Remarks:	TP-ARC PLS ENSURE CONSISTENCE AND BE STRINGENT ON COR.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AXA_SG (28/12/2017): New TP Assignment - C0464740/P1680520									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

28.12.2017 @ 1:58 pm
Vannira veh in
GB



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd

8 Shenton Way

#27-01 Singapore 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017

Vehicle Num. : SKV 6527L

Make/Model : Toyota Vellfire

Chassis/Eng# : JTNGF3DH708000119 (205)

Accident Date : 21/12/2017

Claim No. : TP AXA

Reference : -

Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount SS
LIST ITEMS :				
1.	1	Rear bumper / <i>Dis</i>		587.60
2.	1	Rear bumper cover LH - Upper <i>- Re</i>		224.20
3.	1	Rear bumper cover RH - Upper <i>X NP</i>		224.20
4.	2	Rear bumper side retainer <i>- Acc</i>	83.20	166.40
5.	2	Rear bumper upper retainer <i>- LH ipc Re RH X NN</i>	87.70	175.40
6.	1	Rear bumper towing cover - LH <i>- Cut</i>		24.02
7.	2	Rear bumper reflector <i>LH ipc - Acc RH X NN</i>	67.60	135.20
8.	8	Rear Bumper clips <i>- Acc</i>	3.89	31.12
9.	1	Tailgate <i>- buc</i>		1,956.20
10.	1	Tailgate weatherstrip <i>- Turi</i>		367.70
11.	1	Tailgate lock <i>- Turi</i>		796.80
12.	1	Tailgate striker <i>- Turi</i>		32.80
13.	1	Tailgate - power back door sensor - LH <i>X NN</i>		856.40
14.	1	Tailgate - power back door sensor - RH <i>X NN</i>		856.40
15.	1	Tailgate trimboard <i>X NN</i>		781.12
16.	1	Tailgate emblem - Vellfire <i>- Acc</i>		66.79
17.	1	Rear end panel <i>- buc</i>		785.60
18.	1	Rear end panel top garnish <i>- Acc</i>		212.50
19.	2	Rear bumper mounting bracket <i>X NN</i>	85.00	170.00
20.	1	Rear windscreen glass moulding <i>- Acc</i>		122.70
21.	1	Rear floor deck box <i>X</i>		326.20
22.	1	Rear floor board Number 1 <i>X</i>		456.30
23.	1	Rear floor board Number 2 <i>X</i>		476.33
24.	1	Rear floor board number 3 <i>X</i>		256.22

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017
 Vehicle Num. : SKV 6527L
 Make/Model : Toyota Vellfire
 Chassis/Eng# : JTNGF3DH708000119
 Accident Date : 21/12/2017
 Claim No. : TP AXA
 Reference : -
 Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	Rear floor board plate upper number 1 <i>X NN</i>		102.50
26.	1	Rear floor board plate upper number 2 <i>X NN</i>		102.50
27.	1	Utility sub - box <i>R / ee</i>		400.75
28.	1	Rear seat cross member number 1 <i>X BT</i>		1,718.70
29.	1	Rear seat cross member number 2 <i>X BT</i>		1,718.70
30.	1	Spare wheel anchor screw <i>X NN</i>		45.70
31.	1	Rear floor panel <i>R / buc</i>		755.43
32.	1	Rear floor panel reinforcement <i>BT BT</i>		179.60
33.	1	Rear floor panel bracket <i>X BT</i>		67.50
34.	4	Hole plug <i>2pc - ee</i>	25.60	102.40
35.	1	Rear keyless entry sensor <i>R / som</i>		179.40
36.	1	Rear keyless entry buzzer <i>R / som</i>		246.73
37.	2	Tail lamp <i>X LH - CH</i>	674.50	1,349.00
38.	2	Boot lamp <i>X RH X NN</i>	647.55	1,295.10
39.	1	Front bumper <i>R</i>		792.40
40.	1	Front bumper sponge <i>R - ee</i>		129.75
41.	1	Front bumper reinforcement <i>X NN</i>		487.52
42.	1	Front bumper reinforcement bracket <i>X NN</i>		298.60
43.	2	Front bumper retainer <i>ee</i>	93.60	187.20
44.	1	Front bumper lower grille <i>R - ee</i>		107.80
45.	1	Front bumper lower splash guard <i>X NN</i>		157.80
46.	1	Front bumper towing cover RH <i>X NN</i>		214.50
47.	1	Front grille with chrome <i>CH</i>		1,345.70
48.	1	Support top garnish <i>X NN</i>		269.70
49.	1	Wiper garnish side cover - LH <i>X NN</i>		48.90
50.	1	Wiper garnish side cover - RH <i>X NN</i>		48.90

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017
 Vehicle Num. : SKV 6527L
 Make/Model : Toyota Vellfire
 Chassis/Eng# : JTNGF3DH708000119
 Accident Date : 21/12/2017
 Claim No. : TP AXA
 Reference : -
 Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
51.	2	Bonnet hinge <i>BT</i>	79.34	158.68
52.	1	Bonnet lock <i>NN</i>		176.45
53.	2	Headlamp <i>CH - CMA</i> <i>PH X NN</i>	4,544.65	9,089.30
List Total S\$:				31,865.41
25.00% Discount S\$:				7,966.35
				23,899.06
SPECIAL NETT ITEMS :				
1.	1	Rear windscreen glass sealant <i>GC</i>		40.00
2.	4	Reverse sensor - original <i>3PC - PM</i>	391.60	1,566.40
3.	1	Front number plate <i>BT</i>		25.00
4.	1	Front number plate casing <i>RL</i>		35.00
Special Nett Total S\$:				1,666.40
LABOUR :				
*To check wiring and lighting				30 60.00
*To supply sealant and reseal all weld spot seam & gaps				60 80.00
*To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts				1200 1400 1,700.00
*Spray painting on affected & replace parts				1600 1,800.00
*To use diagnosis computer to reset and recalibrate tailgate and re-activate PWD system				8 150 280.00
*To remove and reinstall rear windscreen glass				100 150.00

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 Singapore 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017
Vehicle Num. : SKV 6527L
Make/Model : Toyota Vellfire
Chassis/Eng# : JTNGF3DH708000119
Accident Date : 21/12/2017
Claim No. : TP AXA
Reference : -
Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|--|--|--|--------|--|
| | | *Remove and refit rear view camera | 120.00 | |
| | | *To remove rear seat, trimboard and upholstrey | 280.00 | |

Labour Total S\$:

4,470.00

12 - 14 Days .

part by part

before paint photos.

Guo Qiang - 82880282

Guo Qiang @ lkk auto. com

28/12/17.

E. & O.E.

Total S\$: 30,035.46

=====

30,437.33

for CITY AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-00/02, SIN MING ROAD, SINGAPORE 575643.

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 Singapore 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Supplementary Estimate : ES004976

Date : 02/01/2018

Vehicle Num. : SKV 6527L

Make/Model : Toyota Vellfire

Chassis/Eng# : JTNGF3DH708000119

Accident Date : 21/12/2017

Claim No. : TP AXA

Reference : -

Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : Spare wheel carrier / el		375.83
----	---	--	--	--------

		List Total S\$:		375.83
--	--	------------------	--	--------

		25.00% Discount S\$:		93.96
--	--	-----------------------	--	-------

281.87

1.	1	SPECIAL NETT ITEMS : Rear floor pan Insulator / MC.		120.00
----	---	--	--	--------

		Special Nett Total S\$:		120.00
--	--	--------------------------	--	--------

P - 21070.63

- 20 / -

16850.60

SN - 1,394.80

L - 3,600.00

21,851.30

PP - 21,851.30

14 Days

One Set.
02/1/18

L. R. O. E.

Total S\$: 401.87

=====

for CITY AUTO PTE LTD



CITY AUTO PTE LTD

BLK 8, SIN MING INDUSTRIAL ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575043.
 TEL: 6453 1235, 6452 0880 FAX: 6453 7944
 24hrs Towing Services Tel: 6523 8098
 Co. Reg. No.: 199503380C GST Reg. No.: S55-0040679-4

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017
 Vehicle Num. : SKV 6527L
 Make/Model : Toyota Vellfire
 Chassis/Eng# : JTNGF3DH708000119 (206)
 Accident Date : 21/12/2017
 Claim No. : TP AXA
 Reference : -
 Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount	SS
-----	----------	------------	------------	--------	----

LIST ITEMS :					
1.	1	Rear bumper		587.60	✓
2.	1	Rear bumper cover LH - Upper		224.20	✓
3.	1	Rear bumper cover RH - Upper		224.20	✓
4.	2	Rear bumper side retainer	83.20	166.40	✓
5.	2	Rear bumper upper retainer	87.70	175.40	✓
6.	1	Rear bumper towing cover - LH		24.02	✓
7.	2	Rear bumper reflector	67.60	135.20	✓
8.	8	Rear Bumper clips	3.89	31.12	✓
9.	1	Tailgate		1,956.20	✓
10.	1	Tailgate weatherstrip		367.70	✓
11.	1	Tailgate lock		796.80	✓
12.	1	Tailgate striker		32.80	✓
13.	1	Tailgate power back door sensor - LH		856.40	✓
14.	1	Tailgate power back door sensor - RH		856.40	✓
15.	1	Tailgate trimboard		784.42	✓
16.	1	Tailgate emblem - Vellfire		66.79	✓
17.	1	Rear end panel		785.60	✓
18.	1	Rear end panel top garnish		212.50	✓
19.	2	Rear bumper mounting bracket	85.00	170.00	✓
20.	1	Rear windscreen glass moulding		122.70	✓
21.	1	Rear floor deck box		326.20	✓
22.	1	Rear floor board Number 1		456.30	✓
23.	1	Rear floor board Number 2		476.33	✓
24.	1	Rear floor board number 3		256.22	✓
				6,733.56	

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0880 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9823
 Co. Reg. No.: 198634550 GST No.: 802-8820915

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 63304838

Estimate : ES004952

Date : 23/12/2017
 Vehicle Num. : SKV 6527L
 Make/Model : Toyota Vellfire
 Chassis/Eng# : JTNGF3DH708000119
 Accident Date : 21/12/2017
 Claim No. : TP AXA
 Reference : -
 Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	Rear floor board plate upper number 1 ?		102.50 x
26.	1	Rear floor board plate upper number 2 ?		102.50 x
27.	1	Utility sub - box ?		400.75 /
28.	1	Rear seat cross member number 1 ?		1,718.70 /
29.	1	Rear seat cross member number 2 ?		1,718.70 /
30.	1	Spare wheel anchor ?		45.70 x
31.	1	Rear floor panel ?		755.43 /
32.	1	Rear floor panel reinforcement		179.60 /
33.	1	Rear floor panel bracket		67.50 /
34.	4	Hole plug 2PCS - 3PCS	(25.60 x 2)	102.40 51-20
35.	1	Rear keyless entry sensor ?		179.40 /
36.	1	Rear keyless entry buzzer ?		246.73 /
37.	2	Tail lamp ?		674.50 1,349.00
38.	2	Boot lamp ?	647.55	1,295.10
39.	1	Front bumper		792.40 /
40.	1	Front bumper sponge ?		129.75 /
41.	1	Front bumper reinforcement ?		487.52 x
42.	1	Front bumper reinforcement bracket ?		298.60 x
43.	2	Front bumper retainer		187.20 /
44.	1	Front bumper lower grille ?	93.60	107.80 /
45.	1	Front bumper lower splash guard ?		157.80 x
46.	1	Front bumper towing cover RH		214.50 x
47.	1	Front grille with chrome - CAA		1,345.70 /
48.	1	Support top garnish ?		269.70 x
49.	1	Wiper garnish side cover		48.90 x
50.	1	Wiper garnish side cover - RH		48.90 x

9,202.91

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 19980438C GST Reg. No.: NL2-8920979-4

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 63387288

Estimate : ES004952

Date : 23/12/2017

Vehicle Num. : SKV 6527L

Make/Model : Toyota Vellfire

Chassis/Eng : JTNGF3DH708000119

Accident Date : 21/12/2017

Claim No. : TP AXA

Reference : -

Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

51.	2	Bonnet hinge	79.34	158.68 ✓
52.	1	Bonnet lock		176.45 ✓
53.	2	Headlamp	4,544.65	9,089.30 ✓

List Total S\$:

25.00% Discount S\$:

4,703.33

31,865.41

7,966.35

23,899.06

SPECIAL NETT ITEMS :

1.	1	Rear windscreen glass sealant		40.00 ✓
2.	4	Reverse sensor - original	1,174.30	4,696.40 ✓
3.	1	Front number plate		25.00 ✓
4.	1	Front number plate casing		35.00 ✓

Special Nett Total S\$:

1,274.30

1,666.40

LABOUR :

- *To check wiring and lighting
- *To supply sealant and reseal all weld spot seam & gaps
- *To knock Jack out damaged parts, panel beating, welding, align, refix and to renew accident parts
- *Spray painting on affected & replace parts
- *To use diagnosis computer to reset and recalibrate tailgate and re-activate PWD system
- *To remove and reinstall rear windscreen glass

30 60.00

60 80.00

1200 - 1400 1,700.00

1600 1,800.00

? 150 280.00

100 150.00

5,340.00

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 675643.
TEL: 6453 1235, 6452 0880 FAX: 6453 7966
24hrs Towing Services Tel: 9823 9888
Co. Reg. No.: 199503436C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 Singapore 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68904838

Estimate : ES004952

Date : 23/12/2017
Vehicle Num. : SKV 6527L
Make/Model : Toyota Vellfire
Chassis/Eng# : JTNGF3DH708000119
Accident Date : 21/12/2017
Claim No. : TP AXA
Reference : -
Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- *Remove and refit rear view camera
- *To remove rear seat, trimboard and upholstery

Labour Total S\$:

220	40	120.00
180	160	280.00
260		4,470.00

12-14 Days.
part by part
before paint photos.

Guo Qiang - 82880282
Guo Qiang @ lkk auto. com
28/12/17.

E. & O.E.

Total S\$: 30,035.46

for CITY AUTO PTE LTD



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 Singapore 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Supplementary Estimate : ES004976

Date : 02/01/2018
Vehicle Num. : SKV 6527L
Make/Model : Toyota Vellfire
Chassis/Eng# : JTNGF3DH708000119
Accident Date : 21/12/2017
Claim No. : TP AXA
Reference : -
Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS : Spare wheel carrier ✓		375.83
		List Total S\$:		375.83
		25.00% Discount S\$:		93.96
				281.87
1.	1	SPECIAL NETT ITEMS : Rear floor pan insulator ✓		120.00
		Special Nett Total S\$:		120.00

One Set.
02/1/18

E. & O.E.

Total S\$: 401.87

=====

for CITY AUTO PTE LTD



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Page 1 / 4

Joy

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017
 Vehicle Num. : SKV 6527L
 Make/Model : Toyota Vellfire
 Chassis/Eng# : JTNGF3DH708000119 (2015)
 Accident Date : 21/12/2017
 Claim No. : TP AXA
 Reference : -
 Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Rear bumper / DTS		587.60
2.	1	Rear bumper cover LH - Upper - Re		224.20
3.	1	Rear bumper cover RH - Upper X		224.20
4.	2	Rear bumper side retainer	83.20	166.40
5.	2	Rear bumper upper retainer - LH 1 pc.	87.70	175.40
6.	1	Rear bumper towing cover - LH		24.02
7.	2	Rear bumper reflector LH 1 pc.	67.60	135.20
8.	8	Rear Bumper clips	3.89	31.12
9.	1	Tailgate		1,956.20
10.	1	Tailgate weatherstrip		367.70
11.	1	Tailgate lock		796.80
12.	1	Tailgate striker		32.80
13.	1	Tailgate - power back door sensor - LH ?		856.40
14.	1	Tailgate - power back door sensor - RH ?		856.40
15.	1	Tailgate trimboard		781.12
16.	1	Tailgate emblem - Vellfire		66.79
17.	1	Rear end panel		785.60
18.	1	Rear end panel top garnish		212.50
19.	2	Rear bumper mounting bracket ?	85.00	170.00
20.	1	Rear windscreen glass moulding		122.70
21.	1	Rear floor deck box		326.20
22.	1	Rear floor board Number 1		456.30
23.	1	Rear floor board Number 2		476.33
24.	1	Rear floor board number 3		256.22

CONTINUE / ...



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643.

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA Insurance (Singapore) Pte Ltd

8 Shenton Way

#27-01 Singapore 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : ES004952

Date : 23/12/2017

Vehicle Num. : SKV 6527L

Make/Model : Toyota Vellfire

Chassis/Eng# : JTNGF3DH708000119

Accident Date : 21/12/2017

Claim No. : TP AXA

Reference : -

Policy No. : MSD/VPCP/17-001930

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	Rear floor board plate upper number 1 ?		102.50
26.	1	Rear floor board plate upper number 2 ?		102.50
27.	1	Utility sub - box R ✓		400.75
28.	1	Rear seat cross member number 1 R -		1,718.70
29.	1	Rear seat cross member number 2 R -		1,718.70
30.	1	Spare wheel anchor screw ?		45.70
31.	1	Rear floor panel R ✓		755.43
32.	1	Rear floor panel reinforcement -		179.60
33.	1	Rear floor panel bracket R ✓		67.50
34.	4	Hole plug 2PCS - 3PCS	25.60	102.40
35.	1	Rear keyless entry sensor R -		179.40
36.	1	Rear keyless entry buzzer R -		246.73
37.	2	Tail lamp R ✓	674.50	1,349.00
38.	2	Boot lamp R ✓	647.55	1,295.10
39.	1	Front bumper - R ✓		792.40
40.	1	Front bumper sponge R ✓ ?		129.75
41.	1	Front bumper reinforcement ?		487.52
42.	1	Front bumper reinforcement bracket ?		298.60
43.	2	Front bumper retainer - R ✓	93.60	187.20
44.	1	Front bumper lower grille R ✓		107.80
45.	1	Front bumper lower splash guard ?		157.80
46.	1	Front bumper towing cover RH X		214.50
47.	1	Front grille with chrome - CAA		1,345.70
48.	1	Support top garnish ?		269.70
49.	1	Wiper garnish side cover - LH ?		48.90
50.	1	Wiper garnish side cover - RH ?		48.90

CONTINUE / ...



CITY AUTO PTE LTD

Page 3 / 4

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: 892097111

AXA Insurance (Singapore) Pte Ltd
 8 Shenton Way
 #27-01 Singapore 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68304338

Estimate : ES004952

Date : 23/12/2017

Vehicle Num. : SKV 6527L

Make/Model : Toyota Vellfire

Chassis/Eng# : JTNGF3DH708000119

Accident Date : 21/12/2017

Claim No. : TP AXA

Reference : -

Policy No. : MSD/VPCP/17-001930

S/N Quantity Particular

Unit Price Amount SS

51.	2	Bonnet hinge			
52.	1	Bonnet lock	79.34	158.68	
53.	2	Headlamp		176.45	
			4,544.65	9,089.30	
		List TotalSS :			31,865.41
		25.00% Discount SS :			7,966.35
					23,899.06

		SPECIAL NETT ITEMS :			
1.	1	Rear windscreen glass sealant		40.00	
2.	4	Reverse sensor - original		1,566.40	
3.	1	Front number plate		25.00	
4.	1	Front number plate casing		35.00	
		Special Nett Total SS :			1,666.40

LABOUR :

*To check wiring and lighting	30	60.00
*To supply sealant and reseal all weld spot seam & gaps	60	80.00
*To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1200 - 1400	1,700.00
*Spray painting on affected & replace parts	1600	1,800.00
*To use diagnosis computer to reset and recalibrate tailgate and re-activate PWD system	? 150	280.00
*To remove and reinstall rear windscreen glass	100	150.00

CONTINUE / ...