

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vale Oh

Date: 15 Feb 2018

## **Preliminary Advice**

Insured Vehicle No : SHB7715U

TP Vehicle No : SKV6527L

Make : TOYOTA VELLFIRE

Date of Inspection : 28/12/2017

Inspection At : CITY AUTO PTE LTD

Accident Date : 21/12/2017

Assignment Date : 28/12/2017

Est. Duration of Repair : 12-14/Days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...Front & Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,035.46
Revised Amount	:S\$	10,848.98
Check Items (Estimated)	:S\$	17,439.38
Total	:S\$	28,288.36

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.