

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Date:

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CS3/EQI17024730/Gbe2 EQ INSURANCE COMPANY LTD 02-04-2018

COMPLEXSINGAPORE 069110


5 MAXWELL ROAD #17-00 TOWER BLOCK MND

Code: FOI

			Code: EQI			
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	GBB 6509B	Veh. Inspected	SLK 6504Z		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	DM18HO00021	Excess (\$)	0.00		
	Assign From	BAZLIN AHMAD	Assign Date	28/12/2017		
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA LEXUS GS450H	c.c	3456		
	Engine No.	HIDDEN	Year of Reg.	2010		
	Chassis No.	JTHBC96S905021282	Colour	WHITE		
	Odometer	122953 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	245/40Z R18	WEST LAKE	6 mm		
	L/H Front Tyre	245/40Z R18	WEST LAKE	6 mm		
	R/H Rear Tyre	245/40Z R18	WEST LAKE	6 mm		
	L/H Rear Tyre	245/40Z R18	WEST LAKE	6 mm		

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.



Page No.:1 of 1

5.	General Information					
	Accident Date	27/12/2017	Inspect Date / Time	02/01/2018 (10:40 AM)		
	Survey held at	H S AUTOMOTIVE SERVICES				
		2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921				

5a. **Remarks**

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800-\$6,500

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

Report Ref No. CS3/EQI17024730/Gbe2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A **Automotive Assessor** BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.