

ASS. R/C BY:

REF CS/FC18000008 / Airbnz

Special Instruction:

SURVIVOR

ASSIGNMENT (Office)

From (Person): May Chua of First Capital Insurance Date/Time: 02/01/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 6104R Insured: SHC 1760Ynt Workshop m/s Autolution Industrial Pte Ltd Tel: 64909666/0of 19 Ubi Road 4Policy No: \_\_\_\_\_ Claim No: D18000051 MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 26/22017  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2/1 Person Contacted: Horn Vehicle: IN / OUT

Date/Time Action/Instruction ( ) Estimate

SLG 6104R -Xconfirm \$2176.24 @ 4 daysRed: \$2678.72, 55%

REF: Surveillance

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLG 6104R Yr Regn: 2016 March  
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Nissan X-Trail c.o. 1997  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 36054 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JN1JANT32Z0001653  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/60R18  
 R: 225/60R18  
 BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front Rear  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 08/01/18  
 Survey held at: Tan Chong Cubi  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction  
TP 1st Cap

RECEIVED 15 AUG 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time: File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

|     |
|-----|
| 135 |
| 50  |
| 25  |
| 210 |

Report Format: TP

Lump Sum / I.B.I: (\$ 2176.24)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000008/Arb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-01-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHC 1760Y      | Veh. Inspected | SLG 6104R  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | D18000051MFSH  | Excess (\$)    | 0.00       |
| Assign From  | CWS (MAY CHUA) | Assign Date    | 02/01/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                               |                 |            |
|----------------|-------------------------------|-----------------|------------|
| Accident Date  | 26/12/2017                    | Inspection Date | 02/01/2018 |
| Survey held at | AUTOLUTION INDUSTRIAL PTE LTD |                 |            |
| Repairer       | AUTOLUTION INDUSTRIAL PTE LTD |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                             |                                      |
|---------------------------|-------------------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 28-12-2017                                                  | <b>Our Ref No.</b> D18000051MFSH     |
| <b>Accident Date</b>      | 26-12-2017                                                  | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHC1760Y                                                    | <b>Third Party Vehicle.</b> SLG6104R |
| <b>Survey Location</b>    | 19 UBI ROAD 4                                               |                                      |
| <b>Contact Person.</b>    | HAMZAH SA'AD                                                |                                      |
| <b>Contact No.</b>        | 64909666/ 0                                                 | <b>Fax No.</b> 68467483              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                      |
| <b>Contact Person</b>     | NA                                                          | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                                          |                                      |

Hasni -  
Veh not in

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                  |                                |
|--------------------------|----------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | AUTOLUTION<br>INDUSTRIAL PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                               | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | MAY CHUA                         |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0762/17

DATE : 28-DEC-2017

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

S(068877)

TEL : 65073848 / 68543466

FAX : 65073849

ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MR. MOHAMED ELMIE BIN NEKMAT

ADDRESS : 235B JDO CHIAT PLACE

S(427929)

TELEPHONE NO : 90258602

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : \*

VEHICLE NO : SLG6104R

MODEL CODE : JDRNRRT32EWA-----

MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I

ENGINE NO : MR20836474B

CHASSIS NO : JN1JANT32Z0001653

MILEAGE : 33000 KM

DATE IN : 28/12/2017

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 26/12/2017

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLG6104R

| S/NO                 | JOB CODE | NATURE OF JOB                                                                | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|------------------------------------------------------------------------------|-------------------|---------------------------|
| 1                    | ZZ/001   | LABOUR CHARGES TO REPAIR REAR PANEL, REAR R/BACK DOOR AND RENEW REAR BUMPER. | 800.00            | 570 /                     |
| 2                    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME.                                              | 800.00            | 500 /                     |
| 3                    | ZZ/003   | REMOVE AND INSTALL REVERSE SENSOR TO RENEW.                                  | 110.00            | / /                       |
| 4                    | ZZ/004   | RENEW EXHAUST MUFFLER.                                                       | 180.00            | 7 X                       |
| TOTAL LABOUR CHARGES |          |                                                                              | 1890.00           |                           |

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLG6104R

## DAMAGED PARTS &amp; PRICES

| S/NO                                                  | PARTS DESCRIPTION                        | PARTS NUMBER | NETT    | LIST | S/NETT  | REMARKS |
|-------------------------------------------------------|------------------------------------------|--------------|---------|------|---------|---------|
| 1                                                     | SUNDRIES <i>Not Nec</i>                  | NPN          |         |      | 60.00   | X ?     |
| 2                                                     | EMBLEM REAR X-TRAIL <i>Free</i>          | 84895-4CLDA  | 101.30  | ✓    |         |         |
| 3                                                     | EMBLEM REAR NISSAN                       | 84890-4CLDA  | 59.70   | ✓    |         |         |
| 4                                                     | EXHAUST MUFFLER <i>Not Nec</i>           | 20100-4CADA  |         |      | 1082.00 | X ?     |
| 5                                                     | REAR FENDER ARC MLDG LH <i>Not Nec</i>   | 78861-4CEDA  | 150.00  | ? X  |         |         |
| 6                                                     | REAR BUMPER STAY LH <i>Not Nec</i>       | H5211-4CQMA  | 174.80  | ? X  |         |         |
| 7                                                     | REAR BUMPER STAY RH <i>Not Nec</i>       | H5210-4CQMA  | 174.80  | ? X  |         |         |
| 8                                                     | REAR BUMPER REINFORCEMENT <i>Not Nec</i> | 85032-4CCDA  | 533.80  | ? X  |         |         |
| 9                                                     | SENSOR-REVERSE <i>Dozd</i>               | SENSOR       |         |      | 250.00  | ✓       |
| 10                                                    | REAR BUMPER GRILLE GARNISH <i>Del'd</i>  | 85070-1KADA  | 105.00  | ✓    |         |         |
| 11                                                    | REAR BUMPER SIDE BRKT LH <i>re</i>       | 85221-4CEDA  | 35.80   | ✓    |         |         |
| 12                                                    | CLIP REAR BUMPER @ \$1.20 EACH <i>re</i> | 01553-10501  | 7.20    | ✓    |         |         |
| 13                                                    | REAR BUMPER FASCIA <i>Del'd</i>          | 85022-4CEDH  | 623.80  | ✓    |         |         |
| SUB TOTAL                                             |                                          |              | 1966.20 | 0.00 | 1392.00 |         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                                          |              | 393.24  | 0.00 | 0.00    |         |
| GRAND TOTAL                                           |                                          |              | 1572.96 | 0.00 | 1392.00 |         |
| OVERALL TOTAL                                         |                                          |              | 2964.96 |      |         |         |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

## SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLG6104R

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 1890.00   |
| TOTAL SPARE PARTS CHARGES | 2964.96   |
| GRAND TOTAL               | 4854.96 * |

\* All charges do2 not include GST.

## SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

Adrian Lij  
08/01/18  
96893735  
P/p 04Days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7487

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0762/17  
DATE : 28-DEC-2017

FIRST CAPITAL INSURANCE LTD \*\*\* REFER MS FIRST  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848 / 68543466  
FAX : 65073849  
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MR MOHAMED ELMIE BIN NERHAT  
ADDRESS : 235B JOO CHIAT PLACE

TELEPHONE NO : 5(427929)  
: 90258602

4 days

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : \*  
VEHICLE NO : SLG6104R  
MODEL CODE : JDRNRRT32FWA-----  
MODEL/YEAR : X-TRAIL 2.0i ALL MODE 4X4i  
ENGINE NO : MR20B35474B  
CHASSIS NO : JN1JANT3220001653  
MILEAGE : 33000 KM  
DATE IN : 28/12/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 26/12/2017

- 96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGH NO SUG8104R

| S/NO                 | JOB CODE | NATURE OF JOB                                                                | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|------------------------------------------------------------------------------|-------------------|---------------------------|
| 1                    | 22/001   | LABOUR CHARGES TO REPAIR REAR PANEL, REAR H/BACK DOOR AND RENEW REAR BUMPER. | 600.00            | 570.00 *                  |
| 2                    | 22/002   | CHARGES TO SPRAY PAINTING SAME.                                              | 800.00            | 800.00                    |
| 3                    | 22/003   | REMOVE AND INSTALL REVERSE SENSOR TO RENEW.                                  | 110.00            | 110.00                    |
| 4                    | 22/004   | RENEW EXHAUST MUFFLER.                                                       | 180.00            | 100                       |
| TOTAL LABOUR CHARGES |          |                                                                              | 1690.00           | 1180.00                   |

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL66104R

| S/NO                                                   | PARTS DESCRIPTION              | PARTS NUMBER | DAMAGED PARTS & PRICES |      |                |
|--------------------------------------------------------|--------------------------------|--------------|------------------------|------|----------------|
|                                                        |                                |              | NETT                   | LIST | S/NETT REMARKS |
| 1                                                      | SUNDRIES                       | NPN          |                        |      | 60.00 X        |
| 2                                                      | EMBLEM REAR X-TRAIL            | 04090-ACLOA  | 101.30                 |      | OK             |
| 3                                                      | EXHAUST MUFFLER                | 20100-4CADA  |                        |      | 1082.00 X      |
| 4                                                      | REAR FENDER ARC MOLD LH        | 7B061-4CEDA  | 150.00                 |      | X              |
| 5                                                      | REAR BUMPER STAY LH            | 15211-4COPA  | 174.80                 |      | X              |
| 6                                                      | REAR BUMPER STAY RH            | 15210-4COPA  | 174.80                 |      | X              |
| 7                                                      | REAR BUMPER REINFORCEMENT      | 8B032-4CLOA  | 533.80                 |      | X              |
| 8                                                      | SENSOR-REVERSE                 | SENSOR       |                        |      | 250.00 OK      |
| 9                                                      | REAR BUMPER GRILLE GARNISH     | 8B070-1XAGA  | 105.00                 |      | OK             |
| 10                                                     | REAR BUMPER SIDE BRKT LH       | 8B221-4CEOA  | 35.60                  |      | OK             |
| 11                                                     | CLIP REAR BUMPER B \$1.20 EACH | 01553-10501  | 7.20                   |      | OK             |
| 12                                                     | REAR BUMPER FASCIA             | 8B022-4CEOH  | 623.60                 |      | OK             |
| 13                                                     | EMBLEM REAR NISSAN             | 04890-4CLOA  | 59.70                  |      | OK             |
| SUB TOTAL                                              |                                |              | 932.80                 | 0.00 | 250.00         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%) |                                |              | 186.56                 | 0.00 | 0.00           |
| GRAND TOTAL                                            |                                |              | 746.24                 | 0.00 | 250.00         |
| OVERALL TOTAL                                          |                                |              | 996.24                 |      |                |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SL651048

|             |         |
|-------------|---------|
| NETT ITEM   | 932.60  |
| LESS 20.00% | -186.56 |
| NETT AMOUNT | 746.24  |

|             |      |
|-------------|------|
| LIST ITEM   | 0.00 |
| LESS 50.00% | 0.00 |
| LIST AMOUNT | 0.00 |

|                     |        |
|---------------------|--------|
| SPECIAL NETT ITEM   | 250.00 |
| LESS 00%            | 0.00   |
| SPECIAL NETT AMOUNT | 250.00 |

|                           |         |
|---------------------------|---------|
| TOTAL LABOUR CHARGES      | 1180.00 |
| TOTAL SPARE PARTS CHARGES | 996.24  |

|               |         |
|---------------|---------|
| TOTAL CHARGES | 2176.24 |
| ADD 7 % GST   | 152.34  |

|             |         |
|-------------|---------|
| GRAND TOTAL | 2328.58 |
|-------------|---------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                    |                 |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                    |                 | Ref : CS/FCI18000008/Arbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                    |                 | Date : 17-08-2018          |  |
|                                                                                                                                                                                        |                                                                    |                 | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                    |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 1760Y                                                          | Veh. Inspected  | SLG 6104R                  |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                    | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                              | D18000051MFSH                                                      | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                            | MAY CHUA                                                           | Assign Date     | 02/01/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                    |                 |                            |                                                                                     |
| Make & Model                                                                                                                                                                           | NISSAN X-TRAIL                                                     | c.c             | 1997                       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                             | Year of Reg.    | 2016                       |                                                                                     |
| Chassis No.                                                                                                                                                                            | JN1JANT32Z0001653                                                  | Colour          | BLACK                      |                                                                                     |
| Odometer                                                                                                                                                                               | 36054                                                              | Steering        | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                           | Modification    | STANDARD ALLOY RIM         |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                               |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                    |                 |                            |                                                                                     |
|                                                                                                                                                                                        | Size                                                               | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 225/60 R18                                                         | DUNLOP          | 6 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 225/60 R18                                                         | DUNLOP          | 6 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 225/60 R18                                                         | DUNLOP          | 6 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 225/60 R18                                                         | DUNLOP          | 6 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                    |                 |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                    |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                    |                 |                            |                                                                                     |
| Accident Date                                                                                                                                                                          | 26/12/2017                                                         | Inspection Date | 08/01/2018                 |                                                                                     |
| Survey held at                                                                                                                                                                         | AUTOLUTION INDUSTRIAL PTE LTD<br>19 UBI ROAD 4<br>SINGAPORE 408623 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                    |                 |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                    |                 |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                    |                 |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                    | 4 Working Days  |                            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6104R

| Qty                         | Description of Parts                                                         | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                              |               |                           |                   |
| 1                           | EMBLEM REAR X-TRAIL (N)                                                      | NECESSARY     | 101.30                    | 101.30            |
| 1                           | EMBLEM REAR NISSAN (N)                                                       | NECESSARY     | 59.70                     | 59.70             |
| 1                           | REAR FENDER ARC MLDG LH (N)                                                  | NOT NECESSARY | 150.00                    | -                 |
| 1                           | REAR BUMPER STAY LH (N)                                                      | NOT NECESSARY | 174.80                    | -                 |
| 1                           | REAR BUMPER STAY RH (N)                                                      | NOT NECESSARY | 174.80                    | -                 |
| 1                           | REAR BUMPER REINFORCEMENT (N)                                                | NOT NECESSARY | 533.80                    | -                 |
| 1                           | REAR BUMPER GRILLE GARNISH (N)                                               | DEFORMED      | 105.00                    | 105.00            |
| 1                           | REAR BUMPER SIDE BRKT LH (N)                                                 | NECESSARY     | 35.80                     | 35.80             |
| 6                           | CLIP REAR BUMPER @\$1.20 (N)                                                 | NECESSARY     | 7.20                      | 7.20              |
| 1                           | REAR BUMPER FASCIA (N)                                                       | DEFORMED      | 623.80                    | 623.80            |
|                             | LESS 20% DISCOUNT                                                            |               | -393.24                   | -186.56           |
|                             |                                                                              |               | 1,572.96                  | 746.24            |
| <b>SPECIAL NETT ITEMS</b>   |                                                                              |               |                           |                   |
| 1                           | SUNDRIES (SN)                                                                | NOT NECESSARY | 60.00                     | -                 |
| 1                           | EXHAUST MUFFLER (SN)                                                         | NOT NECESSARY | 1,082.00                  | -                 |
| 1                           | SENSOR-REVERSE (SN)                                                          | DAMAGED       | 250.00                    | 250.00            |
|                             |                                                                              |               | 1,392.00                  | 250.00            |
| <b>LABOUR</b>               |                                                                              |               |                           |                   |
|                             | LABOUR CHARGES TO REPAIR REAR PANEL, REAR H/BACK DOOR AND RENEW REAR BUMPER. |               | 800.00                    | 570.00            |
|                             | CHARGES TO SPRAY PAINTING SAME.                                              |               | 800.00                    | 500.00            |
|                             | REMOVE AND INSTALL REVERSE SENSOR TO RENEW.                                  |               | 110.00                    | 110.00            |
|                             | RENEW EXHAUST MUFFLER.                                                       | NOT NECESSARY | 180.00                    | -                 |
|                             |                                                                              |               | 1,890.00                  | 1,180.00          |
| <b>GRAND TOTAL</b>          |                                                                              |               | <b>4,854.96</b>           | <b>2,176.24</b>   |

|                                    |  |  |                 |
|------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF REPAIRS</b> |  |  | <b>2,176.24</b> |
|------------------------------------|--|--|-----------------|

Report Ref No. CS/FCI18000008/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.