

Q. No. 138

VEHICLE NO : SHB 4335C

DATE 29/12/2017 15:07

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH) ✕			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 2,101.48
	Kalut ICCV ✓ 29/12/17 1610hr 2 Days PIP Before Paint photo			
	LKK Auto Consultancy will notify the Repairer of the following: • To resurvey before spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer Signature:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.