



TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBE2010H

1. Towing - \$35
 2. Front wheel rim - \$250
 3. Front bearing - \$50
 4. Front wheel shalf - \$40
 5. Front brake disc - \$130
 6. Front fork assy lh - \$290
 7. Front fork assy rh - \$290
 8. Front fork under bracket - \$180
 9. Steering cone bearing - \$90
 10. Front fender - \$95
 11. P plate - \$10
 12. Head cowling - \$150
 13. Windscreen - \$90
 14. Head light - \$280
 15. Lamp stay - \$80
 16. Front signal rh - \$45
 17. Handlebar - \$120
 18. Handlebar balancer - \$30
 19. Side mirror lh / rh - \$90
 20. Brake lever - \$25
 21. Fuei tank - \$550
 22. Fuel tank side cover rh - \$130
 23. Brake pedal - \$80
 24. Front foot rest - \$55
 25. Exhaust pipe - \$480
 26. Exhaust cover - \$90
 27. Side cover rh - \$120
 28. Tail board rh - \$90
 29. Top box - \$160
 30. Top box rack - \$80
 31. Rear signal rh - \$45
 32. Rear body alignment - \$450
 33. Labour - \$550
- Total - \$ 5250