

India Insurance

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: INDIA INTERNATIONAL INSURANCE	DATE	: 26/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKX5343X		
MODEL	: TOYOTA WISH 1.8A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>	DATE : 23-Dec-17		
	TIME : 01:00HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR DOOR RH ✓ DD	1	\$ 1,422.30	\$ 1,422.30
2	FRONT DOOR DOOR OUTER CHROME ✓ DD NEC	1	\$ 390.00	\$ 390.00
3	FRONT DOOR LOCK ?	1	\$ 488.30	\$ 488.30
4	FRONT DOOR CATCH ?	1	\$ 105.00	\$ 105.00
5	FRONT DOOR WEATHERSTRIPE ✓ NEC	1	\$ 202.50	\$ 202.50
6	CENTRE PILLAR (OUTER) RH R	1	\$ 1,055.30	\$ 1,055.30
7	REAR DOOR RH ✓ DD	1	\$ 1,280.20	\$ 1,280.20
8	REAR DOOR DOOR OUTER CHROME ✓ NEC	1	\$ 390.00	\$ 390.00
9	REAR DOOR HINGE ? DD DD P	2	\$ 102.50	\$ 205.00
10	REAR DOOR CHECKER X	1	\$ 166.30	\$ 166.30
11	REAR DOOR INNER BOARD ?	1	\$ 755.30	\$ 755.30
12	REAR DOOR REGULATOR ?	1	\$ 322.20	\$ 322.20
13	REAR DOOR POWER WINDOW MOTOR ?	1	\$ 688.80	\$ 688.80
14	REAR DOOR WEATHERSTRIPE ✓ NEC	1	\$ 202.50	\$ 202.50
15	ROCKER PANEL RH ?	1	\$ 1,133.20	\$ 1,133.20
16	REAR SIDE SKIRT ✓ SCR / DD	1	\$ 755.20	\$ 755.20
17	REAR FENDER RH ✓ DD / DD	1	\$ 1,020.00	\$ 1,020.00
18	REAR FENDER INNER COWLING LH ?	1	\$ 225.00	\$ 225.00

19	REAR FENDER QUARTER GLASS WITH MOULDING ?	1	\$ 480.00	\$ 480.00
----	---	---	-----------	-----------

TOTAL PRICE \$ 11,287.10

LESS 25% \$ 2,821.78

SUB TOTAL PRICE \$ 8,465.33

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR INNER BOARD CLIPS(SET) ✓ NRC	1	\$ 22.00	\$ 22.00
2	REAR FENDER SEALANT RH ✓ NEC	1	\$ 80.00	\$ 80.00
3	REAR FENDER INNER COWLING CLIP (SET) ✓ NEC	1	\$ 23.00	\$ 23.00
4	SIDE SKIRT CLIPS(SET) ✓ NEC	1	\$ 20.00	\$ 20.00
5	REAR WINDSCREEN SEALANT ✓ NEC	1	\$ 80.00	\$ 80.00
6	REAR WINDSCREEN INNER SEAL X	1	\$ 120.00	\$ 120.00

TOTAL \$ 345.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	800.	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000	
3	TUFF COAT	\$ 250.00	X	
4	WIRING AND BULB CHECK	\$ 80.00	X	
5	REMOVE AND REFIX QUARTER WINDSCREEN Glass	\$ 120.00	100.	
6	REMOVE FRONT & REAR DOOR MECHANISM	\$ 220.00	180.	

TOTAL \$4,270.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,810.33

TOTAL LABOUR COST : \$ 4,270.00

TOTAL REPAIR COST : \$ 13,080.33

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

wilson@lkkauto.com

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> ✓ To resurvey before/after spray painting ✓ To display damaged part(s) during resurvey ✓ Parts prices are subject to confirmation ✓ Third party survey is on a "Without Prejudice" basis ✓ No illegal modification(s) is allowed ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--

*Without Prejudice
Lump Sum
Resurvey After Paint
Part Price Subject to Confirmation
5 Days Repair
27/12/2017*

CONTACT NUMBER :

FAX NUMBER :