

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 05 Jan 2018

Preliminary Advice

Insured Vehicle No	: GBB7647D		
TP Vehicle No	: SJW3299X	Accident Date	: 30/12/2017
Make	: HYUNDAI AVANTE	Assignment Date	: 03/01/2018
Date of Inspection	: 04/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,209.90
Revised Amount	:S\$	6,453.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,453.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
SOME OF THE PARTS,PENDING FOR PARTS PRICES.