

MSG (WINNER)
 REPORT on RECOVERY -
 EMAIL ON 28/12/17

PDI TUAS

PDI TUAS

LOO GUAT KHIAW
 286B TOH GUAN ROAD
 #21-34
 Singapore, 602286
 Singapore

Phone No.
 Fax No.
 E-Mail

VAT Registration No. M20098505-2
 Tax No. 199101494Z

Service Quote

Customer No. CV032884
 Quote No. SER/QUO/1702010
 QuoteDate 04/12/17
 Salesperson Jimmy Lee
 Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 VNA	21,039	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SFG15A	WVGZZZ5NZGW065089	29/02/16	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 240347	5N22QY

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT	475	950
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT	500	1000
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		200.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		360.00
	Sum Labor				4,460.00
P 1Q0853675Q GQF	NAME PLATE TSI	1	Pieces		66.73
P 1T0919133C 9B9	PARKING SENSOR O RING	4	Pieces		3.00
P 5N0807305	RR BUMPER REINFORCEMENT	1	Pieces		554.95
P 5N0807393E	BUMPER BRACKET LHS Use Predecessor 5N0807393B	1	Pieces		27.46
P 5N0807394D	BUMPER BRACKET RHS Use Predecessor 5N0807394B	1	Pieces		27.46
P 5N0807421G GRU	REAR BUMPER	1	Pieces		1,313.62
P 5N0807521AFGRU	REAR LOWER SPOILER	1	Pieces		459.45
P 5N0807568 2Z0	REAR LOWER SPOILER INSERT Use Predecessor 5N0807568	1	Pieces		509.38
P 5N0853630 FXC	VW SIGN	1	Pieces		92.25
P 5N0853675M CWB	NAME PLATE BLUE MOTION	1	Pieces		80.28
P 5N0853687B 739	NAME PLATE TIGUAN	1	Pieces		104.56
P 5N0919397	SENSOR BRACKET	1	Pieces		15.42
P 5N0919398	SENSOR BRACKET	1	Pieces		17.05
P 5N0919491D	SENSOR BRACKET	2	Pieces		51.14
P D 180KU2A1	2KADHESIVE	1	Pieces		103.65
	Sum carried forward				7,886.40

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

LOO GUAT KHIW
286B TOH GUAN ROAD
#21-34
Singapore, 602286
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032884
Quote No. SER/QUO/1702010
QuoteDate 04/12/17
Salesperson Jimmy Lee
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 VNA	21,039	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SFG15A	WVGZZZ5NZGW065089	29/02/16	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 240347	5N22QY

		Continued	7,886.40
P D 822150A1	BONDAGENT	1 Pieces	74.16
	Sum Item		3,500.56

	Sum Labor	4,460.00
	Sum Item	3,500.56

Total	SGD	7,960.56
7% GST		557.24
Total SGD Incl. GST		8,517.80

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Rasul
Hp 90010068
4-5 days
04/01/18 @ 0930
EXCESS: 500
REVERT
Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to:

- BBN: - Acc.-No.: