meimen — rom (Person): stimated Cost		_ of0	151(1	Date/Ti	me: 04012018 9-47am
	TP RES / OD RES / EV	VA/INV/MV/O	Bill to:	Insured:	SCR 1193J
t Workshop n	VsW	ng Solution		Tel: 6	744 465
f	23	Kaki Bukt	Ave 4 #0	1-(BB	
olicy No:	2861 E034AVW	2002000 00 0000	Claim No:	543615	
Sum Insured:_			Excess:		
Make of Veh: Client's Record				D.O.A.	30122017
CA / REV /	REP. / REV 24 HRS			н.о.н). Endorsement:
Date/Time:	04012018 10-09cm	Person Contacted.	Juck	Vehicle(DELOUT
)ate/Time	Action/Instruction (/) Estimut			
	23c - FJP66 2[2	5/TINC 1 2006	715 / Kan-1		DOA: ULUH2012
	X - [EIPH AD2		-		
	2 1	menmen	Cremin	a estima	te)
21	THE WORLD IN IN				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	0.111011011011011011011011	Affiliated to Federation Internation	D-4		
MSI	G INSURANCE (SI	NGAPORE) PTE LTD	Ref : CS/MSG180002	D4/AQD	
	AFFLES QUAY 01 HONG LEONG	BLDG SINGAPORE 048581	Date: 04-01-2018 Code: MSG		
1.	CONTRACTOR OF THE PARTY OF THE	Policy Particulars	:- THIRD PARTY CLAIM	l de la companya de	
	Insured Veh.	SCR 4913J	Veh. Inspected	SJC 6696T	
	Policy No.	28615034AVW	Coverage (\$)	0.00	
	Claim No.	543615	Excess (\$)	0.00	
	Assign From	MERIMEN (KATHERINE WONG)	Assign Date	04/01/2018	
2.		Vehicle Parti	culars & Condition	高型高价的高键型 (2017)	
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer -		Steering		
	Brakes		Modification		
	General				
3.		Condit	ions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Descripti	on of Damages		
5.	Engine No. 2	Genera	Il Information	Mark To the State of the State	
	Accident Date	30/12/2017	Inspection Date	04/01/2018	
	Survey held at	MG SOLUTION PTE LTD			
	100	23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE SINGAPORE 415933	,		
5a.		R	temarks		

STC 66967 Reference No.: Comsel 8000354 Agb Policy Type: OD / TP / TP RES / TL / EVA Typist Case Handler): Case handler to make sure all Information created by the assignment team are ACCURATE. Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C Customer Code Assign From N Assign Date C Veh No (Inspected) C Veh No (Insured) C D.O.A C C Policy No C Claim No Insurance Authorisation (CA /REV/REP) C Report Type C Weekend Charges C Survey held at/Repairer N C Excess): Case handler to make sure the surveryor completed all required information. Surveyor ((1) Assignment Form C Vehicle No Regn Month/Year C Vehicle Type Make & Model Engine Capacity. (C.C) C Colour N C Odometer. (Sp.Reading) Chassis No. C General Condition N Steering N Brake Modification (Modi) N Tyre Size C N Tyre Make Tyre Balance C C Date of Inspection Survey held N Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition N C Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair C Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded Check By:

Date

Survey Department Check List (Case Handler)

Case Handler

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	02 Jan 2018		04 Jan 2018 09:47 Assign				New Assignm Cancel Case	A CONTRACTOR OF THE PROPERTY O
	Main	Re	ference	Clai	m Details	Docum	ents	Show All
CLAIM S	UBFOLDER DET	AILS		CARRY LANCE SHE SHARE		[Created I	oy insurer]	
Insured:		TAN TOO KUI	CHRIS, ID: S69	009231				
Main Clai	mant:	HON SERVICE	S, Co. Reg. No.	: 53316720E				
Vehicle R	leg. No.:	SJC6696T		Da	te of Loss:	30/12/2017	15:00 - :59	
Claim Ty	pe:	TP / 543615		Po	licy/Cover Note I	No.: 28615034A Coverage:	VW 17/09/2017 - 16	/09/2018
Vehicle Reg. No. (Insured):		No. SCR49133		Po	Policy No. (Claimant):			
				Ex	cess:			
Repairer		91886931				OM Inspection Cent		
Handling	Insurer:	Shong - 6594	2544]	0.0000000000000000000000000000000000000		7888 [Handled by		ng Chew
Adjuster	10	LKK Auto Con	sultants Pte Ltd	(HQ) - Tel: 62	56-3561 [Imn	n.Advice due 05	/01/2018]	
Driver/C (Insured	ustodian):	TAN TOO KUI	CHRIS (), NRIC:	S6900923I				
Adj Asg.	Remarks:	Please assign N	4r Adrian Ling Wai	Ping to survey	, Thank You.			
ASSOCT	ATED MAIL REC	ETVED				View	All I Compos	se Case Mail
						view	Compos	se case Maii
There are	no mail for this o	ase.						
E								
ALL ASS	OCIATED TASK	(S			View All Se	arch Tasks Cr	reate New Task	Complete
Due Da	te Priority	Type Task (Froup Subjec	t Handler	Assigned By	Completed O	n Created	On Done?

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Katherine Wong Chew Shong

Date: 23 Feb 2018

Preliminary Advice

Insured Vehicle No : SCR4913J

TP Vehicle No

: SJC6696T

Accident Date

: 30/12/2017

Make

: HONDA STREAM

Assignment Date

: 04/01/2018

Date of Inspection : 04/01/2018

Est. Duration of Repair

Inspection At

: MG SOLUTION PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,676.16
Revised Amount	:S\$	1,953.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,953.44
Lump Sum Repair	:S\$	1,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	;S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

,	1	The vehicle	is economical/not	economical	for repair.
		the vehicle	s economicalmo	economical	ioi iopan.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with:

*SJC6696T (543615) [SCR4913J] TP

HON SERVICES
Dec 30 2017 3:00PM
[TAN TOO KUI CHRIS]
MG Solution Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 05/01/2018 12:12 PM.

To katherine_wong@sg.msig-asia.com

CC siewsc@lkkauto.com

Subject SJC6696T (543615) [SCR4913J]

Dear Sir/Madam

Please be informed that we have inspected the vehicle SJC 6696T on 04/01/2018 We are pending estimate from repairer.

Best Regards, Denise Tay | Case Handler LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Business	
Owner ID:	6720E	
Vehicle Details		
Vehicle No.:	SJC6696T	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	04 Jan 2018	
Vehicle Make:	HONDA	
Vehicle Model:	STREAM 1.8L A	
Primary Colour:	Blue	
Manufacturing Year:	2007	
Engine No.:	R18A12801835	
Chassis No.:	JHMRN68408S201833	
Maximum Power Output:	103.0 kW (138 bhp)	
Open Market Value:	\$20,001.00	
Original Registration Date:	26 Feb 2008	
First Registration Date:	26 Feb 2008	
Transfer Count:	3	
Actual ARF Paid:	\$22,002.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	25 Feb 2018	
PARF Rebate Amount:	\$11,001,00	
Intended COE Rebate Details		
COE Expiry Date:	25 Feb 2018	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$15,989.00	
COE Rebate Amount:	\$233.00	
Total Rebate Amount:	\$11,234.00	

The information contained herein is correct as at 04 Jan 2018

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



ANNOUNCING BENEFIT AUTO

as sgCarMart Premium Dealer for the 4th Consecutive Year



Honda Stream

Price Range

▼ Depreciation ▼ 2008

▼ Vehicle Type

Used Car Comparison

--- Comparing 3 Vehicles ---

Honda Stream 1.8A

Honda Stream 1.8A X

Honda Stream 1.8A











Use search bar above to se

Clear All

Add all to Shortlist Back to search result

Add to Shortlist

\$13,099

Add to Shortlist

Add to Shortlist

to compare.

CAR DETAILS

Price
Instalment
Registration Date
Manufactured
Mileage
Transmission
Engine Cap
Road Tax

Accessories

Description

COE

OMV

ARF

Depreciation No. of Owners

Type of Vehicle

Category

Availability

N.A. 31-Jan-2008 2007 120,000 km

Auto 1,799 cc \$978 /yr

Power 103.0 kW (138 bhp) **Curb Weight** 1,370 kg

Features Responsive 1.8L I-VTEC Engine, 5 Speed Auto Transmission, ABS, Dual SRS Airbags, Immobilizer, Digital Climatic Control Aircon, Retractable Mirrors.

\$15,989

\$20,252

\$22,278

PARF Car

Available

2

Leather Seats, Audio/CD Player. Knockdown Rear Seats, Reverse Sensors, Tinted Films, Remote Alarm.

Great Running Engine And Smooth Transmission, Good For Short Term Usage To Decide Your COE Renewal Direction Until 30th Jan 2018, Minimum PARF \$11,139 Excluding Body Value. Please Call For A Viewing Schedule To Avoid Disappointment.

\$13,800

\$9,684 25-Feb-2008

Auto

2007

1,799 cc \$978 /yr

\$13,209

\$18,620

\$20,482

2

MPV

PARF Car

Available

103.0 kW (138 bhp)

1,350 kg 1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Auto Climatic

Sport Rims, Sony Car Stereo System, Front Recording Camera, Roof Mount Monitor, Electrical Retractable Side Mirrors, Upholstery Leather Seats.

Aircon Control, Knockdown Rear Seats.

Monthly At \$950 Only! Ideal For Short Term Usage! Good Fuel Economy At 14.8km/L! Proven To Be Accident Free! Well Kept By Previous Owner, Test Drive And See It For Yourself! Buy It From Us With A Peace Of Mind, Professional After Sales Service Assured. Drop By Our Aircon Showroom To Appreciate It In Pristine Condition Now, Don't Miss It!

\$14,800

28-Mar-2008 2008

\$5,206

1,370 kg

Auto 1,799 cc

\$978 /yr 103.0 kW (138 bhp)

1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Auto Climatic Aircon Control, Reverse Sensors, Knockdown Rear Seats, 4 x Disc Brake.

Sports Rims, Pioneer Touchscreen Audio System, Solar Film, Roof Mount Monitor, Electrical Retractable Side Mirrors, Upholstery Leather Seats.

Excellent Choice For Either Short Term Usage Or Renewal Of COE! STA Evaluated Cars! Well Kept In Tip Top Condition, A Unit You Must View To Believel Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come Visit Us At Our Aircon Showroom To Appreciate It In Pristine Condition Now, Before It's Gonet

\$18,000 \$20,486 \$20,486 3 PARE Car Available

SELLER INFORMATION

Used Car Compare & Comparison | Singapore Cars - sgCarMart

Seller	5 Star Automobiles Pte Ltd	Dickson Automobile	Dickson Automobile	
Address	18 Sin Ming Lane #02-09	55 Ubi Avenue 3 #01-01	55 Ubi Avenue 3 #01-01	
Office Number	66100055	68447667	68447667	*
Contact Person		Jonathan Quah / Ricky Eng / Eric Lee		
Contact Number		January Quality Ricky Eng / Eric Lee	Steven Lee / Jonathan Quah / Ricky Eng	•
Contact Number	87	91901666 / 91853390 / 91827304	83832206 / 91901666 / 91853390	
	· property and the second	Record of the second		

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Missubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, varis, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpank rates 8 car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

- Home
 New Car
 Used Car
- Sell Car
 Motoring Directory
 Products Guide
 Article

- Forum
 Tool & Tip

© 2004-2018 sgCarMart. All rights reserved.

- About Us
 Careers
 Contact Us
 Sitemap

- Terms of Service
 Privacy Policy
 Personal Data Protection Statement

MVA318000727 / VAC - Kaki Bukit ENTRY DATE & TIME: 02/01/2018 16:30 SUBMITTED BY: Norhaini Bite Abdul Majid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	02/01/2018 16:30
Date Of Accident	30/12/2017 15:55
Exact Location Of Accident	CTE TOWARDS SLE BEFORE JALAN BAHAGIA
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJC6696T
Insured/Policyholder	
Name Of Registered Owner	HON SERVICES
Co Reg No	53316720E
Email Address	NOEMAIL
Mobile Phone No	

OFFICE-86555043

Alternative Phone No. Vehicle Particulars

Manufacturer HONDA

Model STREAM 1.8L A

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

NO

Policy Number

5096921162 TPFT

Cover Note Number

Driver

Name of Driver HON HSIEH YING

NRIC No S8912874I Date Of Birth 16/04/1989 Occupation OUTDOOR Date Of Driving Pass 06/09/2013

Driving Experience 4 YEARS AND 3 MONTHS

Gender

(LOCAL) +65-86555043

Mobile Number Fax Number

MALE

Contact Number

EMail Address

NOEMAIL

Address

BLK 551 JURONG WEST ST 42 #04-243

Postcode

640551

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle.

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver) Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SCR4913J

Vehicle Make/Model/Colour

VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T TL 1632G5

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1



MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933 Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO

: MSIG INSURANCE

DATE

03/01/2017

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE T/P CLAIM

ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO

: SJC6696T

MODEL

: HONDA STREAM 1.8 A

CHASSIS NO

ACCIDENT DETAILS

DATE : 30-Dec-18

TIME : 16:30HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER John Pyris	1	\$ 833.50	\$ 833.50	K
2	FRONT BUMPER SIDE RETAINER RH	1	\$ 83.00	\$ 83.00	-
3	HEADLAMP RH M	1	\$ 655.20	\$ 655.20	4
4	HEADLAMP LOWER BRACKET RH	1	\$ 84.90	\$ 84.90	4
5	FRONT FENDER RH Derted	1	\$ 922.50	\$ 922.50	4918
6	FRONT FENDER INNER COWLING RH	1	\$ 184.60	\$ 184.60	1
7	FRONT DOOR RH Pyris	1	\$ 1,120.00	\$ 1,120.00	4
8	FRONT SIDE MIRROR	1	\$ 630.00	s 630.00	×
9	FRONT LOWER ARM RH	1	\$ 412.00	s 412.00	£
10	FRONT KNUCKLE ARM RH	1	\$ 322.00	\$ 322.00	8
11	FRONT KNUCKLE ARM BEARING RH	1	\$ 233.00	\$ 233,00	K
12	FRONT SHOCK ABSORBER RH	1	\$ 412.00	\$ 412.00	×

491.80 393.44 TOTAL PRICE

\$5,892.70

LESS 20%

\$ 1,178.54

SUB TOTAL PRICE

\$4,714.16

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	----------------	-----------------

FRONT BUMPER CLIP(SET)	1	\$	22.00	\$	22.00
FRONT FENDER INNER COWLING CLIP(SET)	1	\$	22.00	\$	22.00
FRONT WHEEL TYRE (SET)	1	s	350.00	S	350.00
4 FRONT WHEEL RIM (SET) at	1	s	850.00	S	850.00

ASO TOTAL

\$1,222.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED	
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$500.00	400.		
2	TO SPRAY PAINT AFFECTED AREA	\$600.00			
3	WIRING CHECK	\$30.00	_		
4	TO TRANSFER FRONT DOOR MECHANISM	\$150.00	+		
5	FRONT WHEEL ALIGHMENT	\$80.00	/		
6	REMOVE AND REFIX FRONT UINDERCARRIAGE	\$380.00	×		

1110

TOTAL

\$1,740.00

ESTIMATE REPORT

TOTAL PARTS COST : TOTAL LABOUR COST :

TOTAL REPAIR COST :

APPROVED DETAILS

\$5,936.16 \$1,740.00 \$7,678.16

7698.16

EXCESS

NO. OF WORKING DAY:

RE-SURVEY

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Adria 5 04/01/18 45 04 Days. -18 \$1.5k. 865 total 1953 HH.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18000254/AQBN2

Date:

28/02/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28615034AVW

Claimant

Vehicle No:

SJC6696T

Insured Vehicle No:

SCR4913J

Date of Loss:

30/12/2017

Nature of Claim:

TP

Claim No: 543615

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJC6696T

Make & Model:

HONDA STREAM, 1.8 L (A) 26/02/2008 (Man. Year: 2007) Engine No: Chassis No: R18A12801835

Reg. Date: Colour:

Odometer:

JHMRN68408S201833 161894 km

Engine Capacity:

1799 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Market Value/New Car Price:

Front Tyre Size:

225/45R17 Pirelli 6 mm Rear Tyre Size: Rear Left Side:

225/45R17

Front Left Side: Front Right Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 5,958.16	Adjuster's 843.44	Difference	Diff %
Miscellaneous Items	0.00	0.00	5,114.72 0.00	85.84
Labour	1,740.00	1,110.00	630.00	36.21
Paintwork Labour	0.00	0.00	0.00	00.21
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,698.16	1,953.44	5,744.72	74.62
Approved Total (Overridden) (S\$)		1,500.00	10-9-03200.001000	
(S\$)	7,698.16	1,500.00	6,198.16	80.51
+ GST 7.00/7.00% (S\$)	538.87	105.00	433.87	80.51
Nett Amount (S\$)	8,237.03	1,605.00	6,632.03	80.51

INSPECTION

Date of Assignment:

04/01/2018

Date Inspected:

04/01/2018 Inspected At:

MG Solution Pte Ltd (HQ)

23 Kaki Bukit Avenue 4 #02-03B,

VICOM Inspection Centre Singapore 415933

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2018)

Parts: M1-MPV HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJC6696T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	833.50 FL	*-FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	83.00 FL	*-FL
3	1		*HEADLAMP RH	Not Necessary	655.20 FL	*-FL
4	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	84.90 FL	*-FL
5	1		*FRONT FENDER RH	Dented	922.50 FL	*491.80 FL
6	1		*FRONT FENDER INNER COWLING RH	Not Necessary	184.60 FL	*-FL
7	1		*FRONT DOOR RH	Repair	1,120.00 FL	*- FL
8	1		*FRONT SIDE MIRROR	Repair	630.00 FL	*- FL
9	1		*FRONT LOWER ARM RH	Not Necessary	412.00 FL	*-FL
10	1		*FRONT KNUCKLE ARM RH	Not Necessary	322.00 FL	*-FL
11	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	233.00 FL	*-FL
12	1		*FRONT SHOCK ABSORBER RH	Not Necessary	412.00 FL	*-FL
13	1		*SET FRONT BUMPER CLIP	Not Necessary	22.00 FS	*-FS
14	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	22.00 FS	*-FS
15	1		*SET FRONT WHEEL TYRE	Not Necessary	350.00 FS	*- FS
16	1		*SET FRONT WHEEL RIM	Cut	850.00 FS	*450.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	7,136.70	941.80
			- List Item Discount on L Items	20.00/20.00% (S\$)	1,178.54	98.36
				Total Parts (S\$)	5,958.16	843.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	500.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	600.00	600.00
3	WIRING CHECK	New	30.00	30.00
4	TO TRANSFER FRONT DOOR MECHANISM	New	150.00	_
5	FRONT WHEEL ALIGNMENT	New	80.00	80.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	380.00	
	Gross Lal	oour Cost (S\$)	1,740.00	1,110.00
	Report was unsubmitted d	uring this print-out		

< END OF ESTIMATES >