

12/03/2001

ASS. REC. BY:

REF: CS / SMO18000298 / Utd3n2 Special Instructions:

Supervisor:

## ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 9:30am @ 5/01/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SG7551K Insured: YP 6967R

at Workshop m/s Prof Automotive Tel: 9433 5558

of 10 Kaki Bk Rd 2 # 01-03

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 28/12/17  
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

08/01/2017

H.O.D. Endorsement:

Date/Time: 10:43am @ 05/01/2018 Person Contacted: Edward

Vehicle: IN (OUT)

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SG7551K - X                     |
|           | YP6967R - X                     |
|           |                                 |
|           |                                 |
|           |                                 |
|           |                                 |
|           |                                 |

REF: SMO

## ASSIGNMENT

Project: Date: 08/01/2017

Estimated Cost:

QD TP WS TPRES QD RES / EVA / INV / MV

To inspect / Vehicle No: SG77551K  
At Workshop: Profi Automotive  
of 10 kaki Bkt Rd 2 # 01-03

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bel on Market Value

32k.

IDV / Accident Report

Consistent? Yes or No

G / P / Seen

Consistent? Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

20

%

G Val:

Yes or No

QA / REV / REP. / 24 HRS 'wp'

L7A20481  
Vehicle IN / OUT

Date:

Person Contacted

Vehicle

Type: M/Cycle / Boat / Van / Lorry / Taxi / Home Motor

Truck / Trailer

Make

Mits Lancer

Colour

white

Chassis No

168095

Engine

C/V

JmYSTC53A8U003298

Gen Cond: Good / Fair / Poor / Burnt

Steering: Free / Jammed / Leaked / Burnt / or

Brake: Free / Jammed / Leaked / Burnt / or

Mod: Nil / Spdm / STD A/Rim / or

Tyre Size

R

R

205/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO / or

FALKEN

Front

6

R.Rail

6

L.Bal

6

D.O.A

28/12/17

Survey held at

Des of Damages: Fnt / Rear / O/S / N/S / U/O / Roof / or

Rear

The U/O / Chassis frame / Body Structure affected due to St/Bch

Date / Time

Action / Instruction

coe 31/10/2022

8/1/18

confirmed

L/S

4000

with Edward

Red: 5384.35 : 57%

RECEIVED 15 JAN 2018

Cost Time / Fee / Passes

☐

Prelim. Report

☒

Final Report

Cost Time / Fee / Passes

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Ins:

☐

Interior:

☐

Tech. Ins:

☐

Access:

Report Format:

Cost Time / Fee / Passes

4000/-

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Friday, 5 January, 2018 9:30 AM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Ow Edward  
**Subject:** CMTD1800014/THE - ACCIDENT INVOLVING YP6967R & SGZ7551K ON 28.12.2017

Our Reference : CMTD1800014/THE

Dear LKK AUTO/ Marcus,

Please make arrangement to conduct the survey for SGZ7551K.

Please be informed that Thelma Choo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Ow Edward [mailto:profi.automotive@asia.com]  
**Sent:** Friday, January 05, 2018 9:16 AM  
**To:** Teo, Grace  
**Subject:** Re: CMTD1800014/THE - ACCIDENT INVOLVING YP6967R & SGZ7551K ON 28.12.2017  
**Importance:** High

WITHOUT PREJUDICE

Dear Grace,

Our choice is Marcus Chua of LKK Auto Consultants.

Warmest regards,  
Edward Ow

Profi Automotive  
10 Kaki Bukit Road 2,  
#01-03, First East Centre,  
Singapore 417868  
M: 94335558 F: 66048454  
E: [profi.automotive@asia.com](mailto:profi.automotive@asia.com)

**From:** [grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)  
**Sent:** 5 January 2018 09:11  
**To:** [profi.automotive@asia.com](mailto:profi.automotive@asia.com)  
**Cc:** [thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg); [irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)  
**Subject:** CMTD1800014/THE - ACCIDENT INVOLVING YP6967R & SGZ7551K ON 28.12.2017

Our Reference : CMTD1800014/THE  
Your Reference: PA171201-SGZ7551K

Date: 5<sup>th</sup> January 2018

Without Prejudice

Attention:  
M/S PROFI AUTOMOTIVE PTE LTD

ACCIDENT INVOLVING YP6967R & SGZ7551K ON 28.12.2017

Dear Edward,

We refer to your Notice of Accident dated 04/01/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

|   | Motor Surveyor                   | Surveyor                  | Selection (Indicate as tick) |
|---|----------------------------------|---------------------------|------------------------------|
| 1 | Raleigh Services                 | Andrew Ow Yong            |                              |
|   |                                  | Vincent Ng                |                              |
| 2 | LKK Auto Consultants             | Kenneth Kong (North area) |                              |
|   |                                  | Marcus Chua (East area)   |                              |
|   |                                  | Mohd Rasul (West area)    |                              |
|   |                                  | Mohd Taufikh (West area)  |                              |
| 3 | Priority Services                | Jimmy Lee                 |                              |
|   |                                  | Lawrence Ng               |                              |
|   |                                  | Jeffery Ong               |                              |
| 4 | JP Knights Adjusters & Surveyors | Jason Lek                 |                              |

|   |                   |              |  |
|---|-------------------|--------------|--|
| 5 | In House surveyor | Teo See Ling |  |
|   |                   |              |  |
|   |                   |              |  |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Ow Edward [<mailto:profi.automotive@asia.com>]

**Sent:** Thursday, 4 January, 2018 12:39 PM

**To:** claimsreport <[claimsreport@sompo.com.sg](mailto:claimsreport@sompo.com.sg)>

**Subject:** Request for 3rd party claim survey (Direct Settlement) || SGZ755QK against YP6967R

**Importance:** High

WITHOUT PREJUDICE

Our ref: PA171201-SGZ7551K

Your ref: Your insured YP6967R

SOMPO INSURANCE SINGAPORE PTE. LTD

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLE SGZ7551K & YP6967R ON  
28.12.2017 @ 1700HRS**

Please be informed that the said vehicle (SGZ7551K) can be surveyed at:

Name of workshop: **Profi Automotive**

Address: **10 Kaki Bukit Road 2 #01-03, First East Centre, Singapore 417868**

Contact person: **Edward**

Tel: **9433 5558**

Fax: **6604 8454**

Please send your list of surveyor.

Warmest regards,  
Edward Ow

Profi Automotive  
10 Kaki Bukit Road 2,  
#01-03, First East Centre,  
Singapore 417868  
M: 94335558 F: 66048454  
E: [profi.automotive@asia.com](mailto:profi.automotive@asia.com)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                           |   |
|---|--|---------------------------|---|
| SOMPO INSURANCE SINGAPORE PL  |  | Ref : CS/SMO18000298/Utd3 |   |
| 50 RAFFLES PLACE<br>#05-01/06<br>SINGAPORE LAND TOWERS SINGAPORE 048623   |  | Date : 05-01-2018         |  |
|   |  | Code : SMO                |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                           |   |
| Insured Veh.  | YP 6967R   | Veh. Inspected            | SGZ 7551K   |
| Policy No.  |  | Coverage (\$)             | 0.00  |
| Claim No.   |  | Excess (\$)               | 0.00  |
| Assign From   | GRACE TEO  | Assign Date               | 05/01/2018  |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                           |   |
| Make & Model  |  | c.c                       | 0   |
| Engine No.  | HIDDEN   | Year of Reg.              |   |
| Chassis No.   |  | Colour                    |   |
| Odometer  | -  | Steering                  |   |
| Brakes  |  | Modification              |   |
| General   |  |                           |   |
| <b>3. Conditions of Tyres</b>   |  |                           |   |
|   | Size   | Make                      | Balance   |
| R/H Front Tyre  |  |                           | mm  |
| L/H Front Tyre  |  |                           | mm  |
| R/H Rear Tyre   |  |                           | mm  |
| L/H Rear Tyre   |  |                           | mm  |
| <b>4. Description of Damages</b>  |  |                           |   |
|   |  |                           |   |
| <b>5. General Information</b>   |  |                           |   |
| Accident Date   | 28/12/2017   | Inspection Date           |   |
| Survey held at  | PROFI AUTOMOTIVE<br>BLK 10 KAKI BUKIT ROAD 2<br>#01-03 FIRST EAST CENTRE<br>SINGAPORE 417868 |                           |   |
| <b>5a. Remarks</b>  |  |                           |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                           |   |

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 2526J

## Vehicle Details

Vehicle No.: SGZ7551K  
Vehicle to be Exported: No  
Intended De-registration Date: 08 Jan 2018  
Vehicle Make: MITSUBISHI  
Vehicle Model: LANCER 1.6 A  
Primary Colour: Black  
Manufacturing Year: 2007  
Engine No.: 4G18JL6833  
Chassis No.: JMYSTCS3A8U003298  
Maximum Power Output: 79.0 kW (105 bhp)  
Open Market Value: \$11,134.00  
Original Registration Date: 16 Nov 2007  
First Registration Date: 16 Nov 2007  
Transfer Count: 2  
Actual ARF Paid: \$12,248.00

## Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date: 31 Oct 2022  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$21,282.00  
COE Rebate Amount: \$20,481.00  
**Total Rebate Amount: \$20,481.00**

## Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jan 2018

OK



A-Assurance  
Assurance in Insurance

Car Insurance Expiring?  
We get you the cheapest insurance renewal

Click to get quote



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad: Advertiser Login Ways of Selling

Volkswagen Scirocco 1.4A TSI



Sporty Red. Price Negotiable!  
Accident Free! Low Mileage  
Done, One Owner  
Direct Owner StarAd

**HIN LUNG AUTO**  
HoBee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars  
30 years of car sale

Browse by Category







Back ( 1 2 3 ) Next »

Sort by Date Posted 20 results/page

47 vehicles

Lancer

Advanced Search Submit

|  | Make       | Model                                     | Price    | Depreciation | Reg Date         | Eng Cap  | Mileage    | Veh Type | Status    |
|--|------------|---|----------|--------------|------------------|----------|------------|----------|-----------|
| <b>Search Selection</b>  | Lancer     |   | Any      | Any          | > 10 year(s) old | Any      | Any        | Any      | Available |
|   | Mitsubishi | Lancer 1.6M MR (COE till 04/2019)         | \$15,888 | \$12,160 /yr | 17-May-1999      | 1,597 cc | -          | Sedan    | Available |
| Fully Rebuilt Classic Lancer With A Beautiful Black Chrome Exterior Up For Sale. Fully Done Up By Reputable Garage From Top To Bottom. Perfect For Short Term Drive Or To Renew. Owner Letting Go Due To...              |            |   |          |              |                  |          |            |          |           |
| Posted: 28-Dec-2017 Tags: 1999 Mitsubishi Lancer, 1999 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |
|   | Mitsubishi | Lancer 1.6A GLX Sports (COE till 05/2021) | \$22,800 | \$6,760 /yr  | 24-May-2006      | 1,584 cc | -          | Sedan    | Available |
| Meticulously Well Maintained & Service Regularly In Excellent Pristine Condition With Well Kept Interior. Low Mileage Done! Guaranteed Accident Free! Various In House Or Bank Loan With Low Drive Away ...              |            |   |          |              |                  |          |            |          |           |
| Posted: 26-Dec-2017 Tags: 2006 Mitsubishi Lancer, 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |
|   | Mitsubishi | Lancer 1.6A GLX (OPC) (New 5-yr COE)      | \$35,800 | \$7,160 /yr  | 26-Nov-2007      | 1,584 cc | 120,000 km | Sedan    | Available |
| Posted: 25-Dec-2017 Tags: 2007 Mitsubishi Lancer, 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |
|   | Mitsubishi | Lancer 1.6A GLX (COE till 05/2021)        | \$24,838 | \$7,380 /yr  | 22-May-2006      | 1,584 cc | -          | Sedan    | Available |
| Beautiful Leather Seat, No Repairs Needed! We Deliver Our Promise! 6 Months Warranty Provided! High Trade In Most Welcome! Flexible Bank / In House Loan Available! 100% Loan Can Be Arranged! View To B...              |            |   |          |              |                  |          |            |          |           |
| Posted: 24-Dec-2017 Tags: 2006 Mitsubishi Lancer, 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |
| <div>Car Buying</div> <div>Car Ownership</div> <div>Car Selling</div> <div>On The Move</div> <div>Car Aftermarket</div> <div>Lifestyle</div> <div>Buy Tyres Online!</div> <div>Latest Special Offers from Tyrepac!</div> |            |   |          |              |                  |          |            |          |           |
|   | Mitsubishi | Lancer 1.6M GLX (COE till 10/2021)        | \$23,000 | \$6,150 /yr  | 06-Oct-2006      | 1,584 cc | 152,000 km | Sedan    | Available |
| Original Condition, No Modification Well Maintain.   |            |   |          |              |                  |          |            |          |           |
| Posted: 23-Dec-2017 Tags: 2006 Mitsubishi Lancer, 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |
|   | Mitsubishi | Lancer 1.6A GLX (COE till 07/2020)        | \$21,200 | \$8,330 /yr  | 26-Jul-2005      | 1,584 cc | 93,500 km  | Sedan    | Available |
| Decide To Sell Car As Low Usage:   |            |   |          |              |                  |          |            |          |           |
| Posted: 23-Dec-2017 Tags: 2005 Mitsubishi Lancer, 2005 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Lancer, Used Mitsubishi  |            |   |          |              |                  |          |            |          |           |

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                      |
|----------------------------|--------------------------------------|
| Date Of Report             | 29/12/2017 10:54                     |
| Date Of Accident           | 28/12/2017 17:00                     |
| Exact Location Of Accident | OPEN C/P OF BLK 256 BISHAN STREET 22 |
| Country/State of Loss      | SINGAPORE                            |

### DETAILS OF OWN VEHICLE

|                             |                           |
|-----------------------------|---------------------------|
| Vehicle Registration Number | SGZ7551K                  |
| <b>Insured/Policyholder</b> |                           |
| Name Of Registered Owner    | YUSMAN BIN ABD MADJID     |
| NRIC No                     | S8112526J                 |
| Email Address               | GHOST_RYDER27@HOTMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-92223297      |
| Alternative Phone No        | OTHERS-92223297           |

### Vehicle Particulars

|              |                |
|--------------|----------------|
| Manufacturer | MITSUBISHI     |
| Model        | LANCER-1.6 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | GA049596/1            |
| Cover Note Number         |                       |

### Driver

|                      |                           |
|----------------------|---------------------------|
| Name of Driver       | YUSMAN BIN ABD MADJID     |
| NRIC No              | S8112526J                 |
| Date Of Birth        | 27/04/1981                |
| Occupation           | INDOOR                    |
| Date Of Driving Pass | 11/01/2010                |
| Driving Experience   | 7 YEARS AND 11 MONTHS     |
| Gender               | MALE                      |
| Mobile Number        | (LOCAL) +65-92223297      |
| Fax Number           |                           |
| Contact Number       | OTHERS-92223297           |
| Email Address        | GHOST_RYDER27@HOTMAIL.COM |

|   |   |
|---|---|
| Address   | BLK 535 WOODLANDS DRIVE 14 #02-603<br>SINGAPORE |
| Postcode  | 730535  |
| Was driver an employee of the Insured's Company     | NO  |
| If No, Relationship of the Driver with the Insured  | OWNER   |
| Vehicle Registration Number of Driver's Own Vehicle | -   |
|   | -   |
|   | -   |
| Insurance Company of Driver's Own Vehicle           | -   |
|   | -   |
|   | -   |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |  |
|---|--|
| Was any foreign vehicle involved in this accident?  | NO   |
| Number of vehicles involved in the accident   | 2  |
| Was any body injured in the Accident?   | NO   |
| Was any injured conveyed to hospital by ambulance?  | NO   |
| Was any other material or property damaged?   | YES  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO   |
| Number of Passengers (Including Driver)   | 2  |
| Passenger 1   | NAME: : UMARSHAH BIN ROSLI<br>GENDER: : MALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                    |
|-------------------------------------|--------------------|
| Vehicle Registration Number         | YP6967R            |
| Vehicle Make/Model/Colour           |                    |
| Details Of Properties               |                    |
| Vehicle Category                    | COMMERCIAL VEHICLE |
| Name of Driver                      | MALAIRAJ SARANRAJ  |
| NRIC/Passport Number                | G6703220P          |
| Contact Number                      | 93720323           |
| Address                             |                    |
| Postcode                            |                    |
| Insurance Company Name              |                    |
| Nature Of Damage                    |                    |
| No. Of Passenger (Including Driver) |                    |

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
  - (ii) investigating the accident and/or my claim;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management of present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 29/12/17 1030am

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 29/12/17 1030am

  
Redacting Centre Personnel's Signature  
Name: permen  
NRIC/IN No:

# Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at the roadside at B/256, waiting for a car part lot when vehicle B hit my rear.

## DECLARATION

We declare the foregoing particulars to be true and correct.

*[Signature]*

Holder's Signature

Date & Time 29/12/17 1030am

*[Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time 29/12/17 1030am

*[Signature]*

Reporting Officer/Police Officer's Signature

Name

NR/Cr No:

PR121217

08 January 2018

Your Ref: Your insured YP6967R

Our Ref: PA171201-SGZ7551K

Accident Date: 28 December 2017

Vehicle No: SGZ7551K

Make/Model: Mitsubishi Lancer

Name: Yusman Bin Abd Madjid

Address: c/o 10 Kaki Bukit Road 2 #01-03 Singapore 417868

not followed  
n/w  
2/5 @ 4000h  
7.6k photo. After 4y.  
6m.  
8/1/18

| S/NO            | QTY    | NETT ITEM   | AMOUNT (S\$)          |
|-----------------|--------|---|-----------------------|
| 01              | 1 pc   | Rear Boot   | 10/cue 593.00 ✓       |
| 02              | 2 pc   | Rear Boot Hinge (84.00 x 2)                       | 1 168.00 x            |
| 03              | 1 pc   | Rear Boot Rubber                                  | 7m 160.00 ✓           |
| 04              | 1 pc   | Rear Boot Emblem M. Sub. 5k.                      | 1 38.00 ✓             |
| 05              | 1 pc   | Rear Boot Logo                                    | 1 40.00 ✓             |
| 06              | 1 pc   | Rear Fender o/s                                   | 3.0 500/que 641.00 ✓  |
| 07              | 1 pc   | Rear Fender Inner Side Garnish RH                 | 1 212.00 x            |
| 08              | 5 2 pc | Rear Fender Inner Side Garnish Clip RH (5.50 x 5) | 1 27.50 x             |
| 09              | 1 pc   | Rear Boot Lock                                    | 1 61.00 ✓             |
| 10              | 1 pc   | Rear Boot Lock Catch                              | 1 20.00 x             |
| 11              | 2 pc   | Rear Tail Lamp (404.00 x 2)                       | 0/5 cue 808.00 1 pc   |
| 12              | 4 2 pc | Rear Tail Lamp Clip (8.50 x 4)                    | 1 34.00 x             |
| 13              | 2 pc   | Rear Tail Lamp Panel (87.00 x 2)                  | 0/500/cue 174.00 1 pc |
| 14              | 1 pc   | Rear End Panel                                    | 1 414.00 x            |
| 15              | 1 pc   | Rear End Panel Top Garnish                        | 1 150.00 x            |
| 16              | 2 pc   | Rear End Panel Top Garnish Clip (5.50 x 2)        | 1 11.00 x             |
| 17              | 1 pc   | Rear Bumper Side Beam                             | 1 40.00 ✓             |
| 18              | 1 pc   | Rear Windscreen Moulding                          | 1 50.00 ✓             |
| Nett Item Total |        |   | 3641.50               |
| *Less 10%       |        |   | 364.15                |
|                 |        |   | 3277.35               |

2114  
1902.6

| S/NO                    | QTY   | SPECIAL NETT ITEM          | AMOUNT (S\$)     |
|-------------------------|-------|----------------------------|------------------|
| 01                      | 1 pc  | Rear Boot Spoiler          | 1 cue 850.00 800 |
| 02                      | 1 pc  | Rear Bumper (Carbon Fibre) | 1 1200.00 x      |
| 03                      | 1 pc  | Rear Windscreen Gum        | 1 80.00 40       |
| 04                      | 1 set | Rear Bumper Sensor         | 1 300.00 x       |
| Special Nett Item Total |       |                            | 2430.00          |
| * 05                    | 1 pc  | Rear Number Plate          | 1 50.00 x        |

| S/NO | LABOUR  | AMOUNT (S\$)     |      |
|------|---|------------------|------|
| 01   | Panel Beating                                   | 1600.00          | 900  |
| 02   | Check Wiring & Reset                            | 80.00            | 30   |
| 03   | Rust Proofing                                   | 100.00           | 80   |
| 04   | Remove & Replace Rear Bumper Sensor             | 100.00           | 50   |
| 05   | Remove & Refit Rear windscreen                  | 200.00           | 120  |
| 06   | Remove & Refit Rear Seats, Roofing & Upholstery | 300.00           | 80   |
| 07   | Spray Painting                                  | 1200.00          | 1000 |
| 08   | Towing  | 50.00            | X    |
|      | <b>Labour Total</b>                             | <b>3630.00</b>   |      |
|      | <b>Grand Total</b>                              | <b>9337.35</b>   | 5000 |
|      |   | <b>9337 + 35</b> |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                             |            |   |
|--|--|-----------------------------|------------|---|
| SOMPO INSURANCE SINGAPORE PL   |  | Ref : CS/SMO18000298/Utd3n2 |            |   |
| 50 RAFFLES PLACE<br>#05-01/06<br>SINGAPORE LAND TOWERSINGAPORE 048623  |  | Date : 17-01-2018           |            |  |
|  |  | Code : SMO                  |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                             |            |   |
| Insured Veh.   | YP 6967R   | Veh. Inspected              | SGZ 7551K  |   |
| Policy No.   |  | Coverage (\$)               | 0.00       |   |
| Claim No.  | CMTD1800014/THE  | Excess (\$)                 | 0.00       |   |
| Assign From  | GRACE TEO  | Assign Date                 | 05/01/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                             |            |   |
| Make & Model   | MITSUBISHI LANCER (A)  | c.c                         | 1584       |   |
| Engine No.   | HIDDEN   | Year of Reg.                | 2007       |   |
| Chassis No.  | JMYSTCS3A8U003298  | Colour                      | WHITE      |   |
| Odometer   | 168095   | Steering                    | IN ORDER   |   |
| Brakes   | IN ORDER   | Modification                | SPORTS RIM |   |
| General  | GOOD   |                             |            |   |
| <b>3. Conditions of Tyres</b>  |  |                             |            |   |
|  | Size   | Make                        | Balance    |   |
| R/H Front Tyre   | 205/50 R16   | FALKEN                      | 6 mm       |   |
| L/H Front Tyre   | 205/50 R16   | FALKEN                      | 6 mm       |   |
| R/H Rear Tyre  | 205/50 R16   | FALKEN                      | 6 mm       |   |
| L/H Rear Tyre  | 205/50 R16   | FALKEN                      | 6 mm       |   |
| <b>4. Description of Damages</b>   |  |                             |            |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                             |            |   |
| <b>5. General Information</b>  |  |                             |            |   |
| Accident Date  | 28/12/2017   | Inspection Date             | 08/01/2018 |   |
| Survey held at   | PROFI AUTOMOTIVE<br>BLK 10 KAKI BUKIT ROAD 2<br>#01-03 FIRST EAST CENTRE<br>SINGAPORE 417868 |                             |            |   |
| <b>5a. Remarks</b>   |  |                             |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                             |            |   |
| <b>5b. Estimate Days of Repair</b>   |  |                             |            |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 6 Working Days              |            |   |





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 7551K

| Qty                                | Description of Parts                               | Condition              | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|------------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |                        |                           |                   |
| 1                                  | REAR BOOT (N)                                      | DENTED / CRACKED       | 593.00                    | 593.00            |
| 2                                  | REAR BOOT HINGE @\$84.00 (N)                       | TO REPAIR SEE LABOUR   | 168.00                    | -                 |
| 1                                  | REAR BOOT RUBBER (N)                               | TWISTED                | 160.00                    | 160.00            |
| 1                                  | REAR BOOT EMBLEM "MITSUBISHI" (N)                  | NECESSARY              | 38.00                     | 38.00             |
| 1                                  | REAR BOOT LOGO (N)                                 | NECESSARY              | 40.00                     | 40.00             |
| 1                                  | REAR FENDER O/S (N)                                | BADLY DENTED / BUCKLED | 641.00                    | 641.00            |
| 1                                  | REAR FENDER INNER SIDE GARNISH RH (N)              | NOT NECESSARY          | 212.00                    | -                 |
| 5                                  | REAR FENDER INNER SIDE GARNISH CLIP RH @\$5.50 (N) | NOT NECESSARY          | 27.50                     | -                 |
| 1                                  | REAR BOOT LOCK (N)                                 | TWISTED                | 61.00                     | 61.00             |
| 1                                  | REAR BOOT LOCK CATCH (N)                           | NOT NECESSARY          | 20.00                     | -                 |
| 2                                  | REAR TAIL LAMP @\$404.00 (N)                       | O/S CRACKED            | 808.00                    | 404.00            |
| 4                                  | REAR TAIL LAMP CLIP @\$8.50 (N)                    | NOT NECESSARY          | 34.00                     | -                 |
| 2                                  | REAR TAIL LAMP PANEL @\$87.00 (N)                  | O/S DENTED / CRACKED   | 174.00                    | 87.00             |
| 1                                  | REAR END PANEL (N)                                 | TO REPAIR SEE LABOUR   | 414.00                    | -                 |
| 1                                  | REAR END PANEL TOP GARNISH (N)                     | NOT NECESSARY          | 150.00                    | -                 |
| 2                                  | REAR END PANEL TOP GARNISH CLIP @\$5.50 (N)        | NOT NECESSARY          | 11.00                     | -                 |
| 1                                  | REAR BUMPER SIDE BEAM (N)                          | BENT                   | 40.00                     | 40.00             |
| 1                                  | REAR WINDSCREEN MOULDING (N)                       | CUT                    | 50.00                     | 50.00             |
|                                    | LESS 10% DISCOUNT                                  |                        | -364.15                   | -211.40           |
|                                    |  |                        | 3,277.35                  | 1,902.60          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |                        |                           |                   |
| 1                                  | REAR BOOT SPOILER (SN)                             | CRACKED                | 850.00                    | 800.00            |
| 1                                  | REAR BUMPER (CARBON FIBRE)(SN)                     | TO REPAIR SEE LABOUR   | 1,200.00                  | -                 |
| 1                                  | REAR WINDSCREEN GUM (SN)                           | NECESSARY              | 80.00                     | 40.00             |
| 1                                  | SET REAR BUMPER SENSOR (SN)                        | NOT NECESSARY          | 300.00                    | -                 |
| 1                                  | REAR NUMBER PLATE (SN)                             | NOT NECESSARY          | 50.00                     | -                 |
|                                    |  |                        | 2,480.00                  | 840.00            |

Report Ref No. CS/SMO18000298/Utd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
|   | <b>LABOUR</b>  |               |                           |                   |
|   | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE ,REAR END PANEL AND REAR BUMPER (CARBON FIBRE). |               | 1,600.00                  | 900.00            |
|   | CHECK WIRING & RESET.  |               | 80.00                     | 30.00             |
|   | RUST PROOFING.   |               | 100.00                    | 80.00             |
|   | REMOVE & REPLACE REAR BUMPER SENSOR.   |               | 100.00                    | 50.00             |
|   | REMOVE & REFIT REAR WINDSCREEN.  |               | 200.00                    | 120.00            |
|   | REMOVE & REFIT REAR SEATS,ROOFING & UPHOLSTERY.  |               | 300.00                    | 80.00             |
|   | SPRAY PAINTING.  |               | 1,200.00                  | 1,000.00          |
|   | TOWING.  | NOT NECESSARY | 50.00                     | -                 |
|   |  |               | 3,630.00                  | 2,260.00          |
|   | <b>GRAND TOTAL</b>   |               | <b>9,387.35</b>           | <b>5,002.60</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |               |                           | <b>4,000.00</b>   |

Report Ref No. CS/SMO18000298/Utd3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.