

Vehicle no. : SLJ7878T
Model : Toyota Altis

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
		B/F	\$ -
		LABOUR & OTHER CHARGES:-	
1		To panel beat and renewal of all necessary damaged body parts	\$ 1,000.00
2		To remove and reinstall front door components	\$ 80.00
3		To remove and reinstall front/rear undercarriage items	\$ 350.00
4		To perform 4 wheel alignment	\$ 120.00
5		To perform wheel balancing	\$ 80.00
6		To anti-rust	\$ 140.00
7		To putty and spray-paint of affected areas	\$ 1,200.00
			\$ 2,970.00

Grand - Total \$ -